

# OFFICE OF THE DIRECTOR Office of Research & Environmental Protection Plans Review & Inspections

410-396-0732 DPW.ESCinspections@baltimorecity.gov

### **EROSION AND SEDIMENT CONTROL INSPECTIONS**

The purpose of this form is to document erosion and sediment control (ESC) inspections as it relates to approved ESC plans approved by DPW- Plans Review and Inspections (DPW-PRI) Section.

A. <u>General P</u>	roject Information f	or ESC Plans	□ Data change	e since last ins	pection.
Project name:	Insulator Drive				
Project locatio	n: 2525 Insulator Dri	ive		Watershe	ed: Gwynns Falls
DPW plan ID:	<b>BCNR 10258</b>	Plan approval dat	e: 12-29-2022	Expiration	n date: 12-29-2024
Construction s	chedule, start date:	Active	E	End date: 2	2026
Project type:	Mass grading	On-site BMP status	s/ type: Pendin	ng, not started	Other
DHCD permit:		ROW permit/ D/	<b>\</b> :		☑ NPDES 20-CP
LOD area (ac):	25.79 AC	LOD volume (cy):			nin Critical Area
□ LOD within	sensitive areas:		□ Non-	tidal stream	□ Stream buffer
			olain 🗆 Wetl	and	☐ Forest buffer
		□ Steep slopes	□ Othe	r:	
Source of borre	ow material:		Disposal	area:	
B. Construct	ion Contact Informa	ation .	☐ Data change	e since last ins <sub>i</sub>	pection.
Owner / develo	per company:	nsulator Drive LLC c	o 28 Walker		
Address: 28	8 Walker Ave, Pikesvill	e, MD 21208	Ph	none: 410-32	0-6007
Contact name:	Bruce Shields		Email: Bruce(	@28walker.co	m
Contractor con	npany/ type: SEH	Excavation			Grading (sub)
Address: 29	940 Dede Rd, Finksbur	rg, MD 21048			
Contact name:	Jason Neuhause	r			
Contact phone	: 410-984-2960		Email: Jneuha	auser@sehexc.	.com
Responsible pe	ersonnel:		ID:		
C. <u>Inspection</u>	Information				
Inspection date	9-12-2024	Time: 10:00 AM	Current we	ather: Clea	ır
DPW Inspector	: Brian Hartman		Site status:	: Activ	/e
Inspection type	Routine: bi-weel	kly	Inspection	ref. for follow-	-up:
nspection resu	In Violation (See	Part D)	Nu	ımber of Viola	tions:
Penalty:	☐ None. ☐ Fines ma	ay be issued. 🛛 🖂 🗐	nes have been issu	ued in the amou	unt of
Total Fines: 6 \$ 500.00	Stop Work Order has construction activities may only result of the sufficiently performed to	nust stop, except thos me once the DPW In	e necessary to co spector has confire	rrect the violation	ons. Normal construction ctive actions were

## D. <u>Summary Table of ESC Requirements and Inspection Results:</u>

Requirement	Status	Comments
DPW-PRI must receive written notification prior to start of construction.	Compliant	
Responsible person (MDE ESC training / certification) must be on-site during earth disturbance activities.	Compliant	
Approved ESC plans ("Plans") must be maintained on-site and available to DPW Inspector.	Compliant	
ESC measures must be installed prior to any earth disturbance activities except as necessary for installation of controls.	Compliant	
Earth disturbance activities, including staging areas and access paths, must be located ONLY within the limit of disturbance (LOD) shown on plans.	Compliant	
Clearing and grading activities must follow sequence of construction as shown on plans.	Compliant	
Any pumping of water must be filtered and discharged as shown on plans.	Compliant	
All points of access to the LOD must be protected to minimize tracking of soil on the public rights-of-way. Any material tracked, spilled or washed on to adjacent roads must be immediately removed by shoveling or sweeping. No flushing will be permitted.	Violation - Deficient	SEE BELOW
Buried utility construction should be limited to only that section of trench that can be backfilled and stabilized within the workday (i.e. same day stabilization)	Compliant	
BMPs with an infiltration/recharge component must be protected from sediment-laden runoff and construction traffic prior to, during, and after excavation of the BMP.	Not part of inspection.	
Filtering controls that do not have an infiltration/recharge component as part of the design must be protected from sediment-laden runoff or construction traffic after the filtering media is installed.	Not part of inspection.	
All ESC measures must be installed and maintained per the Plans and the 2011 Maryland Standards and Specifications for Soil Erosion and Sediment Control until DPW has provided written notice to remove the measures.	Compliant	
Stabilized Construction Entrance (B-1)	Compliant	
Land grading (B-3): benching, serrated slope	Compliant	9-10-1 E-10-1
Vegetative stabilization (B-4)	Compliant	
Water Conveyance (Section C): dikes, swales, diversions, and berms	Compliant	
Silt Fence (E-1), super silt fence (E-2), and silt fence on pavement (E-3), with clear water pipe (E-4)	Violation - Deficient	SEE BELOW
Filter berm (E-5), filter log (E-6)	Not applicable to project.	
Storm drain inlet protection (E-9)	Compliant	
Portable sediment tank (F-3)	Not applicable to project.	
Filter bag (F-4)	Compliant	
Other ESC measure	Not part of inspection.	


#### E. Inspection Findings


- 1. DPW Inspector met with Jason w/ SEH.
- 2. FINE ISSUED \$200.00
  - a. WILLFUL DESTRUCTION OF AN SEDIMENT CONTROL DEVICE \$100.00
  - b. FAILURE TO MAINTAIN PERIMTER SEDIMENT CONTROL DEVICE \$100.00



3. Excessive sediment on Insulator Drive. Sweep immediately. Continued instances of this will result in additional fines. (Final Warning)








4. Please start sweeping the interior roadway at these locations. Sediment build-up is increasing, and these points of egress have no E&S controls.





Continue sweeping Insulator Drive. Tracking is occurring in Nicks parking lot as well at the section of Insulator Drive by the Marina.

#### F. Corrective Actions

Department by a

All items shall be fixed immediately. Due to the nature of Item 2 in section E, penalty fines have been issued in the amount of \$200.00.

#### G. Acknowledgement of Receipt

Please acknowledge the receipt of this notice and your agreement to perform the work by the signing and returning this document immediately to DPW-OREP-Plans Review and Inspections Attn: ESC Inspection Report: 3001 Druid Park Drive, Room 228 Baltimore, MD 21215 or emailing <a href="mailto:brian.hartman@baltimorecity.gov">brian.hartman@baltimorecity.gov</a>.

DPW is required to post all ESC violation notices on its website. Any questions about this inspection report should be directed to **Brian Hartman** at 410-396-0732 or **brian.hartman@baltimorecity.gov.** 

Per Article 7, Division III, Subtitle 35 of the City Code, any ESC violation notice may be appealed and eligible for administrative review. Any appeal must be submitted in writing within 10 days of the inspection report. The appeal may be submitted to the Director of Public Works via email <a href="mailto:DPWDirector@baltimorecity.gov">DPWDirector@baltimorecity.gov</a> (preferred) or Baltimore City DPW, Abel Wolman Building, 6th Floor, Attn: ESC Appeals, 200 N. Holliday Street, Baltimore, 21202. The written appeal must include:

- Project Name, DPW ID, and inspection date as listed on page 1 of this inspection report.
- A statement of the legal ground on which the appeal is based; and
- An express statement of any desire for an administrative hearing.

Printed Name/ Company	
Signature	Date