SSO Notification List

January 2014

	Date of				Dry or Wet West-				Description of	Est. Quantity of	Measures taken to Minimize	Preventive Action to Ctar	
Serial No.	Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Time	Discharge	Discharge (gallons)	Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2014	2400 Cross Country Blvd	21209	Roots, Vandalism	DWO	Patapsco	11:06	01/01/2014 1:21PM - 01/02/2014 12:27PM	Heavy Gray Water	3330	Relieved M/L choke with pressure truck 10ft. of 10in. T/O for CCTV water running from ground	N/A	174869
2	1/1/2014	2600 Huron St	21230	Rags, Grease	DWO	N/A	Not Witnessed	Overflow not Witnessed	Gray colored water, wet paper	Evidence of Overflow	Used sewer jet	UAMD	174845
3	1/1/2014	4333 Eldone Rd	21229	Rags, Roots	DWO	Patapsco	1:38	1:48PM - 3:26PM	Heavy Gray Water	490	Relieved M/L choke with pressure truck 175ft. of 8in T/O for CCTV & Sewer	N/A	174826
4	1/6/2014	Greenspring Ave & W Coldspring Ln	21209	Rags, Grease, Debris	wwo	Patapsco	0:39	11:20AM - 11:59AM	Gray Water	195	Relieved M/L choke, 200ft. Pressure machine hose	UAMD CCTV Mainline	177018
5	1/2/2014	126 N Clinton St	21224	Rags, Grease	wwo	N/A	Not Witnessed	Overflow not Witnessed	Paper debris, grease	Evidence of Overflow	Drain cleaning machine relieved h/c choke	UAMD	174889
6	1/6/2014	428 E Preston St	21202	Rags, Grease	wwo	Jones Falls	1:30	7:00PM - 8:30PM	Wet Paper	45	Used Elec. Mach.	UAMD	177063
7	1/6/2014	500 University Pkwy	21210	Rags, Roots, Debris	wwo	Jones Falls	23:05	01/06/2014 4:00PM - 01/07/2014 2:39PM	Gray Water Paper	6795	Pressure truck relieve Mainline choke, 300ft.	UAMD CCTV Mainline	177058
8	1/6/2014	2815 Maudlin Ave	21230	Rags, Roots, Grease, Infiltration	wwo	Patapsco	23:04	01/06/2014 7:06AM - 01/07/2014 6:30PM	Paper debris	7020	Bypass pumping stop overflow	UAMD	177034
9	1/8/2014	914 N Monroe St	21217	Rags	DWO	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Relieved choke, 60ft. Elec. Machine	UAMD	117987
10	1/8/2014	107 N Rock Glen Rd	21229	Rags, Grease	DWO	Patapsco	1:30	6:00PM - 7:30PM	Gray colored water	90	Used sewer jet	UAMD	177160
11	1/9/2014	1806 N Longwood St	21216	Rags	DWO	Patapsco	Not Witnessed	Overflow not Witnessed	N/A	Evidence of Overflow	Relieved house connection choke with pressure truck, 150ft. of 6in. also flush M/L. T/O for CCTV houce connection	N/A	177197
12	1/9/2014	3643 Woodland Ave	21215	Rags	DWO	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Used Elec. Mach.	UAMD	177216
13	1/9/2014	1622 McCulloh St	21217	Rags	DWO	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Ran elec. machine, relieved 30ft. elec. machine cables	UAMD	177186
14	1/10/2014	721 Eastern Ave	21202	Roots	wwo	N/A	0:60	11:20AM - 12:20PM	Heavy Gray Water	300	Relieve with jet, T/O CCTV	UAMD Investigate	177229
15	1/6/2014	4209 Willshire Ave	21206	Rags	wwo	N/A	Not Witnessed	Overflow not Witnessed	N/A	Evidence of Overflow	Relieved house connection choke, 45ft of 6in T/O for CCTV	N/A	177048
16	1/9/2014	2309 Allendale Rd	21216	Pipe Break	DWO	Gwynns Falls	8:20	8:48AM - 5:00PM	Gray Water, Debris	984	Bypass pumping, turn over for repairs	UAMD	177187
17	1/11/2014	2317 Tucker Ln	21207	Rags	wwo	Patapsco	7:18	8:42AM - 4:00PM	Heavy Gray Water	2100	Relieved M/L choke with pressure truck, 175ft. of 8in san M/L T/O for CCTV	N/A	177268
18	1/11/2014	3304 Ellerslie Ave	21218	Roots	wwo	Patapsco	1:30	5:30PM - 7:00PM	Heavy Gray Water	270	Relieved with pressure truck	UAMD - CCTV	177290
19	1/12/2014	1400 Aisquith St	21202	Rags, Grease, Debris	DWO	Patapsco	4:21	8:00AM - 12:21PM	Paper, Gray Water	1305	Pressure truck relieved 200ft. pressure hose. CCTV M/L	N/A	177318
20	1/14/2014	2300 Lipps Ln	21223	Rags	wwo	Patapsco	3:27	9:58AM - 1:00PM	Heavy Gray Water	207	Relieved house connection choke with elec. mach. 60ft. of 6in.	N/A	177369
21	1/13/2014	517 N Carrollton Ave	21223	Rags	DWO	Patapsco	3:06	10:54AM - 2:00PM	Heavy Gray Water	186	Not relieved, ran 120ft. of elec. mach. back mud, T/O for bypass pumping construction	N/A	177372
22	1/13/2014	5803 Stuart Ave	21215	Roots	DWO	Patapsco	Not Witnessed	Overflow not Witnessed	N/A	Evidence of Overflow	Relieved house conn choke with elec. mach. 75ft. of 6in. CCTV bottom 6.1 M/L 66.1	N/A	177409
23	1/14/2014	911 Desoto Rd	21229	Rags, Roots, Grease	wwo	Patapsco	6:03	8:27AM - 2:30PM	Heavy Gray Water	9075	Relieved M/L choke with pressure truck, 50ft of san M/L T/O for CCTV	N/A	177421
24	1/14/2014	536 E 26th St	21218	Rags, Grease, Debris	wwo	Back River	2:03	11:03AM - 1:00PM	Paper, Grease	246	Pressure truck, rec choke 250ft. pressure hose	UAMD - CCTV Mainline	177424
25	1/14/2014	5267 Cordelia Ave	21215	Grease, Sand, Gravel, Rocks, Debris	wwo	Patapsco	18:06	01/14/2014 5:54PM - 01/15/2014 12:00PM	Heavy Gray Water	2172	Relieved M/L choke with pressure truck, 200ft. of 8in. san M/L T/O for CCTV	N/A	177455
26	1/15/2014	2401 Cross Country Blvd	21209	Roots, Sand Gravel, Rocks	DWO	Patapsco	3:18	11:42AM - 3:00PM	Heavy Gray Water	990	Relieved M/L choke with pressure truck 10ft of 10in. sewer water running from ground/CCTV	N/A	177489
27	1/16/2014	2435 Washington Blvd	21230	Rags, Grease	wwo	Patapsco	1:06	2:54PM - 3:30PM	Heavy Gray Water	36	Relieved M/L choke with pressure truck, 300ft. of 8in T/O for CCTV	N/A	177537

SSO Notification List

January 2014

		1											
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Time	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
28	1/16/2014	Joplin St & O'Donnell St	21224	Roots	wwo	Dundalk	1:40	2:00PM - 3:40PM	Heavy Gray Water	500	Relieved with pressure	UAMD Invest/CCTV	177544
29	1/16/2014	Brehms Ln & Kenyon Ave	21213	Pipe break	wwo	Herring Run	12:30	01/16/2014 12:00PM- 01/17/2014 12:30PM	Sewer liquid/ TP	15000	Installed pump around the break from the upstream san MH to the downstream san MH	N/A	
30	1/17/2014	3000 Normount Ave	21216	Rags, Grease	DWO	N/A	Not Witnessed	Overflow not Witnessed	Evidence	Evidence of Overflow	Used sewer jet	UAMD	177606
31	1/18/2014	6500 O'Donnell St	21224	Rags, Grease	wwo	Patapsco	5:24	3:53PM - 9:17PM	Gray water, debris	1620	Pressure truck relieved 75ft of pressure	Hose, CCTV Mainline	177624
32	1/18/2014	3626 Greenmount Ave	21218	N/A	wwo	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Pressure truck, flush mainline	UAMD	177629
33	1/20/2014	Greenspring Ave & Dupont Ave	21209	Rags, Grease	DWO	Jones Falls	2:14	2:46PM - 5:00PM	Paper & Debris	134	Rec 45ft Elec-machine	CCTV Mainline	177692
34	1/20/2014	400 Heaver St	21218	Rags, Debris	DWO	Jones Falls	2:08	12:00PM - 2:08PM	Gray Water	128	Pressure truck Rel. 185ft	CCTV Mainline	177685
35	1/20/2014	141 N Highland Ave	21224	Debris	DWO	Low Level	1:30	4:00PM - 5:30PM	Gray colored water	45	Used sewer jet	N/A	177690
36	1/16/2014	841 E Fort Ave	21230	Roots	wwo	Low Level	5:00	2:25PM - 7:25PM	Heavy Gray Water	1500	Relieved with pressure truck	UAMD Inv. and CCTV	177554
37	1/23/2014	3626 Greenmount Ave	21218	Rags	wwo	N/A	Not Witnessed	Overflow not Witnessed	Sewer water, paper debris, feces	Evidence of Overflow	Drain cleaning machine relieved H/C choke	UAMD	180362
38	1/25/2014	701 E 33rd St	21218	Rags, Roots	wwo	Jones Falls	0:60	5:00PM - 6:00PM	Gray colored water	30	Used elec. machine	UAMD-CCTV	181181
39	1/27/2014	600 Markham Rd	21229	N/A	DWO	N/A	Not Witnessed	Overflow not Witnessed	Paper, Gray Water	Evidence of Overflow	Ran 75ft elec. machine cable	UAMD	181221
40	1/2/2014	410 Hollen Rd	21212	N/A	wwo	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Relieved with electric mach.	UAMD-CCTV	174894
41	1/28/2014	6541 Eastern Ave	21224	Rags, Grease	wwo	Back River	1:30	9:00PM - 10:30PM	Gray colored water	270	Used sewer jet	UAMD-CCTV	181308
42	1/29/2014	3100 Sun St	21226	Grease	wwo	Patapsco	3:00	5:00PM - 8:00PM	Brown Ice	90	Used sewer jet	UAMD	181349
43	1/29/2014	6105 Maywood Ave	21209	Rags, Roots	wwo	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Ran 45ft Elec-machine	UAMD	181325
44	1/31/2014	1707 Ashburton St	21216	Debris	DWO	N/A	Not Witnessed	Overflow not Witnessed	Paper	Evidence of Overflow	Ran 2ft Elec machine, not relieved	UAMD, plumber needed to replace	118998
45	1/3/2014	4419 Mannasota Ave	21206	Grease	wwo	Herring Run	3:14	10:01AM - 1:13PM	Gray Water	388	Pressure truck rel. M/L choke 60ft. pressure hose	CCTV Mainline	175788
				# WWO	26				TOTAL	55541	EVIDENCE ONLY	15	