

SSO Notification List

February 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/1/2017	3318 Burleigh Ave	21215	Rags, Roots	WWO		0	Heavy gray water around clean out.	8	Relieved 6" house connection choke with 30 ft of electric machine.	Performed CCTV inspection. 5 ft to the bottom of the clean out, 21 ft to the main.	383544
2	2/1/2017	200 East St. (Private)	21202	Rags, Grease, Trash	WWO	Harbor	94	Murky colored water overflowing from manhole	470	Flushed and cleaned 8" sewer main using 200 ft of pressure hose.	Performed CCTV inspection.	383636
3	2/2/2017	400 W 26th St	21211	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO		176	Heavy gray water overflowing from manhole.	880	Relieved mainline choke with 25 ft of press truck.	Cleaned mainline and submitted manhole for repair	384020
4	2/2/2017	6312 Elinore Ave	21206	Rags, Roots, Trash	DWO		0	Gray water	15	Used 45 ft of electric cable to try and relieve house connection choke.	Bypass pumping has been initiated at this location.	384095
5	2/3/2017	29 Merrymount Rd	21210	Rags, Roots	DWO		0	Gray water and sewage around house connection.	8	Relieved house connection choke with 60 ft of electric machine on 6 in line.	Mainline cleaning and CCTV inspection at this location.	384230
6	2/3/2017	1813 W Lafayette Ave	21217	Rags, Trash	DWO		0	Gray water and debris.	10	Relieved house connection choke with 30 ft of electric machine.	Cleaned the mainline to help prevent future overflows at this location.	384203
7	2/4/2017	Curtis Ave and Cherry St	21226	Structural	DWO		305	Murky colored water overflowing.	3,050	Initiated bypass pumping at this location to abate overflow.	Pipe will need to be repaired to prevent future overflows.	384433
8	2/5/2017	821 McKean Ave	21217	Rags, Grease, Trash	DWO	Gwynns Falls	0	Murky colored water near house connection at the rear of the property.	12	Relieved house connection choke using 35 ft of electric H cutter.	Performed CCTV inspection.	384475
9	2/5/2017	2013 E 32nd St	21218	Rags, Structural	DWO		0	Sewage discharging from consumers' yards on the 2000 block of East 31st St.	15	Relieved 8" main line choke with 300 ft of pressure hose.	Cleaned main line in preparation for CCTV inspection.	384508
10	2/6/2017	E 32nd St and Jenifer Ave	21218	Rags, Grease, Trash	DWO		144	Murky colored water overflowing from manhole.	1,440	Relieved 8" main line choke with 385 ft of pressure hose. Removed rags, paper, and debris.	Performed mainline CCTV inspection at this location.	384541
11	2/6/2017	6656 Belair Rd	21206	Rags, Grease, Trash	DWO		0	Signs of an overflow including dirty colored water	15	Cleaned line with 45 feet of electric cable and H-cutter. Removed debris and rags.	Performed CCTV inspection.	384583
12	2/7/2017	1708 N Dukeland St	21216	Rags	DWO		0	Heavy gray water near house connection.	10	Relieved house connection choke with 30 ft of electric cables.	Checked main line and house connection; both clear.	386703
13	2/7/2017	2415 E Northern Pkwy	21214	Rags, Trash	DWO		43	Sewage overflowing from manhole.	215	Relieved 8" main line choke with 275 ft of pressure hose.	Performed CCTV inspection.	386769
14	2/7/2017	6320 Wirt Ave	21215	Rags, Roots, Grease, Trash	DWO		220	Gray water observed overflowing in rear yard.	1,100	Flushed and removed choke on 10" main line using 400 ft of pressure hose. Heavy roots, grease, and debris removed.	Performed CCTV inspection.	386860
15	2/8/2017	5135 Frederick Ave	212229	Rags, Grease, Trash	DWO		152	Sewage discharging from sanitary manhole.	1,520	Relieved mainline choke with 50 ft of pressure truck on 8 in line.	Performed mainline CCTV inspection at this location.	386918
16	2/8/2017	250 S Clinton St	21224	Roots	DWO		0	Gray water and debris	8	Used 10 ft of electric machine to try and relieve house connection choke, water still holding.	Pumped house connection down for further investigation.	386923
17	2/9/2017	3406 Wabash Ave	21215	Rags, Roots, Grease	DWO	Gwynns Falls	97	Subsurface overflow observed and confirmed with dye test on the line segment. Found during routine ammonia screening by OCAI. Please contact Mike if	970	Relieved mainline choke with 400 ft of pressure truck on 8 in line.	Mainline CCTV inspection.	387246
18	2/9/2017	4210 Parkwood Ave	21206	Roots, Trash, Structural	DWO		0	Toilet paper and sewage visible.	10	Ran 60 ft of electric machine to try and relieve house connection choke	Unable to relieve choke at this location, bypass pumping has been initiated. Will perform a house lateral CCTV inspection.	387313
19	2/9/2017	Weldon Ave and Falls Rd	21211	Roots, Grease, Trash	DWO		163	Sewage and debris overflowing.	326	Relieved mainline choke with 100 ft of pressure machine hose.	Performed a mainline CCTV inspection at this location.	387310

SSO Notification List

February 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	2/9/2017	6317 Park Heights Ave	21215	Rags, Roots, Grease	DWO		0	Large amount of sewage in field behind apartment building and houses.	10,001	Relieved the mainline choke at this location with pressure hose, cleaned affected area.	Mainline was flushed and cleaned, performed mainline CCTV inspection.	384572
21	2/10/2017	2610 Oswego Ave	21215	Rags, Roots, Grease	WVO		0	Heavy gray water appears to have come out of the clean-out in the rear of the house.	11	Relieved 6" house connection choke using 30 ft of electric cable.	Performed CCTV inspection.	387367
22	2/11/2017	1030 Parksley Ave	21223	Roots, Trash	WVO		0	Heavy gray water around the clean-out at the front of the house.	8	Relieved 6" house connection choke with 60 ft of electric cable and H-cutter.	Performed CCTV inspection.	387673
23	2/11/2017	1209 N Woodyear St	21217	Roots, Trash	WVO		0	Heavy gray water around the clean-out in front of house.	6	Relieved 6" house connection choke with 45 ft of electric cable and H-cutter.	Performed CCTV inspection.	387667
24	2/13/2017	250 S Loudon Ave	21229	Rags, Trash	DWO		0	Paper and debris around house connection.	15	Relieved house connection choke with electric machine.	Spoke to resident about raising external clean out up to grade to prevent future overflows.	387846
25	2/14/2017	2116 N Wolfe St	21213	Rags, Grease	DWO	Harbor	0	Small amount of toilet paper and evidence.	50	Relieved mainline choke with 170 ft of pressure hose, brought back heavy grease.	Mainline CCTV inspection performed at this location.	388073
26	2/16/2017	4716 Parkside Dr	21206	Rain, Unknown	DWO		0	Evidence of prior SSO in field across from 4716 Parkside Dr. Evidence consisted of dried sewage on surrounding ground.	30	Sewage line is flowing freely, manhole no longer overflowing.	Affected area was documented and cleaned.	
27	2/16/2017	4904 Westhills Rd	21229	Rags, Roots	DWO		0	Heavy gray water around the clean-out at the front of the house.	5	Relieved house connection choke with 30 ft of electric machine cable. Used H-cutter to remove roots and debris.	Performed CCTV inspection.	388507
28	2/16/2017	2006 E 30th St	21218	Sand, Gravel, Rocks, Structural	DWO		0	Gray water observed around clean-out at the rear of the house.	6	Ran 60 ft of electric cable and H-cutter.	Performed CCTV inspection and referred this location for bypass pumping.	388707
29	2/18/2017	1204 Cochran Ave	21239	Roots, Grease, Trash	DWO		0	Sewage observed near clean-out at the front of the house.	10	Relieved house connection choke with 30 ft of electric cable with expander cutters.	Performed CCTV inspection.	389147
30	2/18/2017	949 Montpelier St	21218	Roots	DWO		0	Toilet paper and evidence around the clean out.	0	Relieved house connection choke with 30 ft of electric cable.	Performed mainline cleaning at this location.	389152
31	2/19/2017	3505 Lyndale Ave	21213	Roots, Grease, Trash	DWO		0	Gray water around the clean-out at the front of the house.	6	Relieved house connection choke with 45 ft of electric cable and expander.	Performed CCTV inspection.	389368
32	2/20/2017	5200 Beaufort Ave	21215	Rags, Grease, Trash	DWO	Jones Falls	98	Clean-out overflowing at the rear of the house and running into the storm drain.	196	Relieved house connection choke with 30 ft of electric machine.	Cleaned the mainline at this location.	389431
33	2/20/2017	4121 Falls Rd	21211	Rags, Grease	DWO	Jones Falls	108	Manhole overflowing into the street.	540	Relieved 8 inch mainline choke with 220 ft of pressure hose.	Performed CCTV inspection.	389404
34	2/21/2017	4258 Woodridge Rd	21229	Rags, Grease, Trash, Structural	DWO		152	A slow flow of sewage possibly coming from a lateral of an abandoned home.	456	Relieved mainline choke and house connection choke with 600 ft of pressure machine hose.	Performed mainline CCTV inspection at this location.	389631
35	2/21/2017	421 E Lafayette Ave	21202	Structural	DWO		0	Evidence of overflow around broken house connection.	5	Delegated to construction to repair sanitary connection.	Performed CCTV inspection.	388400
36	2/22/2017	340 S Augusta Ave	21229	Rags, Roots, Trash	DWO		0	Signs of heavy sewage debris around clean out and alley.	8	Relieved 6" house connection choke with 30 ft of electric cables and H-cutter.	Performed CCTV inspection.	389929
37	2/23/2017	4002 Kathland Ave	21207	Rags, Roots, Trash	DWO		0	Gray water and debris around the clean-out at the rear of the home.	9	Relieved 6" house connection choke with 90 ft of electric machine.	Performed house lateral CCTV inspection.	390195
38	2/24/2017	2211 Roslyn Ave	21216	Rags, Roots, Grease, Trash	DWO		190	Heavy gray water coming out of the clean-out at the rear of the property.	570	Relieved 6" house connection choke with 75 ft electric cable.	Performed CCTV inspection and cleaned the mainline.	390439
39	2/27/2017	2600 Frederick Ave	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	Gwynns Falls	1355	Heavy sewage coming from manhole.	13,550	Relieved 10" mainline choke with 10 ft of pressure hose.	Performed CCTV inspection and cleaned the manhole of heavy rocks.	391214

SSO Notification List

February 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
40	2/27/2017	925 Montpelier St	21218	Rags, Roots, Trash	DWO		0	Sewage visible around the clean-out at the rear of the house.	5	Relieved house connection choke with 35 ft of electric machine cable.	Performed CCTV inspection.	391136
41	2/27/2017	2607 Goodwood Rd	21214	Rags, Roots, Grease, Trash	DWO		0	Gray water around the clean-out at the front of the property.	4	Relieved house connection choke with 35 ft of electric machine cable and used expander cutter to remove rags.	Performed CCTV inspection.	391168
42	2/28/2017	1105 Argonne Dr	21218	Rags, Roots, Grease, Trash	WWO		141	Water coming out of the clean-out at the rear of the house.	423	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and cleaned the mainline.	391225
43	2/28/2017	1812 Druid Hill Ave	21217	Rags, Roots, Trash	WWO		108	Heavy gray water coming out of the clean-out at the front of the house.	108	Relieved house connection choke with 45 ft of electric cables.	Performed CCTV inspection.	391451
				# WWO	4			TOTAL	35.634	UNDER 100 GALLONS	26	