

SSO Notification List

July 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2016	1639 Northwick Rd	21218	Rags, Roots, Other	DWO	N/A	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with electric machine	Removed paper, debris and roots to prevent future overflows	315817
2	7/1/2016	1700 Ruxton Ave	21216	Pipe Break	WWO	Gwynns Falls	8,845	Cloudy water	8,845	Maintenance performed repair on mainline, overflow is abated	CCTV mainline, maintenance repaired mainline. Overflow is no longer ongoing.	315834
3	7/1/2016	3007 Ridgewood Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine.	Used H-Cutter to bring back rags and roots.	315819
4	7/3/2016	1503 W Mulberry St	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Grease and debris	Evidence of Overflow	Pressure truck relieved mainline choke with 150 ft of pressure hose.	CCTV	316048
5	7/4/2016	N. Pine St & W. Saratoga St	21201	Rags, Grease	WWO	Inner Harbor	480	Rags and sewage	48,000	Overflow caused by sinkhole, repairs are ongoing. Bypass pumping is in place to abate peak flows.	Larger scale bypass pumping will be installed to facilitate repairs to failed sewer pipe.	316074
6	7/5/2016	4940 Eastern Eve	21224	Rags, Grease	WWO	N/A	Not Witnessed	Wet around manhole, toilet paper	Evidence of Overflow	Relieved mainline choke with 400 ft of sewer jet	Cleared line of rags and debris to prevent future overflows	316680
7	7/6/2016	3404 Woodbine Ave	21207	Rags, Pipe Break	WWO	N/A	Not Witnessed	Sewage and debris	Evidence of Overflow	Ran 40 ft of electric machine, broken house connection. Turned over for repair.	CCTV	317020
8	7/6/2016	6367 Boston St	21224	Rags, Grease	WWO	Inner Harbor	1,614	Gray murky water	8,070	Relieved mainline choke with 260 ft of pressure machine hose.	Turned over for CCTV	316884
9	7/7/2016	1112 Bryn Mawr Rd	21210	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	214	Gray water and sewage overflowing	1,070	Relieved mainline choke with 400 ft of pressure truck on 10" line	Removed rags and roots to prevent future overflows	317625
10	7/7/2016	401 Overhill Rd	21210	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	272	Debris and sewage overflowing	1,360	Relieved mainline choke with 400 ft of pressure hose on 8" sanitary line.	CCTV	317662
11	7/11/2016	1729 Chilton St	21218	Pipe Break	WWO	N/A	Not Witnessed	Light paper around cleanout	Evidence of Overflow	Cleaned line with electric machine	Line to be CCTV'd	318235
12	7/12/2016	1106 N Glimor St	21217	Rags, Roots	DWO	N/A	Not Witnessed	Paper and muck	Evidence of Overflow	Relieved house connection choke with 60 ft of electric machine cable.	CCTV	318752
13	7/13/2016	4100 Keswick Rd	21210	Rags, Roots	WWO	N/A	61	Gray water overflowing	305	Relieved mainline choke with 200 ft of pressure truck on 6" line	CCTV	319201
14	7/13/2016	118 Taplow Rd	21212	Roots	WWO	N/A	Not Witnessed	Wet around clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	319599
15	7/14/2016	1109 N Carey St	21217	Sand, Gravel, Rocks, Pipe Break	WWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Ran 13 ft of electric machine to try and relieve house connection choke	Flushed mainline 200ft, initiated bypass pumping	319968
16	7/18/2016	6301 Leith Walk	21239	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	Chinquapin Run	86	Murky colored water overflowing	430	Jetted line with 100 ft of pressure hose to relieve mainline choke	Turned over for CCTV	321833

SSO Notification List

July 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	7/18/2016	3500 Bancroft Rd	21215	Rags, Roots	WWO	N/A	Not Witnessed	Wet area around clean out	Evidence of Overflow	Relieved house connection choke with 75 ft of electric machine	Removed roots and CCTV'd connection	321055
18	7/20/2016	428 E Preston St	21202	Rags, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	96	Sewer water overflowing	96	Used 30 ft of electric machine with h-cutter, also cleaned and flushed the mainline	CCTV both lines	321761
19	7/20/2016	617 Ploy St	21201	Other	DWO	Inner Harbor	16	Small bypass pipe leaking sewage	80	Contractor shutoff the bypass pump stopping the flow to the leaking pipe.	Leaking pipe is no longer being used	
20	7/21/2016	3920 Norfolk Ave	21216	Rags, Roots	DWO	N/A	Not Witnessed	Heavy gray water and debris	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	322426
21	7/23/2016	3100 Ferndale Ave	21207	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Wet around manhole	Evidence of Overflow	Used 300 ft of pressure truck hose to flush sanitary mainline	CCTV	322848
22	7/25/2016	1322 W Pratt St	21223	Rags	WWO	N/A	Not Witnessed	Gray water and evidence around the clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	Turned over for root control	323526
23	7/26/2016	3012 W Lanvale St	21216	Rags, Roots	DWO	N/A	Not Witnessed	Gray debris	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6 in line	CCTV	323765
24	7/26/2016	1709 Latrobe St	21202	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Sewer and water evidence	Evidence of Overflow	Cleaned line with 30 ft of electric machine and H-cutter	Line will be CCTV'd	323773
25	7/26/2016	1715 Lancaster St	21231	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water around clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6 in line	CCTV	323958
26	7/27/2016	1924 E 30th St	21218	Roots	DWO	Herring Run	201	Clear colored water overflowing	201	Cleaned line with 30 ft of electric machine	Used h-cutter to clear roots	324242
27	7/28/2016	2103 Cliftwood Ave	21213	Rags, Trash, Sand, Gravel, Rocks	WWO	Inner Harbor	77	Clear colored water overflowing	385	Relieved mainline choke with 300 ft of pressure hose	Mainline has been flushed and cleaned, marked for manhole inspection	326188
28	7/28/2016	3213 Bancroft Rd	21215	Pipe Break	DWO	Jones Falls	247	Sewage leaking into storm drain underground from a shifted pipe	1,235	Initiated bypass pumping to stop leak and abate overflow. Turned over to construction for repair	CCTV, turned over to construction to fix damaged sewer line	326013
29	7/28/2016	4812 Frankford Ave	21206	Rags, Trash, Sand, Gravel, Rocks	DWO	Herring Run	Not Witnessed	Cloudy water	Evidence of Overflow	Cleaned 45 ft of house connection with electric machine	Used H-Cutter to remove roots	326007
30	7/28/2016	SSO #152 - N Charles St and W Lanvale St	21201	Rain	WWO	Jones Falls	820	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed	14,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
31	7/29/2016	4800 Tamarind Ave	21209	Roots, Grease	WWO	N/A	119	Brown water overflowing	595	Relieved mainline choke on 8 in line with 40 ft of pressure hose	Mainline CCTV	326412

