

SSO Notification List

November 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2016	516 W Preston St	21201	Rags, Sand, Gravel, Rocks, Structural	DWO		119	Overflowing from private manhole going into public storm drain about 8 gpm down curb line.	595	Relieved choke by pumping down manhole and using pressure truck to flush 2 in line.	Customer will repair break in private sewer line.	363476
2	11/1/2016	1112 Bryn Mawr Rd	21210	Rags, Roots, Trash	DWO	Jones Falls	181	Overflowing manhole in stream, found during routine sampling. OCAL Nick 443-826-2904	1810	Relieved mainline choke with 300 ft of pressure truck on 10 in line.	Mainline CCTV inspection.	363497
3	11/1/2016	809 N Caroline St	21205	Rags, Trash	DWO		25	Sewer water overflowing out of the clean out.	25	Cleaned line with 45 ft of electric machine, relieved house connection choke.	House lateral CCTV inspection.	363557
4	11/1/2016	6231 Walther Ave	21206	Structural, Unknown	DWO	Moores Run	333	Unmapped sanitary manhole overflowing in the rear of Glenmont Middle School. Found by OCAL during routine ammonia sampling. Any questions call Mike 410-428-5511	1,665	Partially relieved sanitary mainline choke with 175 ft of pressure machine hose.	Mainline CCTV inspection.	363575
5	11/4/2016	1160 Homestead St	21218	Trash, Structural	DWO		425	Sewer water and toilet paper	6,375	Pressure truck flushed mainline 215 ft, unable to relieve choke. Turned over to PM shift.	Mainline CCTV inspection.	364461
6	11/5/2016	5012 The Alameda	21239	Trash	DWO		0	Paper and evidence around the clean out.	10	Relieved house connection choke with 45 ft of electric machine.	House lateral CCTV inspection.	364560
7	11/4/2016	2611 W Fairmount Ave	21223	Rags, Trash	DWO		0	Gray water and debris	5	Relieved house connection choke with 45 ft of electric machine.	House lateral CCTV inspection.	364431
8	11/6/2016	1107 Anglesea St	21224	Trash	DWO		0	Paper and evidence around clean out.	3	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	364622
9	11/6/2016	5420 Todd Ave	21206	Rags, Roots	DWO		186	Murky water overflowing from house connection	372	Cleaned line with 45 ft of electric machine, and used H-cutter to remove roots.	House lateral CCTV inspection.	364652
10	11/7/2016	2543 Marbourne Ave	21230	Rags	DWO		0	Heavy gray water and debris	4	Relieved house connection choke with 45 ft of electric machine on 6" line.	House lateral CCTV inspection.	364702
11	11/9/2016	2518 Druid Park Dr	21215	Rags, Roots	WWO	Jones Falls	145	Sewage discharge from hole in ground on the hillside. OCAL Nick 443-826-2904	1,015	Relieved mainline choke with 150 ft of pressure truck on 6 in line.	Mainline CCTV inspection.	365014
12	11/10/2016	2800 Rosalind Ave	21215	Rags, Grease	WWO		0	Cloudy water around clean out	38	Relieved house connection choke with 200 ft of pressure truck.	Lateral CCTV inspection.	365238
13	11/10/2016	2410 Saint Paul St	21218	Rags, Trash	WWO		0	Gray Water and debris	10	Relieved house connection choke with 35 ft of electric machine.	House lateral CCTV inspection.	365365
14	11/12/2016	319 E 22nd St	21218	Rags, Roots, Grease	DWO		47	Toilet paper and rags overflowing	47	Relieved house connection choke with 45 ft of electric machine	House lateral CCTV inspection	365513
15	11/13/2016	2313 Hamilton Ave	21214	Rags	DWO		0	Gray water and debris	4	Relieved house connection choke with 45 ft of electric machine on 6 in line.	House lateral CCTV inspection.	365556
16	11/13/2016	1520 E Biddle St	21213	Rags	DWO		10	Toilet paper and sewage	10	Relieved house connection choke with 30 ft of electronic machine	House lateral CCTV inspection	365566
17	11/14/2016	526 N Carrollton St	21223	Rags, Roots	DWO		0	Gray water and debris around clean out	10	Relieved house connection choke with 45 ft of electric machine on 6 in line.	House lateral CCTV inspection.	365726
18	11/16/2016	2402 Talbot Rd	21216	Structural	DWO	Gwynns Falls	10634	Collapsed pipe causing overflow.	10,634	On-site contractor engaged to repair broken pipe	Bypass pumping was put in place, overflow has been abated.	

SSO Notification List

November 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
19	11/17/2016	Darley Ave and N Wolfe St	21213	Rags, Grease, Trash	DWO		0	Gray water and debris.	40	Relieved mainline choke with 200 ft of pressure truck.	Mainline CCTV inspection.	366675
20	11/19/2016	131 W Lanvale St	21217	Rags, Roots	WVO		0	Gray water and debris	5	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	366997
21	11/20/2016	2000 W Saratoga St	21223	Rags, Trash	WVO	Gwynns Falls	89	Gray water overflowing from manhole	178	Relieved mainline choke with 220 ft of pressure machine hose.	Mainline CCTV inspection.	367137
22	11/21/2016	Western Run Dr and Bonnie View Dr	21209	Rags, Grease, Trash	WVO		0	Gray water and debris	30	Relieved mainline choke with 50 ft of pressure hose.	Mainline CCTV inspection.	367261
23	11/22/2016	2109 E North Ave	21213	Trash, Structural	DWO	Northwest Harbor	77	Uncharted house connection choke causing overflow of wastewater. Found during OCAL pollution source tracking.	5	Relieved house connection choke with 11ft of electric machine.	House lateral CCTV inspection.	367627
24	11/22/2016	2403 Talbot Rd	21216	Rags, Grease, Trash	DWO	Gwynns Falls	44	Overflowing manhole in street. OCAL Nick 443-826-2904	11	Relieved mainline choke with 35 ft of pressure hose	Mainline CCTV inspection on 6 in line.	367660
25	11/23/2016	2805 Bookert Dr	21225	Rags, Roots	DWO		0	Dampness around clean out.	5	Relieved house connection choke with 60 ft of electric machine.	CCTV inspection.	368062
26	11/24/2016	1917 E Hoffman St	21213	Rags, Trash	DWO		0	Light paper and trash.	4	Cleaned 30 ft of house connection with electric machine.	House lateral CCTV inspection.	368126
27	11/28/2016	3723 Clarenell Rd	21229	Rags, Roots	DWO		0	Gray water and evidence around the house connection	7	Relieved house connection choke with 45 ft of electric machine.	House lateral CCTV inspection.	368620
28	11/29/2016	403 Old Orchard Rd	21229	Structural	WVO	Maidens Choice	3226	Broken main line pipe overflowing into stream. OCAL Nick 4438262904	6,808	Broken mainline repaired by contractor, no longer overflowing.	Contractor was engaged to repair damaged mainline.	368495
29	11/29/2016	4306 Belview Ave	21215	Rags, Roots	WVO		0	Gray water and debris.	10	Relieved house connection choke with 60 ft of electric machine.	Mainline CCTV inspection and house lateral CCTV inspection.	369016
30	11/30/2016	2518 Druid Park Drive	21215	Rags, Trash, Structural	WVO	Jones Falls	227	Sewage flowing from hole in hillside. OCAL NICK 443-826-2904	3,405	Relieved mainline choke with 100 ft of pressure truck on 8 in line.	Mainline CCTV inspection.	369178
				# WVO	9			TOTAL	33,140	UNDER 100 GALLONS	20	