

## SSO Notification List

October 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/1/2016	4507 Roland Ave	21210	Rags, Roots	WVO	Jones Falls	256	Cloudy water	1,280	Relieved mainline choke with 300 ft of pressure truck on 6 inch line.	Mainline CCTV inspection.	355980
2	10/2/2016	2708 Woodland Ave	21215	Structural, Other	WVO	Jones Falls	38	Cloudy water overflowing	380	Talked to consumer about the sump pump problem, she stated that she will get a plumber.	Relieved mainline choke, consumers need clean outs.	356048
3	10/2/2016	1107 Anglesea St	21224	Rags	WVO		0	Paper and rags	5	Relieved house connection choke with 30 ft of electric machine	House lateral CCTV inspection.	356071
4	10/3/2016	901 Allendale St	21229	Rags, Roots, Trash	WVO		349	Raw sewage and debris flowing from manhole.	3,490	Relieved house connection choke with 250 ft of pressure truck on 8 in line	Mainline CCTV inspection	356190
5	10/4/2016	2905 Woodland Ave	21215	Rags, Roots, Grease	DWO	Jones Falls	0	Overflow at cleanout. less than 50 gallons. OCAL Nick 443-826-2904	15	Relieved house connection choke with 45 ft of electric machine on 6 in line	House lateral CCTV inspection	356443
6	10/5/2016	500 N Hilton St	21229	Rags	DWO	Gwynns Falls	316	Sewage flowing from the clean out.	948	Relieved house connection and mainline choke with 200 ft of pressure truck on 6" line	Lateral CCTV inspection	357498
7	10/5/2016	2910 Woodland Ave	21215	Infiltration, Structural	DWO	Jones Falls	90,663	Sanitary lateral leaking into storm sewer. OCAL Nick 443-826-2904	9,066	Damaged house connection repaired by contractor.	Contractor repaired damaged house connection.	
8	10/6/2016	5616 Frankford Ave	21206	Roots	DWO		81	Gray water	405	Relieved house connection choke with 30 ft of electric machine. Also used saw tooth and expander cutter.	Lateral CCTV inspection	358022
9	10/11/2016	2730 N Longwood St	21216	Rags, Grease, Trash	DWO		208	Gray murky water with paper.	624	Relieved house connection choke with 60 ft of 6" electric machine cable, and used auger and spear head.	CCTV	358867
10	10/11/2016	228 Mount Olivet Ln	21223	Rags, Structural	DWO		54676	Gray water	5,468	Contractor repaired leaking pipe, no longer ongoing.	Mainline CCTV inspection.	358861
11	10/11/2016	219 S. Collins Ave.	21229	Rags, Roots, Grease	DWO		301	Gray water.	602	Flushed and cleaned 8" sanitary mainline, used 400 ft of pressure hose removed grease, roots, and debris.	CCTV	358935
12	10/13/2016	4722 York Rd	21212	Rags, Grease	DWO	Tiffany Run	151	Mainline choke at 4722 York Rd. causing a subsurface SSO into adjacent storm drain system	151	Flushed and cleaned 200 ft of 8" sanitary mainline, brought back grease and debris.	CCTV	359379
13	10/14/2016	827 N Martin Luther King Jr Blvd	21201	Rags, Roots	DWO		257	Sewer water and toilet paper	257	Relieved house connection choke with 7 ft of electric machine.	House lateral CCTV inspection.	359636
14	10/14/2016	226 S Mount Olivet Ln	21223	Structural	DWO		77,788	Heavy gray water leaking from sewer line.	7,779	Sewer leak from 18" inch mainline in the wooded area. Turned over to construction and contractor to repair.	Contractor performed external repairs on damaged pipe.	359637
15	10/14/2016	4902 Pennington Ave	21226	Rags, Roots	DWO		65	Sewer water overflowing from the clean out.	65	Relieved house connection choke with 45' of electric machine.	House lateral CCTV inspection.	359760
16	10/14/2016	4315 Lasalle Ave	21206	Rags, Roots, Trash	DWO		0	Gray water and debris.	5	Relieved house connection choke with 105' of electric machine.	House lateral CCTV inspection.	359776
17	10/15/2016	2518 Druid Park Dr	21215	Roots	DWO	Gwynns Falls	0	Signs of sewage debris on the ground and side of hill.	40	Relieved mainline choke with 100 ft of pressure truck, could not go any farther due to hole in line.	Turned over to construction to repair broken mainline.	359802
18	10/15/2016	1160 Homestead St	21218	Grease, Trash	DWO	Herring Run	428	Sewer water overflowing	4,280	Relieved mainline choke with 300 ft of pressure hose on 8 in sewer line.	Mainline CCTV inspection at this location.	359811
19	10/16/2016	3144 Elmora Ave	21213	Rags, Trash	DWO		0	Gray water and debris.	10	Relieved mainline choke with 350 ft of pressure hose.	Mainline CCTV inspection.	359898
20	10/17/2016	3921 Boarman Ave	21215	Rags, Roots	DWO		0	Gray water and debris	10	Relieved house connection choke with 45 ft of electric machine on 6" line	House lateral CCTV inspection	359967

## SSO Notification List

October 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	10/17/2016	E Fairmount Ave and N Washington St	21231	Rags, Grease, Trash	DWO	Harbor	42	Sewer water overflowing from manhole	210	Relieved mainline choke with 150 ft of pressure machine hose, mainline is clear.	Mainline CCTV inspection	360140
22	10/18/2016	2402 Talbot Rd	21216	Rags, Roots	DWO	Gwynns Falls	0	Sewage overflowing into adjacent storm drain pipe then discharging into stream. OCAL Nick 443-826-2904	0	Manhole is damaged, overflow is currently ongoing.	Turned over to construction for repairs.	360307
23	10/18/2016	2402 Talbot Rd	21216	Structural	DWO		895	Gray water leaking from house connection.	895	House connection was damaged and leaking, Utility Maintenance Division repaired connection.	Turned over to construction to repair damaged house connection.	360393
24	10/19/2016	4117 Massachusetts Ave	21229	Rags, Roots	DWO		0	Heavy gray water and debris	8	Relieved house connection choke with 15 ft of electric machine on 6" line	House lateral CCTV inspection	360491
25	10/19/2016	3300 Windsor Ave	21216	Rags, Roots	DWO		0	Sewage evidence around clean out.	5	Relieved house connection choke with 30 ft of electric machine on 6" line	House lateral CCTV inspection.	360637
26	10/20/2016	3103 Ferndale Ave	21207	Rags, Roots, Trash	DWO		0	Gray water and evidence	3	Relieved house connection choke with 45 ft of electric machine.	House lateral CCTV inspection.	361097
27	10/21/2016	3404 Woodbine Ave	21207	Trash	WWO		0	Paper and evidence around the clean out	4	Left door notice to install proper clean out.	House lateral CCTV inspection.	361151
28	10/21/2016	1328 N Calhoun St	21217	Trash	WWO		0	Gray water and debris	10	Left door notice to remove the clean out and place it close to the city line, clean out is located too close to building.	Left plumbers notice.	361267
29	10/22/2016	600 Wyndhurst Ave	21210	Rags, Trash	WWO		33	Sewer water overflowing	66	Pressure truck relieved mainline choke with 250 ft of pressure machine hose.	Mainline CCTV inspection.	361505
30	10/22/2016	710 N Fulton Ave	21217	Rags, Roots	WWO		0	Gray water overflowing	3	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV	361502
31	10/24/2016	1902 W Fairmount Ave	21223	Rags, Roots	WWO		0	Toilet paper and rags	10	Cleaned house connection with 30ft of electric machine	House lateral CCTV inspection	361695
32	10/24/2016	236 N Milton Ave	21224	Roots	WWO		0	Toilet paper and evidence around house connection	2	Relieved house connection choke with 60 ft of electric machine	House lateral CCTV inspection	361761
33	10/24/2016	3826 West Bay Ave	21225	Rags, Trash	WWO		0	Sewage evidence and muck found around clean out	5	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	361901
34	10/25/2016	1410 Gusryan St	21224	Trash	DWO		0	Sewer water around manhole	40	Relieved mainline choke with 230 ft of pressure hose	Mainline CCTV inspection	361962
35	10/25/2016	2723 W North Ave	21216	Roots	DWO		0	Paper and debris around clean out	10	Relieved house connection choke with 45 ft of electric machine, used H-Cutter to remove tree roots	House lateral CCTV inspection	362010
36	10/25/2016	325 Yale Ave	21229	Trash	DWO		0	Cloudy water	8	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	362056
37	10/26/2016	5615 York Rd	21212	Grease	DWO		20	Coming from clean out pipe	60	Relieved house connection choke with 45 ft of electric machine	Lateral CCTV inspection.	362369
38	10/26/2016	5800 Northwood Dr	21239	Rags, Grease, Trash	DWO		90	Gray water overflowing.	90	Relieved mainline choke with 100 ft of pressure machine hose.	Mainline CCTV inspection.	362478

## SSO Notification List

October 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
39	10/28/2016	3729 Greenmount Ave	21218	Rags, Trash, Structural	WVO		0	Gray water around cleanout in yard, cleanout is holding water. Found during OCAL pollution source tracking.	4	Could not relieve choke due to broke pipe, cable is coming out of the ground, used 15ft of cable. Turned over to housing and to night shift for a second opinion.	CCTV after plumber fixes the problem.	362932
40	10/28/2016	29 Blythewood Rd	21210	Rags, Roots	WVO		0	Sewage and black water around clean out	8	Attempted to clean house connection with 45 ft of electric machine.	Mainline CCTV inspection.	362970
41	10/30/2016	3128 Weaver Ave	21214	Rags, Roots	DWO		0	Gray water and muck	5	Relieved house connection choke with 45 ft of electric machine	House lateral CCTV inspection	363125
42	10/31/2016	307 S Smallwood St	21223	Rags, Grease, Trash	DWO		0	Gray water and debris	5	Relieved house connection choke with 30 ft of electric machine on 6 in line	Mainline cleaning and house lateral CCTV inspection.	363238
43	10/31/2016	2346 E Fayette St	21224	Rags, Grease, Trash	DWO		0	Gray Water	8	Relieved house connection choke with 35 ft of electric machine.	House lateral CCTV inspection.	362356
				# WVO	13			TOTAL	36,338	UNDER 100 GALLONS	28	