

SSO Notification List

April 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/3/2023	1129 N Fulton Ave	21217	Rags	Wet	N/A		Sewage and rags observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection confirmed the line is clear.	1210858
2	4/5/2023	E Monument St & N Wolfe St	21287	Rags, Trash	Dry	N/A	81	Gray water escaping the manhole.	243	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will determine if further action is needed.	1211447
3	4/7/2023	3407 Edmondson Ave	21229	Rags, Grease	Dry	Gwynns Falls	144	Gray water escaping the manhole in the street.	1440	Relieved mainline choke with 150 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1211942
4	4/7/2023	Lawina Rd & Fairfax Rd	21216	Rags, Grease, Trash	Dry	Gwynns Falls	57	Gray water escaping the manhole and entering nearby storm drain.	285	Relieved mainline choke with 150 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1212030
5	4/7/2023	2805 Walbrook Ave	21216	Rags	Dry	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the line is clear at this time.	1212040
6	4/7/2023	4641 Park Heights Ave	21215	Sand, Gravel, Rocks	Wet	N/A	290	Water escaping the cleanout at the front of the property.	29	Relieved house connection choke with 15 ft of electric cable.	Confirmed line is clear and advised consumer to remove mud on their side of pipe.	1212061
7	4/9/2023	3305 Taney Rd	21215	Roots	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral and mainline are clear.	1212127
8	4/10/2023	E Monument St & N Wolfe St	21287	Rags, Grease	Dry	Northwest Harbor	255	Gray water escaping the manhole in the street.	255	Relieved mainline choke with 250 ft of pressure hose.	Performed CCTV inspection and confirmed the line is now clear.	1212270
9	4/10/2023	2006 Fleet St	21231	Roots	Dry	N/A		Gray water observed at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1212505
10	4/11/2023	1430 McCulloh St	21217	Rags, Grease	Dry	N/A		Paper and gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1212800
11	4/12/2023	313 E Cold Spring Ln	21212	Rags, Roots	Dry	N/A	35	Gray water escaping the cleanout at the rear of the property.	7	Blockage relieved with 60 ft of electric machine cable using various cutters.	CCTV inspection will determine if further steps need to be taken.	1213093
12	4/12/2023	12 Hillside Rd	21210	Structural	Dry	N/A		Gray water observed at the front of the property.	3	Investigated location; lateral will need to be repaired.	Regular functionality will be restored once repairs are made.	1213767
13	4/13/2023	641 W University Pkwy	21210	Rags, Trash	Dry	Stony Run	190	Heavy gray water escaping the manhole and entering storm drain.	760	Used high-pressure jet truck to relieve mainline choke.	CCTV inspection will be performed to determine if further steps are needed.	1213876
14	4/14/2023	309 Mosher St	21217	Sand, Gravel, Rocks	Dry	Jones Falls		Heavy gray water observed around the manhole.	15	Relieved mainline choke with 400 ft of pressure hose.	Line will be vacuumed and have CCTV inspection performed.	1214006
15	4/14/2023	6203 Wallis Ave	21215	Rags, Trash	Dry	Western Run	197	Mainline choke causing SSO and discharge to storm drain.	1970	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1214193
16	4/14/2023	5110 Frederick Ave	21229	Rags, Grease	Dry	Maidens Choice	185	Gray water escaping the manhole.	185	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1214275
17	4/17/2023	423 E Hamburg St	21230	Roots	Wet	N/A		Gray water and paper observed around the cleanout.	1	Blockage relieved with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear. Lining may be necessary.	1214591
18	4/18/2023	2617 W Fairmount Ave	21223	Rags, Grease	Dry	Gwynns Falls	78	SSO discovered during routine water sampling. Sewage entering nearby storm drain.	390	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1214973
19	4/19/2023	5015 Boxhill Ln	21210	Rags, Roots	Dry	Stony Run	176	Choked sewer main overflowing into adjacent storm pipe.	880	Relieved mainline choke with 150 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1215265
20	4/19/2023	Boston St & Steelton Ave	21224	Rags, Grease, Trash	Dry	Inner Harbor	59	Gray water escaping the manhole and reaching a storm drain.	590	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	1215296

SSO Notification List

April 2023

21	4/19/2023	142 W Lanvale St	21217	Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; mainline will be flushed.	1215409
22	4/24/2023	3505 Lyndale Ave	21213	Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	1216631
23	4/25/2023	2803 Elgin Ave	21216	Rags, Roots, Grease	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 200 ft of pressure hose.	Confirmed the lateral and mainline are both clear at this time.	1216777
24	4/25/2023	5713 Edgepark Rd	21239	Rags, Roots, Grease	Dry	N/A		Sewage and water observed around the manhole in the street.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	1217165
25	4/25/2023	5110 Frederick Ave	21229	Rags, Roots, Grease	Dry	Maidens Choice	659	Gray water escaping the manhole.	659	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is now clear; CCTV inspection will be performed.	1217185
26	4/26/2023	1127 E Lombard St	21202	Rags, Grease, Trash	Dry	N/A		Gray water observed around the manhole in the street.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1217501
27	4/28/2023	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	115	Structure monitored by metering equipment in the pipe. Not visually observed.	110055	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
28	4/30/2023	702 S Broadway	21231	Rags	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1218427
29	4/30/2023	31 S Washington St	21231	Rags, Grease	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection to confirm lateral is clear.	1218455
				# WWO	9			TOTAL	117,783	UNDER 100 GALLONS	17	