

SSO Notification List

August 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/1/2019	1802 Guilford Ave	21202	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	15	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	753789
2	8/1/2019	1407 Park Ave	21217	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1.5	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	755039
3	8/2/2019	3506 Berwyn Ave	21207	Rags, Roots, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	755302
4	8/5/2019	Dillon St & Oldham St	21224	Rags, Trash	Wet	N/A	115	Gray water escaping the manhole in the street.	173	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	756002
5	8/6/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	55	Structure monitored by metering equipment in the pipe.	52,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
6	8/6/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	180	Structure monitored by metering equipment in the pipe.	1,078,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
7	8/6/2019	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	55	Structure monitored by metering equipment in the pipe.	3,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
8	8/7/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	35	Manhole adjacent to creek overflowed due to heavy rain.	742,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
9	8/8/2019	2819 Overland Ave	21214	Structural	Wet	Herring Run	370	Choked main causing overflow into storm pipe and discharging from storm water outfall.	1,850	Bypass pumping installed to stop the overflow.	Eventual point repair work will restore system to regular functionality.	
10	8/10/2019	1002 Light St	21230	Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with electric cable.	Confirmed lateral and mainline are clear.	757580
11	8/12/2019	1015 W 37th St	21211	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	758243
12	8/12/2019	839 Ramsay St	21230	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed lateral is clear.	758193
13	8/13/2019	1514 Lester Morton Ct	21205	Rags, Trash, Structural	Dry	N/A	0	Gray water and debris observed near the cleanout.	30	Flushed the mainline and set up bypass pumping to reroute lateral flow to abate the overflow.	Point repair work on twin lateral will restore the system to regular functionality.	758432
14	8/14/2019	1200 Steelton Ave - Private	21224	Rags, Grease, Trash	Dry	N/A	515	Gray water, grease, and debris escaping the manhole.	1,030	Relieved mainline choke with 400 ft of pressure hose.	Performed CCTV inspection.	759512
15	8/17/2019	1121 McDonogh St	21213	Rags, Grease	Dry	Harbor	72	Gray water escaping the cleanout at the rear of the property.	72	Relieved house connection choke with 15 ft of electric cable, sawtooth, and auger.	Performed lateral CCTV inspection.	760354
16	8/18/2019	2078 Echodale Ave	21214	Rags, Rain	Wet	Herring Run	244	Water escaping the manhole in the street.	1,220	Relieved mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection; confirmed line is clear.	760461
17	8/18/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	35	Structure monitored by metered equipment in the pipe. Not visually observed.	13,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
18	8/19/2019	13 N Eilwood Ave	21224	Rags, Grease	Wet	Harbor	0	Gray water observed near the cleanout at the rear of the property.	15	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	760708
19	8/22/2019	2819 Overland Ave	21214	Structural	Dry	Herring Run	150	Sewage entering adjacent storm drain pipe.	150	Contractor adjusted bypass pumps to abate the overflow.	Added 10 feet of heavier hose to prevent discharge.	

SSO Notification List

August 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	8/22/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	125	Structure monitored by metering equipment in the pipe.	15,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
21	8/22/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	215	Structure monitored by metering equipment in the pipe.	801,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
22	8/22/2019	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	30	Structure monitored by metering equipment in the pipe.	14,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
23	8/22/2019	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in pipe	4,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
24	8/22/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	90	Manhole adjacent to creek overflowed due to heavy rain.	7,778,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
25	8/22/2019	1901 Falls Rd	21218	Rain	Wet	Jones Falls	20	Manhole surcharging due to heavy rain event.	6,000	Overflow subsided following heavy rain event.	Location is monitored by an Event Notification System.	
26	8/24/2019	3502 Beech Ave	21211	Rags, Roots, Trash	Wet	N/A	1067	Heavy gray water escaping the manhole.	1,601	Relieved mainline choke with 350 ft of pressure hose.	Mainline CCTV inspection will be performed.	763622
27	8/26/2019	833 E Belvedere Ave	21212	Rags, Roots	Dry	N/A	0	Gray water observed around the manhole.	15	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	764419
28	8/27/2019	3321 Piedmont Ave	21216	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	3	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection; confirmed lines are clear.	764863
29	8/28/2019	914 Wilmington Ave	21223	Structural	Dry	Maidens Choice	0	Sanitary sewer mainline leaking into stream, confirmed via dye test.	Ongoing	Construction crews are determining a solution to resolve the issue.	Bypass pump may be installed if pipe is not able to be quickly repaired.	765371
				# WWO	19			TOTAL	10,511,150	UNDER 100 GALLONS	12	