

SSO Notification List

August 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/1/2020	570 W Preston St - (Private)	21201	Rags, Trash	Wet	N/A	0	Gray water observed around the manhole.	5	Flushed the mainline with pressure hose.	This is not a public line maintained by the City of Baltimore.	875359
2	8/4/2020	1901 Falls Rd	21211	Rain	Wet	Jones Falls	410	Heavy gray water escaping manholes.	410,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	875798
3	8/4/2020	100 N Bond St	21231	Rain, Infiltration	Wet	Inner Harbor	63	Gray water discharging from manhole in the street.	6,300	Pipe capacity was exceeded due to heavy storm. Overflow subsided following rain event.	Flushed the line with 200 ft of pressure hose. CCTV inspection will be performed.	875852
4	8/4/2020	3417 Liberty Heights Ave	21216	Rags, Roots, Rain	Wet	Gwynns Falls	75	Gray water discharging from the manhole in front of the property.	3,750	Relieved mainline choke with 400 ft of pressure hose.	CCTV inspection will be performed.	875813
5	8/4/2020	1800 E Eager St	21205	Rain	Wet	Inner Harbor	255	Heavy rain causing manhole to surcharge.	51,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	875800
6	8/4/2020	1731 E Chase St	21213	Rain	Wet	Inner Harbor	295	Manhole surcharging due to heavy rain. Confirmed via metering equipment.	59,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	875801
7	8/4/2020	518 Old Orchard Rd	21229	Rags, Trash, Sand, Gravel, Rocks, Structural	Wet	Gwynns Falls	303	Gray water escaping the manhole.	606	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear. CCTV will be performed to determine structural damage. Bypass may be needed.	875955
8	8/4/2020	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	100	Structure monitored by metering equipment in pipe. Not visually observed.	100,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital improvement projects.	
9	8/4/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	195	Structure discharges to a storm drain and is monitored by metering equipment in the pipe.	238,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
10	8/4/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	425	Structure discharges to a storm drain and is monitored by metering equipment in the pipe.	1,533,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
11	8/4/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	425	Structure is monitored by metering equipment in the pipe. Not visually observed.	1,283,500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	8/4/2020	N Charles St & Lafayette Ave - SSO Site #154	21202	Rain	Wet	Jones Falls	115	Structure monitored by metering equipment in pipe. Not visually observed.	650,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
13	8/4/2020	W Cold Spring Ln & Ayrdale Ave - SSO Site #138	21215	Rain	Wet	Gwynns Falls	140	Structure monitored by metering equipment in the pipe. Not visually observed.	48,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
14	8/4/2020	W Garrison Ave & Queensberry Ave - SSO Site #139	21215	Rain	Wet	Jones Falls	90	Structured overflow discharging to a nearby storm drain.	14,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
15	8/4/2020	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	90	Structure monitored by metered equipment in the pipe. Not visually observed.	9,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
16	8/4/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	255	Manhole adjacent to creek overflowed due to heavy rain.	1,783,000	Overflow subsided following heavy rain event.	SSO will be prevented after completion of capital improvement projects.	
17	8/4/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	295	Manhole overflowing during heavy rain. Confirmed via metering equipment.	174,640	Overflow subsided following heavy rain event.	SSO will be prevented after completion of capital improvement projects.	
18	8/4/2020	200 E 32nd St	21218	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout and sidewalk.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	875960
19	8/7/2020	3605 Cedardale Rd	21215	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	876510
20	8/7/2020	518 N Carrollton Ave	21223	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	877666
21	8/7/2020	3038 Remington Ave	21211	Rags, Roots, Trash	Wet	Jones Falls	0	Gray water observed around the cleanout at the front of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	877686

SSO Notification List

August 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	8/9/2020	3526 Old Frederick Rd	21229	Rags, Trash	Wet	N/A	0	Gray water and debris observed at the rear of the property.	2	Relieved house connection choke with 90 ft of electric cable.	Performed CCTV inspection. Left notice for consumer to have internal plumbing investigated.	877772
23	8/10/2020	7001 Reisterstown Rd	21215	Rags, Grease, Trash	Wet	N/A	48	Choked mainline causing subsurface overflow into storm drain. Found during routine sampling.	960	Relieved mainline choke with 350 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	877854
24	8/10/2020	4722 York Rd	21212	Grease	Wet	Tiffany Run	125	Mainline choke causing subsurface overflow into nearby storm drain. Found during routine sampling.	31	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear and overflow was abated. CCTV inspection will be performed.	877894
25	8/11/2020	604 Oldham St	21224	Sand, Gravel, Rocks, Structural	Dry	Chinquapin Run	160	Wastewater discharging from cleanout.	40	Relieved choke with 15 ft of electric cable to abate the overflow.	CCTV inspection determined structural damage is present. Line will be repaired.	878016
26	8/12/2020	506 S Central Ave	21231	Other	Dry	Inner Harbor	224	High flow in 60" mainline causing a backup and wastewater is infiltrating the adjacent storm drain.	112	Nearby pump station increased pumping rate to return flow to normal.	Further interdepartmental coordination will take place to determine a solution to prevent reoccurrence.	
27	8/12/2020	408 E 31st St	21218	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	878236
28	8/12/2020	1901 Falls Rd	21211	Rain, Trash	Wet	Jones Falls	110	Heavy gray water escaping the manhole.	1,100	Overflow subsided following heavy rain event.	Eventual capital improvement project will prevent this location from frequently overflowing.	878335
29	8/12/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	35	Structure monitored by metering equipment in the pipe. Not visually observed.	7,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
30	8/12/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	65	Structure monitored by metering equipment in the pipe. Not visually observed.	94,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
31	8/12/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	65	Structure monitored by metering equipment in the pipe. Not visually observed.	94,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
32	8/12/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	290	Manhole overflowed due to heavy rain.	18,000	Overflow subsided following heavy rain event.	SSO will be prevented after completion of capital projects.	
33	8/12/2020	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	50	Structure monitored by metering equipment in the pipe. Not visually observed.	8,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
34	8/13/2020	1512 W Lanvale St	21217	Rags, Trash, Structural	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 17 ft of electric cable through the pipe.	Flushed and cleaned the mainline. Investigation will take place, including performing a lateral launch.	878476
35	8/13/2020	1701 Sulgrave Ave	21209	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved mainline choke with 300 ft of pressure hose. Ran 45 ft of electric cable through the lateral.	Confirmed mainline and house connection are clear.	878520
36	8/14/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	120	Gray water escaping the manhole.	7,440	Overflow subsided following heavy rain event.	Eventual capital improvement project will prevent repeated future overflows.	878664
37	8/14/2020	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	65	Structure monitored by metered equipment in the pipe. Not visually observed.	4,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
38	8/15/2020	1932 McCulloh St	21217	Rags, Trash, Unknown	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	3	Flushed and cleaned the main. Buildup of trash bags made the area inaccessible for lateral work.	Left notice informing the consumer of the issue. Confirmed mainline is clear.	878714
39	8/18/2020	837 W Lombard St	21201	Roots, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable. Flushed and cleaned 8" mainline.	Performed CCTV inspection; confirmed lateral is clear.	879122
40	8/20/2020	5600 Harford Rd	21214	Rags, Trash, Sand, Gravel, Rocks	Wet	Herring Run	1404	Mainline choke causing sewage to enter nearby storm drain; found during routine monitoring.	14,040	Relieved mainline choke with 250 ft of pressure hose.	Performed CCTV inspection.	879447
41	8/21/2020	5813 Loch Raven Blvd	21239	Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear. CCTV inspection and mainline cleaning will be performed.	879673
42	8/24/2020	1816 Poplar Grove St	21216	Trash, Unknown	Dry	N/A	0	Gray water observed in the street.	6	Flushed and cleaned 8" mainline with 50 ft of pressure hose.	CCTV inspection will be performed to determine additional blockage or structural issues.	879813

SSO Notification List

August 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
43	8/24/2020	Gary Ave & Steelton Ave - (Private)	21224	Rags, Grease, Trash	Dry	Inner Harbor	69	Gray water escaping private manhole.	690	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	879941
44	8/25/2020	604 Oldham St	21224	Structural	Dry	Inner Harbor	0	Cleanout overflowed due to break on city side.	10	Structural damage will be repaired to restore line to regular functionality.	Bypass pumping may be required while repairs take place.	880085
45	8/25/2020	3641 Greenmount Ave	21218	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	880158
46	8/27/2020	2732 W Lafayette Ave	21216	Rags	Dry	Gwynns Falls	288	Gray water escaping the cleanout at the rear of the property.	288	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	880469
47	8/27/2020	4701 Yellowwood Ave	21209	Rags, Structural	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved lateral choke with 7 ft of electric cable; determined structural damage to pipe is present.	CCTV inspection will be performed; pipe will be repaired.	880480
48	8/28/2020	3703 Everett St	21225	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the manhole at the rear of the property.	8	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	880642
49	8/28/2020	131 W Randall St	21230	Rags, Trash, Other	Dry	N/A	0	Gray water observed around the cleanout at the side of the property.	3	Relieved house connection choke with 15 ft of electric cable. Flushed and cleaned the mainline.	Performed lateral CCTV inspection.	880686
50	8/28/2020	2901 W North Ave	21216	Trash, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	2	Flushed and cleaned the mainline with 57 ft of pressure hose.	CCTV inspection will be performed to obtain more information.	880702
51	8/31/2020	4260 Clydesdale Ave	21211	Rags, Roots, Grease, Trash	Wet	N/A	189	Gray water escaping the manhole.	1,890	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	880855
				# WWO	38			TOTAL	6,614,761	UNDER 100 GALLONS	20	