

SSO Notification List

January 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2020	4001 Falls Rd	21211	Rags, Grease, Trash	Wet	N/A	210	Gray water escaping the manhole in the street.	210	Relieved 8" mainline choke with 300 ft of pressure hose.	Cleaned the mainline; confirmed line is clear.	821604
2	1/1/2020	2716 Saint Paul St	21218	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	821606
3	1/2/2020	13 N Ellwood Ave	21224	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	821730
4	1/2/2020	4022 Clarks Ln	21215	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole on the sidewalk.	7	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed line is clear.	821777
5	1/4/2020	2702 Bookert Dr	21225	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	822966
6	1/5/2020	617 E 35th St	21218	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	823223
7	1/6/2020	3309 Saint Ambrose Ave	21215	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 9 ft of electric cable.	Lateral CCTV inspection will be performed; confirmed mainline is clear.	823425
8	1/6/2020	200 Westway	21212	Rags, Trash	Wet	N/A	42	Sewer mainline leaking into adjacent subsurface storm drain.	210	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed discharge is no longer occurring via dye test. CCTV inspection will be performed.	823435
9	1/6/2020	1631 Gwynns Falls Pkwy	21217	Rags, Grease, Trash	Wet	N/A	92	Gray water and debris intermittently escaping the cleanout at the rear of the property.	23	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	823554
10	1/7/2020	4814 Seton Dr	21215	Rags, Trash	Wet	Gwynns Falls	0	Heavy gray water and debris observed around the cleanout at the front of the property.	10	Relieved 6" choke with 30 ft of pressure hose. Notified to replace the cleanout cap.	CCTV inspection will be performed; confirmed lateral and mainline are clear.	823650
11	1/7/2020	2123 Annapolis Rd	21230	Trash, Structural	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	4	Ran 10 ft of electric cable through lateral, unable to fully relieve the choke due to structural damage.	Bypass pumping will be set up to prevent further discharge while repairs to the line are made.	823802
12	1/8/2020	2131 Callow Ave	21217	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	824416
13	1/8/2020	2202 E Fairmount Ave	21231	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable. Flushed and cleaned 8" mainline.	Performed CCTV inspection; confirmed lateral and mainline are clear.	824404
14	1/11/2020	600 N Martin Luther King Jr Blvd	21201	Rags, Grease, Trash	Dry	Inner Harbor	205	Water escaping the manhole in the street.	410	Relieved 10" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	825736
15	1/13/2020	1525 Edmondson Ave	21223	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	826242
16	1/13/2020	513 W Mulberry St	21201	Rags, Grease, Trash, Structural, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	5	Ran 75 ft of electric cable through lateral; some blockage remained.	Location will be continue to be investigated; bypass pumping may be needed to prevent further discharge.	826246
17	1/13/2020	1110 Walnut Ave	21229	Roots, Trash	Wet	N/A	0	Water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	826256
18	1/15/2020	3500 Parkdale Ave	21211	Other	Dry	Jones Falls	2727	Sewage pump basin overflowing into storm pipe.	8,181	System was maintained and cleaned; regular functionality has resumed.	Currently designing new infrastructure solutions for this area. Bypass pumping will remain in the interim.	
19	1/16/2020	2215 Chelsea Ter	21216	Rags, Roots, Trash	Dry	Gwynns Falls	63	Mainline choke discovered while conducting routine stream sampling.	32	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear via dye testing.	828579

SSO Notification List

January 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	1/17/2020	806 N Fulton Ave	21217	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	828750
21	1/17/2020	4715 Homesdale Ave	21206	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	829115
22	1/17/2020	121 S Augusta Ave	21229	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection and mainline cleaning will be performed.	829097
23	1/20/2020	810 N Hilton St	21229	Rags, Trash	Wet	Gwynns Falls	103	Gray water escaping the manhole and entering a nearby storm drain.	206	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	829796
24	1/20/2020	1809 Bolton St	21217	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	829804
25	1/20/2020	2219 E Lombard St	21231	Trash, Structural	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 13 ft of electric cable through the lateral; blockage remained.	Repairs will need to be made to the line. Bypass pumping will be set up to prevent further discharge.	829853
26	1/20/2020	22 S Tremont Rd	21229	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV connection; confirmed line is clear.	829831
27	1/21/2020	1200 N Franklinton Rd	21216	Rags, Grease, Trash, Structural	Wet	Gwynns Falls	75	Heavy gray water escaping the manhole.	375	Relieved 8" mainline choke with 35 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	830056
28	1/21/2020	1313 Southview Rd	21218	Rags, Trash	Wet	N/A	380	Gray water escaping the manhole in the alley.	190	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	830866
29	1/21/2020	2926 Virginia Ave	21215	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	830896
30	1/22/2020	1927 Kelly Ave	21209	Rags	Dry	N/A	0	Gray water observed around the cleanout.	9	Relieved house connection choke with 5 ft of electric cable.	CCTV inspection will be performed.	831038
31	1/22/2020	6714 Holabird Ave	21222	Rags, Grease, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	3	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	831252
32	1/24/2020	2922 E Northern Pkwy	21234	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	832019
33	1/25/2020	4029 N Rogers Ave	21207	Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the side of the property.	5	Relieved house connection choke with 13 ft of electric cable.	Performed CCTV inspection.	832085
34	1/25/2020	3030 Poplar Ter	21216	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	7	Relieved house connection choke with 35 ft of electric cable and expander cutter.	Confirmed lateral is clear.	832147
35	1/25/2020	3502 Cottage Ave	21215	Rags, Roots, Grease, Trash	Wet	Jones Falls	711	Gray water escaping the manhole and entering storm drain.	14,220	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed line is clear.	832068
36	1/25/2020	1211 W Northern Pkwy	21209	Rags, Roots, Trash	Wet	Jones Falls	175	Gray water escaping the cleanout at the front of the property.	88	Relieved choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	832141
37	1/25/2020	238 S Loudon Ave	21229	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	832155
38	1/25/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	340	Structure monitored by metered equipment in the pipe. Not visually observed.	1,357,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	

SSO Notification List

January 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
39	1/25/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	160	Manhole adjacent to creek overflowed due to heavy rain.	4,831,000	Overflow subsided following a heavy rain event.	Eventual capital improvement projects will upsize the system.	
40	1/25/2020	1901 Falls Rd	21218	Rain	Wet	Jones Falls	130	Heavy gray water escaping the manhole in the street.	475,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	832058
41	1/25/2020	1800 E Eager St	21205	Rain	Wet	Inner Harbor	25	Manhole surcharging due to heavy rain.	500	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	832070
42	1/25/2020	1731 E Chase St	21205	Rain	Wet	Inner Harbor	60	Manhole surcharging due to heavy rain.	74,000	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	832071
43	1/25/2020	1901 Falls Rd	21205	Rain	Wet	Inner Harbor	130	Heavy gray water escaping the manhole.	13,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	832073
44	1/25/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	530	Structure monitored by metered equipment in the pipe. Not visually observed.	4,854,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
45	1/26/2020	3930 Lowndes Ave	21218	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	832226
46	1/27/2020	3609 Howard Park Ave	21207	Rags, Trash, Unknown	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	1	Ran 60 ft of electric cable through lateral. Flushed and cleaned 8" mainline.	CCTV inspection will be performed along with further investigation of blockage in lateral.	832749
47	1/29/2020	3939 Falls Rd	21211	Rags, Roots, Grease, Trash	Dry	Jones Falls	405	Gray water escaping the manhole.	405	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	833320
48	1/29/2020	5000 Litchfield Ave	21215	Trash, Sand, Gravel, Rocks, Structural	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	1	Ran 25 ft of electric cable through lateral; determined structural damage was present.	House connection will be repaired. Pump set up to prohibit further discharge in the interim.	833819
49	1/30/2020	265 W 31st St	21211	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	834195
50	1/30/2020	6007 Falls Rd	21209	Rags, Trash	Dry	Jones Falls	135	Gray water escaping the cleanout at the front of the property.	270	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	834239
51	1/31/2020	4505 Frederick Ave	21229	Rags, Grease, Trash	Dry	N/A	0	Heavy gray water and paper observed around the cleanout.	15	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	834323
52	1/31/2020	3000 Chestnut Ave	21211	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	1	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	834511
				# WWO	37			TOTAL	11,629,425	UNDER 100 GALLONS	35	