

## SSO Notification List

January 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2024	1216 Riverside Ave	21230	Rags, Trash	Dry	—	—	Gray water observed near the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral is clear.	1285933
2	1/2/2024	2900 Herkimer St	21230	Unknown	Dry	Gwynns Falls	—	Water and sewage observed near manhole and storm drain.	3	Choke relieved itself naturally.	CCTV inspection will be performed to ensure all obstructions are gone.	1285966
3	1/2/2024	3605 Parkside Dr	21206	Rags, Grease, Trash	Dry	—	—	Gray water observed in the alley at the rear of the property.	3	Relieved mainline choke with 350 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1286173
4	1/3/2024	1839 W North Ave	21217	Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1286374
5	1/4/2024	1412 N Luzerne Ave	21213	Rags, Trash	Dry	—	—	Gray water and debris observed around the cleanout.	3	Relieved house connection choke with 35 ft of electric cable.	Confirmed line is clear; advised consumer not to flush sanitary wipes.	1286605
6	1/5/2024	2509 Edmondson Ave	21223	Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	1287228
7	1/6/2024	3134 Gwynns Falls Pkwy	21216	Rags, Roots, Rain	Wet	Gwynns Falls	75	Gray water escaping the manhole and reaching storm drain.	1125	Relieved mainline choke with 350 ft of pressure hose.	CCTV inspection will determine if further steps are needed to stop or reduce SSO from occurring.	1287439
8	1/7/2024	2432 Fait Ave	21224	Rags, Roots	Wet	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	1287442
9	1/9/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	645	Manhole adjacent to creek overflowed due to heavy rain.	975240	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
10	1/9/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	965	Structure monitored by metering equipment in the pipe. Not visually observed.	4115725	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
11	1/9/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	805	Structure monitored by metered equipment in the pipe. Not visually observed	9160900	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
12	1/9/2024	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	410	Structure monitored by metering equipment in the pipe.	27060	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
13	1/9/2024	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	415	Structure monitored by metered equipment in the pipe. Not visually observed.	70965	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	1/9/2024	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	345	Structure monitored by metering equipment in pipe.	126960	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
15	1/9/2024	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	250	Heavy gray water escaping the manhole.	43000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
16	1/9/2024	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	145	Structure monitored by metered equipment in the pipe. Not visually observed.	47995	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
17	1/9/2024	N Charles St & W Lafayette Ave - SSO Site #154	21201	Rain	Wet	Jones Falls	85	Structure monitored by metering equipment in the pipe. Not visually observed.	595	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
18	1/10/2024	3511 Gelston Dr	21229	Rags, Roots, Trash	Wet	Gwynns Falls	—	Gray water and debris observed near the manhole and storm drain.	10	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1288253
19	1/11/2024	3024 Gwynns Falls Pkwy	21216	Roots, Grease	Wet	Gwynns Falls	1630	Gray water escaping the manhole and entering storm drain.	1630	Relieved mainline choke with 280 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1288594
20	1/12/2024	408 E North Ave	21202	Rags, Roots, Grease	Wet	—	—	Gray water and debris observed at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection will be performed.	1288957

SSO Notification List

January 2024

21	1/12/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	45	Manhole adjacent to creek overflowed due to heavy rain.	108000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
22	1/15/2024	612 N Carrollton Ave	21217	Rags, Roots	Wet	—	—	Gray water observed at the rear of the property.	3	Relieved house connection choke with 90 ft of electric cable.	CCTV will be performed and location will be placed on routine cleaning due to roots.	1289326
23	1/16/2024	2423 Fait Ave	21224	Roots	Dry	—	—	Gray water observed around the front cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear; CCTV will be performed.	1290252
24	1/17/2024	901 Chauncey Ave	21217	Rags	Dry	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	—
25	1/18/2024	<i>Filbert St &amp; W Bay Ave - Private</i>	21225	Rags, Trash	Dry	Inner Harbor	109	Privately-owned manhole surcharging in the street.	(109)	DPW assisted by relieving mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	1290583
26	1/19/2024	2700 Cheswolde Rd	21209	Rags, Trash	Dry	—	—	Gray water observed near the cleanout at the side of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	1291397
27	1/23/2024	3206 Clarks Ln	21215	Rags, Trash	Wet	—	—	Gray water observed near the manhole.	4	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	1292696
28	1/24/2024	4813 Seton Dr	21215	Rags	Wet	—	—	Gray water and paper observed near the cleanout.	1	Relieved house connection choke with 95 ft of electric cable.	Confirmed the lateral is clear at this time.	1292963
29	1/26/2024	1521 Park Ave	21217	Rags, Trash	Wet	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	1301323
30	1/26/2024	3701 Clarenell Rd	21229	Rags, Grease, Trash	Wet	Maidens Choice	—	Sewage observed around the manhole and nearby storm drain.	5	Relieved mainline choke with 280 ft of pressure hose.	CCTV will be performed; confirmed line is clear at this time.	1302381
31	1/26/2024	3701 Mactavish Ave	21229	Rags, Infiltration, Trash	Wet	Maidens Choice	1430	Choked mainline causing a subsurface SSO; entering storm drain system.	7150	Relieved mainline choke with 300 ft of pressure hose.	Abatement confirmed via the Office of Research & Environmental Protection.	1303162
32	1/28/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	220	Manhole adjacent to creek overflowed due to heavy rain.	126060	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
33	1/28/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	305	Structure monitored by metering equipment in the pipe. Not visually observed.	1213900	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
34	1/28/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	270	Structure monitored by metering equipment in the pipe. Not visually observed.	490,995	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
35	1/28/2024	3800 Mactavish Ave	21229	Roots, Grease	Wet	Maidens Choice	312	Sewage escaping the manhole in front of the property.	312	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1304538
36	1/29/2024	1522 E Biddle St	21213	Rags	Wet	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed the lateral is clear at this time.	1304633
37	1/29/2024	3301 Towanda Ave	21215	Rags, Trash	Wet	Jones Falls	1188	Sewage overflowing from manhole and reaching storm drain system.	5,940	Relieved mainline choke with 250 ft of electric cable.	Confirmed the line is clear; CCTV inspection will be performed.	1304926
38	1/30/2024	1831 S Charles St	21230	Rags, Grease, Trash	Wet	—	—	Mainline choke causing cleanout to overflow.	3	Relieved mainline choke with 300 ft of electric cable.	CCTV inspection will be performed to ensure all obstructions were removed.	1304981
39	1/31/2024	4014 Linkwood Rd	21210	Rags, Grease, Trash	Dry	Stony Run	2294	Gray water escaping multiple manholes and entering nearby stream.	11,470	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear at this time; CCTV will be performed.	1306567
40	1/31/2024	3601 Fords Ln	21215	Rags, Roots	Dry	Western Run	160	Heavy wastewater discharge from cleanouts; entering storm drain.	4,000	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the line is now clear.	1306719
				# WWO	28			TOTAL	16,539,069	UNDER 100 GALLONS	19	