

SSO Notification List

June 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/3/2024	2345 Washington Blvd	21230	Rags, Grease, Trash	Dry	—	145	Wastewater escaping the manhole.	145	Relieved mainline choke with 250 ft of pressure hose.	CCTV confirmed the line is now clear.	1348292
2	6/3/2024	3601 Fords Ln	21215	Rags, Roots	Dry	—	—	Water and debris observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1348578
3	6/4/2024	3600 Clarks Ln	21215	Rags, Trash	Dry	—	—	Water and debris observed near rear cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1348795
4	6/5/2024	2500 Queens Anne Rd	21216	Rags, Roots	Dry	—	—	Wastewater and paper observed at the side of the property.	3	Relieved house connection choke with 75 ft of electric cable; flushed the mainline.	CCTV inspection will be performed.	1349105
5	6/5/2024	3700 Erdman Ave	21202	Rags, Trash	Dry	Jones Falls	60	Choked mainline causing subsurface SSO infiltrating storm drain.	120	Relieved mainline choke with 200 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	—
6	6/10/2024	5401 York Rd	21212	Rags, Grease	Dry	Stony Run	236	Choked mainline causing discharge from sump pump into street and storm drain.	5900	Relieved 10" mainline choke with 500 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	1350304
7	6/10/2024	400 Key Hwy	21230	Rags, Grease	Dry	—	—	Wastewater and debris observed near the property.	5	Relieved mainline choke with 500 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	—
8	6/12/2024	208 E Eager St	21202	Rags, Trash	Dry	—	—	Wastewater observed by the manhole in the street.	5	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV will be performed.	1350832
9	6/12/2024	3743 Nortonia Rd	21216	Roots, Trash	Dry	—	—	Gray water and debris observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	1350990
10	6/12/2024	726 N Carrollton Ave	21217	Roots, Grease	Dry	—	—	Wastewater observed near cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection performed.	1350775
11	6/14/2024	4104 Springdale Ave	21207	Rags, Trash	Dry	—	—	Wastewater observed near cleanout.	1	Ran 30 ft of electric cable through lateral; line is now clear.	CCTV inspection will be performed.	1351590
12	6/17/2024	4410 Frankford Ave	21206	Rags, Grease	Dry	Biddison Run	326	Choked sanitary sewer overflowing into adjacent storm drain pipe.	978	Relieved mainline choke with 300 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	1352086
13	6/18/2024	1923 W Lafayette Ave	21217	Rags, Trash	Dry	Gwynns Falls	—	Water and paper observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1352257
14	6/18/2024	915 Belgian Ave	21218	Rags, Roots, Grease	Dry	Tiffany Run	180	Subsurface SSO causing wastewater to reach storm drain system.	180	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1352379
15	6/19/2024	2464 Lakeview Ave	21217	Rags, Grease	Dry	Jones Falls	318	Wastewater escaping the manhole in the street.	636	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is flowing freely; CCTV will be performed.	1352451
16	6/19/2024	1202 Havenwood Rd	21218	Rags, Roots	Dry	—	300	Wastewater escaping the cleanout.	30	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection and mainline cleaning will be performed.	1352470
17	6/19/2024	818 E 35th St	21218	Rags	Dry	—	—	Gray water and paper observed near cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed lateral is now clear.	1352479
18	6/20/2024	1142 Monroe Cir	21225	Rags, Roots	Dry	—	—	Gray water and debris observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; CCTV will be performed.	1352628
19	6/22/2024	1512 Poplar Grove St	21216	Roots	Dry	—	—	Water and paper observed near cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	1353088
20	6/23/2024	4418 Shamrock Ave	21206	Rags, Roots, Trash	Dry	—	12800	Wastewater observed near the manhole in the street.	10	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection and mainline cleaning will take place.	1353190

SSO Notification List

June 2024

21	6/24/2024	4410 Frankford Ave	21206	Rags, Trash	Wet	Biddison Run	66	Choked sanitary sewer overflowing into adjacent storm drain pipe.	198	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1353400
22	6/26/2024	4318 Willshire Ave	21206	Structural Damage	Wet	Moores Run	8506	Choked sanitary sewer overflowing into adjacent storm pipe.	4253	Repairs were made to the mainline to stop the SSO.	Abatement confirmed via Office of Research & Environmental Protection.	1353904
23	6/26/2024	2231 Rogene Dr - Private	21209	Rags	Wet	Western Run	(1470)	Wastewater escaping private cleanout.	1470	DPW assisted by relieving house connection choke.	Advised consumer that this is private responsibility.	—
24	6/27/2024	4702 Wakefield Rd	21216	Rags, Roots	Wet	—	—	Gray water and paper observed near cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV will be performed.	—
25	6/27/2024	Longview Ave & Ravenwood Ave	21213	Rags, Trash	Wet	Herring Run	—	Wastewater escaping manhole in the street.	1000	Relieved mainline choke with 300 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	1354230
26	6/30/2024	6000 Falkirk Rd	21239	Rags	Wet	—	—	Water and paper observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	1354564
				# WWO	6			TOTAL	13,474	UNDER 100 GALLONS	16	