

SSO Notification List

May 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2020	4205 N Charles St	21218	Rags, Grease, Trash	Wet	Jones Falls	425	Gray water escaping the manhole.	850	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	860461
2	5/2/2020	2318 Montebello Ter	21214	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed the mainline.	860534
3	5/2/2020	1803 N Payson St	21217	Rags, Grease, Trash	Wet	N/A	72	Gray water escaping the manhole.	108	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	860561
4	5/3/2020	436 Kane St	21224	Rags, Grease, Trash	Wet	Inner Harbor	474	Heavy gray water escaping the manhole.	2,370	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is clear.	860581
5	5/5/2020	821 S Dean St	21224	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection.	860857
6	5/5/2020	3943 Boarman Ave	21215	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	860942
7	5/7/2020	31 Merrymount Rd	21210	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole at the front of the property.	2	Relieved mainline choke with 170 ft of pressure hose.	Confirmed mainline is clear.	861135
8	5/7/2020	4029 Fairview Ave	21216	Roots	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed line is clear; CCTV inspection and mainline cleaning will be performed.	861149
9	5/7/2020	6509 O'Donnell St	21224	Rags, Grease, Trash	Wet	N/A	72	Gray water escaping the manhole.	3,600	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	861179
10	5/8/2020	2859 W Lanvale St	21216	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole at the front of the property.	1	Relieved mainline choke with 100 ft of pressure hose.	Confirmed mainline is clear.	861380
11	5/8/2020	5500 Wabash Ave	21215	Structural	Wet	Gwynns Falls	5910	Heavy gray water escaping a cleanout and entering nearby storm drain.	8,340	Contractors set up bypass pumping in order to stop the overflow.	Eventual repair will restore the line to regular functionality.	861310
12	5/10/2020	3511 Greenspring Ave	21209	Rags, Sand, Gravel, Rocks, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Ran electric cable and pressure hose to partially relieve the choke. Blockage remained on consumer's side.	Left notice to contact private plumber for potential issue on consumer's side of pipe.	862041
13	5/10/2020	2628 Lehman St	21223	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Left notice to contact a private plumber to investigate potential issue on consumer's side.	861510
14	5/10/2020	1248 N Gay St	21213	Rags, Grease	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	861521
15	5/13/2020	100 S Landwehr Ln	21223	Rags, Grease, Trash	Dry	Gwynns Falls	244	Gray water escaping the manhole and entering nearby storm drain.	732	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	862287
16	5/14/2020	2585 Edmondson Ave	21223	Rags, Infiltration, Trash	Dry	Gwynns Falls	50	Subsurface overflow discharging into storm drain.	650	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	862506
17	5/14/2020	4016 Pinkney Rd	21215	Rags, Grease, Trash	Dry	Gwynns Falls	95	Water discharging from sump pump and entering nearby storm drain.	190	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	862527
18	5/14/2020	2036 Druid Hill Ave	21217	Rags	Dry	Jones Falls	53	Gray water escaping the cleanout at the rear of the property.	11	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	862560
19	5/15/2020	1248 N Gay St	21213	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	862875
20	5/16/2020	2821 Beechland Ave	21214	Rags	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	862919
21	5/16/2020	2936 Harford Rd	21218	Rags, Unknown	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Ran 30 ft of electric cable through the lateral; some blockage remained.	CCTV and further investigation will take place. Bypass pumping may be required if problem persists.	861493

SSO Notification List

May 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	5/18/2020	2936 Harford Rd	21213	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	861493
23	5/18/2020	1213 W Northern Pwky	21209	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 15 ft of pressure hose.	Flushed and cleaned the mainline; confirmed lateral and mainline are clear.	863127
24	5/18/2020	2805 Orleans St	21224	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water and paper observed at the rear of the property.	3	Ran 15 ft of electric cable through the lateral; some blockage remained.	Bypass pumping will be integrated while further investigation takes place.	863196
25	5/20/2020	1600 N Lombard St	21231	Rags, Trash	Dry	Jones Falls	1341	Choked mainline leaking subsurface into adjacent storm water manhole.	671	Relieved mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear; performed CCTV inspection.	863478
26	5/20/2020	912 W Franklin St	21223	Trash, Structural	Dry	N/A	0	Gray water and paper observed at the rear of the property.	5	Relieved the choke with 15 ft of electric cable.	CCTV discovered structural damage on consumer's side of pipe.	863515
27	5/21/2020	4552 The Strand	21215	Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	7	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	863610
28	5/21/2020	3421 W Caton Ave	21229	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	4	Relieved house connection choke with electric cable and pressure hose.	Confirmed lines are clear.	863685
29	5/23/2020	2354 Nutmeg Ter	21209	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	10	Relieved choke with 45 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	863875
30	5/25/2020	725 Hollen Rd	21212	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed line is clear.	863985
31	5/25/2020	1917 Division St	21217	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved choke with electric cable and pressure hose.	CCTV inspection will be performed; flushed and cleaned the mainline.	863995
32	5/26/2020	1934 McCulloh St	21217	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with electric cable.	CCTV inspection will be performed; left notice for consumer to address cleanout cap.	864075
33	5/26/2020	4403 Liberty Heights Ave	21207	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	864104
34	5/26/2020	506 S Central Ave	21231	Rags, Grease, Trash	Dry	Inner Harbor	96	Choked mainline overflowing into adjacent storm drain pipe.	48	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	864164
35	5/26/2020	209 Goodwood Grdns	21210	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; performed CCTV inspection.	864248
36	5/26/2020	1919 Fairbank Rd	21209	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	1085	Gray water escaping the manhole.	2,170	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	864277
37	5/27/2020	2733 Prospect St	21216	Rags, Roots	Dry	Gwynns Falls	86	Heavy gray water escaping the cleanout at the rear of the property.	172	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	864432
38	5/27/2020	1248 N Gay St	21213	Rags, Roots, Grease	Dry	N/A	0	Gray water and paper observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	864435
39	5/27/2020	4212 Penhurst Ave	21215	Rags, Roots	Dry	N/A	0	Heavy gray water and paper observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	864484
40	5/27/2020	2535 Brookfield Ave	21217	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed; advised consumer to replace cleanout cap.	864511
				# WWO	19			TOTAL	19,991	UNDER 100 GALLONS	29	