

SSO Notification List

May 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/2/2024	513 W Mulberry St	21201	Unknown	Wet	—	—	Gray water and debris near the cleanout.	1	Ran electric cable; determined further action is needed.	CCTV will determine next steps; bypass may be needed.	1337811
2	5/6/2024	613 Charraway Rd	21229	Rags, Trash	Wet	—	—	Water and debris observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	1338623
3	5/8/2024	2415 W Franklin St	21223	Rags	Wet	Gwynns Falls	—	Water and paper observed near cleanout and storm drain.	2	Ran 13 ft of electric cable; determined structural damage exists in pipe.	Lateral will be repaired to restore system to regular functionality.	1339478
4	5/8/2024	2406 Woodbrook Ave	21217	Rags, Roots	Wet	—	—	Wastewater observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed lateral and mainline are clear.	1339514
5	5/8/2024	125 N Hilton St	21229	Rags, Trash	Wet	Gwynns Falls	115	Choked sanitary sewer overflowing into adjacent storm drain pipe.	575	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	1339324
6	5/20/2024	4719 York Rd	21212	Rags, Trash	Wet	Tiffany Run	238	Choked sanitary sewer overflowing into adjacent storm drain pipe.	238	Relieved mainline choke with 40 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1343636
7	5/20/2024	2040 Linden Ave	21217	Rags, Roots	Wet	—	—	Gray water observed near the cleanout.	1	Ran 30 ft of electric cable.	Confirmed the line is clear.	1343697
8	5/22/2024	Cross Country Blvd & Dale Rd	21209	Structural Damage	Dry	Western Run	TBD	Sanitary sewer assets leaking into adjacent storm drain pipe.	TBD	Sent to contractor for CIPP lining.	Lining will stop the leak to abate overflow.	1344335
9	5/22/2024	1923 W Lafayette Ave	21217	Trash, Unknown	Dry	—	—	Gray water and paper observed near cleanout.	1	Ran 15 ft of electric cable through the lateral; blockage remained.	CCTV inspection will be performed.	1344538
10	5/23/2024	332 Broadmoor Rd	21212	Grease	Dry	Stony Run	7680	Choked sanitary sewer overflowing into adjacent storm drain pipe.	153600	Mainline was repaired to stop the overflow.	CCTV inspection and dye testing will be performed.	1344812
11	5/23/2024	300 W 28th St	21211	Rags, Trash	Wet	Jones Falls	405	Wastewater and rags discharging from manhole cover.	405	Relieved mainline choke with 300 ft of pressure hose.	Line confirmed clear; CCTV to be performed.	1344619
12	5/27/2024	726 N Carrollton Ave	21217	Rags, Grease	Wet	—	—	Wastewater and rags observed near cleanout.	7	Choke relieved with 60 ft of electric cable.	Lateral CCTV inspection will be performed.	1345294
13	5/27/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	35	Structure monitored by metering equipment in the pipe. Not visually observed.	22015	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	5/27/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	50	Manhole adjacent to creek overflowed due to heavy rain.	31000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
15	5/27/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	110	Structure monitored by metering equipment in the pipe. Not visually observed.	143000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
16	5/28/2024	210 Deepdene Rd	21210	Roots	Wet	—	—	Gray water and debris near the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear; CCTV will be performed.	1345669
17	5/29/2024	2907 Wayne Ave	21207	Rags, Roots	Wet	—	—	Wastewater and paper observed near cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection to confirm line is clear.	1346979
18	5/31/2024	104 Elmhurst Rd	21210	Roots	Wet	—	—	Water and paper observed near the rear cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	1347434
				# WWO	15			TOTAL	350,851	UNDER 100 GALLONS	10	