

SSO Notification List

November 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/2/2020	500 W University Pkwy	21210	Rags, Roots, Grease, Trash	Wet	N/A	194	Heavy gray water escaping the manhole.	2,910	Relieved mainline choke with 375 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	890083
2	11/4/2020	3221 Lyndale Ave	21213	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; cleaned the mainline.	890330
3	11/4/2020	702 W University Pkwy	21210	Rags, Trash	Dry	Jones Falls	0	Gray water observed around the manhole.	6	Relieved mainline choke with 150 ft of pressure hose.	Performed CCTV inspection; confirmed line is clear.	890404
4	11/5/2020	1923 N Rosedale St - Private	21216	Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Advised the consumer to contact a private plumber for internal issue.	Consumer needs to replace older-style trap so that work can be performed.	890560
5	11/5/2020	6701 Quad Ave	21237	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 75 ft of electric cable.	Confirmed lateral is clear.	890531
6	11/8/2020	1840 W Fairmount Ave	21223	Rags, Trash	Dry	Gwynns Falls	116	Gray water escaping the manhole in the street.	232	Relieved 8" mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed.	890825
7	11/9/2020	5813 Loch Raven Blvd	21239	Roots	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	890980
8	11/9/2020	131 W Randall St	21230	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	890987
9	11/10/2020	247 N Luzerne Ave	21224	Rags, Trash	Dry	N/A	0	Gray water observed in the rear alley.	5	Relieved mainline choke with 40 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	891052
10	11/10/2020	2806 Roselawn Ave	21214	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	891105
11	11/11/2020	4013 Hilton Rd	21215	Rags, Roots, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	891249
12	11/11/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	70	Manhole adjacent to creek overflowed due to heavy rain.	284,000	Overflow subsided following heavy rain event.	Capital improvement projects will reduce occurrences.	891284
13	11/11/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1155	Structure monitored by metering equipment in the pipe. Not visually observed.	4,256,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
14	11/13/2020	3011 Cresmont Ave	21211	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	891490
15	11/13/2020	408 E 31st St	21218	Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection.	891531
16	11/14/2020	5007 Greenhill Ave	21206	Rags, Roots	Wet	Herring Run	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	891654
17	11/14/2020	1606 Light St	21230	Rags, Roots	Wet	Inner Harbor	0	Gray water observed at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	891645
18	11/15/2020	2749 W Lafayette Ave	21216	Trash, Unknown	Wet	N/A	0	Gray water observed at the rear of the property.	1	Work was unable to be performed due to lack of line accessibility.	Advised consumer to contact a plumber to replace their older-style trap to prevent future incidents.	891690

SSO Notification List

November 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
19	11/15/2020	3601 Parkside Dr	21206	Trash	Wet	N/A	0	Gray water observed near the manhole at the rear of the property.	5	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	891698
20	11/16/2020	616 Woodbourne Ave	21212	Rags, Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	891804
21	11/17/2020	2800 Rosalind Ave	21215	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout.	3	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	891881
22	11/17/2020	616 Oldham St	21224	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	3	Relieved house connection choke with 15 ft of electric cable.	CCTV inspection will be performed. Advised that cleanout location be moved.	891930
23	11/17/2020	102 N Fremont Ave	21201	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 90 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	891994
24	11/18/2020	6701 Quad Ave	21237	Rags, Roots	Dry	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	892033
25	11/18/2020	5214 Beaufort Ave	21215	Trash, Unknown	Dry	N/A	0	Gray water observed around the cleanout on the side of property.	1	Unable to service external cleanout. It appears an obstruction is stuck in the stack pipe.	Left notice to fix or repair external cleanout located on the side of property.	892106
26	11/19/2020	1733 Ensor St	21202	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole in the street.	10	Relieved mainline choke with 280 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	892249
27	11/22/2020	2416 Harriet Ave	21230	Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	892589
28	11/23/2020	1912 W Lexington St - Private	21223	Structural	Dry	N/A	0	Gray water and debris observed around cleanout at the rear of the property.	3	Ran 11 ft of electric cable through the lateral; structural issue exists on the consumer's pipe.	Advised consumer to contact a private plumber to address the issue.	892675
29	11/23/2020	1508 Madison Ave	21217	Sand, Gravel, Rocks, Structural, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 22 ft of electric cable through the lateral; blockage remained.	CCTV and further investigation will take place. Repairs and/or bypass pumping may be required.	892720
30	11/24/2020	725 E 23rd St	21218	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	5	Relieved mainline choke with 150 ft of pressure hose.	CCTV inspection will be performed.	892823
31	11/24/2020	2902 Grindon Ave	21214	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Ran 45 ft of electric cable through lateral. Flushed the mainline with 150 ft of pressure hose.	Confirmed lines are clear.	892862
32	11/24/2020	3623 Milford Ave	21207	Rags, Roots, Trash	Dry	N/A	0	Heavy gray water and debris observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	892884
33	11/25/2020	4109 Massachusetts Ave	21229	Rags, Roots, Grease	Dry	N/A	0	Heavy gray water observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable. Flushed and cleaned the mainline.	CCTV inspection will be performed.	892969
34	11/26/2020	616 Woodbourne Ave	21212	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	893099
35	11/28/2020	503 Edgevale Rd	21210	Rags, Roots, Grease	Wet	N/A	0	Gray water observed around the manhole.	3	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear.	893272
36	11/29/2020	2109 Kentucky Ave	21218	Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	893306

SSO Notification List

November 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
37	11/30/2020	1836 W Fairmont Ave	21223	Rags, Rain, Grease, Trash	Wet	Gwynns Falls	149	Gray water escaping the manhole.	2,235	Relieved mainline choke with 300 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	893434
38	11/30/2020	Crofton Rd & Loch Raven Blvd	21239	Rags, Rain, Grease	Wet	Herring Run	498	Gray water escaping the manhole in the street.	3,486	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	893445
39	11/30/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	800	Structure monitored by metering equipment in the pipe. Not visually observed.	4,410,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
40	11/30/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	30	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe.	500	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
41	11/30/2020	1731 E Chase St	21205	Rain	Wet	Inner Harbor	260	Gray water escaping the manhole in the street.	3,480,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	893386
42	11/30/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	330	Manhole adjacent to creek overflowed due to heavy rain.	1,197,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
43	11/30/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	125	Heavy gray water escaping manhole.	18,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	893371
44	11/30/2020	1901 Falls Rd	21211	Rain	Wet	Jones Falls	120	Bypass pump pit overflowing due to heavy rain event.	661,500	Overflow subsided following heavy rain event.	Multiple CIP projects will prevent this overflow from reoccurring in the future.	
				# WWO	21			TOTAL	14,315,953	UNDER 100 GALLONS	30	