

## SSO Notification List

November 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2023	118 N Fremont Ave	21201	Rags, Roots	Wet	—	—	Gray water observed around cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time.	1270957
2	11/9/2023	118 N Fremont Ave	21201	Roots, Trash	Dry	—	—	Gray water and debris around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1272755
3	11/11/2023	301 Edgevale Rd	21210	Roots	Wet	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	1273337
4	11/13/2023	6203 Greenspring Rd	21209	Rags	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 100 ft of electric cable.	CCTV confirmed the lateral is now clear.	1273575
5	11/14/2023	2300 Cylburn Ave	21209	Rags, Roots, Trash	Dry	Jones Falls	562	Sewage escaping the manhole in the street.	281	Relieved mainline choke with 400 ft of pressure hose.	CCTV inspection will be performed; mainline is clear at this time.	1273900
6	11/17/2023	3903 Pascal Ave	21226	Grease	Dry	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1274777
7	11/17/2023	1903 W North Ave	21217	Rags	Dry	—	—	Gray water observed in the rear alley.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	1275001
8	11/20/2023	1321 Park Ave	0	Roots, Trash	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	—
9	11/21/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	15	Manhole adjacent to creek overflowed due to heavy rain.	25005	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
10	11/21/2023	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	255	Structure monitored by metering equipment in the pipe. Not visually observed.	1265055	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
11	11/21/2023	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	325	Structure monitored by metering equipment in the pipe. Not visually observed.	748150	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
12	11/21/2023	5006 W Forest Park Ave	21207	Rain	Wet	Gwynns Falls	188	Sewage water discharging from manhole cover due to heavy rain event.	4700	Overflow subsided following heavy rain event.	Flushed the mainline with 250 ft of pressure hose.	1275658
13	11/24/2023	3033 Ascension St	21225	Rags, Grease	Wet	—	—	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV will be performed.	1276088
14	11/26/2023	3111 Frisby St	21218	Rags	Dry	—	—	Gray water observed near the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1276203
15	11/27/2023	1612 Elmtree St	21226	Rags, Grease	Wet	—	—	Gray water and rags observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1276378
16	11/27/2023	2601 Steele Rd	21209	Rags, Roots	Wet	—	—	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1276520
17	11/27/2023	2553 Madison Ave	21217	Rags, Unknown	Wet	—	—	Gray water and debris observed around the cleanout.	1	Ran 25 ft of electric cable through the lateral.	Further investigation, including CCTV inspection, will take place.	1276530
18	11/30/2023	5121 Liberty Heights Ave	21207	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 90 ft of electric cable.	CCTV confirmed the lateral is now clear.	1278938
				# WWO	10			TOTAL	2,043,205	UNDER 100 GALLONS	13	