

SSO Notification List

April 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2019	Edmondson Ave & Upper Ellicott Dr	212168	Unknown, Other	Dry	Gwynns Falls	90	Surcharging manhole at construction site. Contractor removed bypass pump from manhole causing an overflow.	9,000	Notified contractor to restart bypass pumping.	Contractor installed a new pump.	
2	4/3/2019	228 S Monastery Ave	21229	Rags, Roots, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	20	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	703259
3	4/3/2019	1819 Appleton St	21217	Rags, Grease, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	10	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	703396
4	4/3/2019	5211 Putney Way	21212	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	703547
5	4/4/2019	3623 Milford Ave	21207	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	704762
6	4/6/2019	3408 W Belvedere Ave	21215	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	15	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	705704
7	4/6/2019	4417 Kathland Ave	21207	Rags, Structural	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	7	Ran 15 ft of electric cable to remove rags and mud from the lateral.	Performed CCTV inspection; will investigate further for potential structural damage.	705709
8	4/7/2019	503 E 23rd St	21218	Structural, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	35	Referred location to Baltimore City Housing Department for an Emergency Sewer Investigation.	Advised that the vent pipe connection does not have a cap, allowing sewage discharge.	705748
9	4/8/2019	5618 Frankford Ave	21206	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	707558
10	4/9/2019	1401 Constellation Plaza - Private	21230	Rags, Grease, Trash	Dry	Harbor	85	Gray water escaping the manhole.	425	Relieved 8" mainline choke with 150 ft of pressure hose.	Confirmed mainline is clear.	708788
11	4/9/2019	1822 N Payson St	21217	Trash, Sand, Gravel, Rocks, Structural	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Ran 3 ft of electric cable, removed shiny blade.	Will return for follow-up investigation once rocks are removed from cleanout.	709113
12	4/9/2019	801 Spedden St	21217	Rags, Trash	Dry	N/A	0	Cleanout holding water; wastewater and debris observed nearby.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed lateral is clear; advised consumer to install cleanout cap.	708849
13	4/10/2019	101 Cotswold Rd	21210	Rags, Roots	Dry	N/A	82	Wastewater escaping the manhole.	82	Relieved 8" mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear.	709337
14	4/10/2019	5621 Belair Rd	21206	Rags, Grease	Dry	N/A	0	Heavy gray water and rags observed around the cleanout.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	709742
15	4/11/2019	3330 Reisterstown Rd	21215	Rags, Grease	Dry	N/A	0	Heavy gray water observed around the manhole.	5	Relieved mainline choke with 160 ft of pressure hose.	Performed mainline CCTV inspection.	710168
16	4/11/2019	Greenspring Ave & DuPont Ave	21209	Structural	Dry	Jones Falls	0	Wastewater leaking from house connection underground and infiltrating the storm drain.	Ongoing	Line will be repaired.	Bypass pumping may be set up to stop the overflow.	710510
17	4/12/2019	1002 Darley Ave	21218	Rags, Roots	Dry	Harbor	0	Gray water observed around the cleanout at the front of the property.	45	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	710695
18	4/12/2019	5701 Chinquapin Pkwy	21239	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the manhole.	10	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed CCTV inspection.	710924
19	4/13/2019	313 S Augusta Ave	21229	Trash, Structural	Dry	Gwynns Falls	0	Paper and gray water observed around the cleanout.	5	Ran 10 ft of electric cable in house connection.	Left notice to contact a plumber for private-side issue.	718969
20	4/13/2019	1525 Edmondson Ave	21223	Trash, Structural	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	7	This lateral is scheduled for repair.	Line will be repaired.	707277

