

SSO Notification List

August 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/1/2015	2013 Brunt St	21217	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of overflow around the clean out behind building	Evidence of Overflow	Flushed and cleaned 8" sanitary mainline, used 100' of pressure hose to remove rags and debris	CCTV	265056
2	8/2/2015	5015 Antanna Ave	21206	Roots	DWO	N/A	Not Witnessed	Gray water, sewage on the ground	Evidence of Overflow	Relieved mainline choke with 100' of pressure machine hose	CCTV	265088
3	8/3/2015	116 S Schroeder St	21223	Rags, Roots	WVO	N/A	Not Witnessed	Signs of an overflow around the clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6"	CCTV	265263
4	8/3/2015	5609 Liberty Heights Ave	21207	Rags, Roots	DWO	Gwynns Falls	300	Sewage discharging from manhole in woods. 50ft from street, observed by OCAL Nick	1,500	Relieved mainline choke with 400 ft of pressure truck on 8", removed grease, roots and rags	CCTV	265196
5	8/3/2015	Edmondson Ave and Hilton Pkwy	21223	Rags, Roots, Grease	DWO	Gwynns Falls	129	Heavy sewage discharge from manhole into stream. OCAL Nick M	6,450	Relieved mainline choke with 250 ft of pressure truck on 8"	CCTV	265194
6	8/6/2015	4625 Falls Rd	21211	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence and debris visible around the clean out	Evidence of Overflow	Relieved the connection choke with 60 ft of electric machine	CCTV	265757
7	8/7/2015	511 Westgate Rd	21229	Rags, Roots	DWO	N/A	Not Witnessed	Evidence of an overflow around the front house connection	Evidence of Overflow	Relieved the house connection choke with 30 ft of electric machine	CCTV	265947
8	8/8/2015	809 N Caroline St	21205	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Heavy paper around cleanout	Evidence of Overflow	Relieved house connection choke with 45ft of electric machine	CCTV	265994
9	8/10/2015	305 Cable St	21210	Rags, Roots	WVO	N/A	255	Murky black water	765	Relieved house connection choke with 150 ft of pressure truck and electric machine	CCTV	266112
10	8/10/2015	1331 N Stricker St	21217	Rags, Grease	WVO	N/A	Not Witnessed	Water and evidence visible around clean out	Evidence of Overflow	Relieved the house connection choke with 45' of electric machine	CCTV	266185
11	8/10/2015	1315 N Stockton St	21217	Rags, Roots	WVO	N/A	Not Witnessed	Dry debris around clean out	Evidence of Overflow	Used 35' of electric machine to relieve rear house connection choke	CCTV	266191
12	8/10/2015	N Charles St and E Lanvale Ave	21202	Rags, Grease	WVO	Jones Falls	105	Heavy sewage flowing into storm drain from overflow structure connected to adjacent sanitary line which is choked. OCAL Nick	2,625	Relieved mainline choke with 150 ft of pressure truck on 12" inch line	CCTV	266304
13	8/11/2015	2611 Kentucky Ave	21213	Rags, Roots	WVO	N/A	Not Witnessed	Wet around clean out, front connection choke.	Evidence of Overflow	Used 60 ft of electric machine to relieve front connection choke, removed roots	CCTV	266359
14	8/12/2015	4701 O'Donnell St	21224	Trash, Sand, Gravel, Rocks	WVO	Herring Run	122	Gray water coming from manhole	610	Relieved mainline choke with 162 ft of pressure hose	CCTV	266511
15	8/12/2015	3117 Calvert St	21218	Rags, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	20,050	Wastewater leaving sanitary line through cracks in pipe segment and entering into storm drain under ground. confirmed with dye test.	5,012	Area was excavated and pipe was repaired. SSO has been abated.	Repair has been confirmed with dye testing, no longer leaking.	266597
16	8/13/2015	1203 John St	21217	Rags, Roots	DWO	N/A	Not Witnessed	Paper and other evidence present around clean out	Evidence of Overflow	Used 15 ft of electric machine and H-Cutter to relieve house connection choke	CCTV	266841

SSO Notification List

August 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	8/13/2015	939 Oldham St	21224	Grease	DWO	Inner Harbor	299	Clear water discharging from sump pump on the side of the building	1,495	Relieved mainline choke, sump pump no longer discharging water	CCTV	266765
18	8/13/2015	4611 Wilmslow Rd	21210	Roots, Pipe Break	DWO	Stony Run	1,566	4611 Wilmslow Rd, main is leaking into adjacent storm drain pipe verified by dye testing. OCAL Nick	1,566	Turn over to construction for repair.	CCTV	266955
19	8/14/2015	3500 N Calvert St	21218	Infiltration/Inflow, Pipe Break, Other	DWO	Jones Falls	31,740	Leaving sanitary line at S35CC1024G1 and infiltrating adjacent storm water line on the 3500 block of N Calvert St.	6,495	Pipe has been repaired by contractor, infiltration has been stopped	Pipe repaired by contractor, no longer leaking	263758
20	8/15/2015	1111 N Stricker St	21217	Rags, Roots, Grease	DWO	N/A	456	Gray water and sewage flowing from clean out	456	Relieved house connection choke with 15 ft of electric machine on 6" line	CCTV	267021
21	8/17/2015	4616 Newgate Ave	21224	Pipe Break	DWO	Herring Run	2,807	Sewage leaking from ground at this address then flowing into adjacent storm drain inlet	701	SSO is no longer ongoing, repairs have been made to the pipe in question	Source of leak was identified and repaired	267198
22	8/18/2015	4501 Foster Ave	21224	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Inner Harbor	152	Murky gray water coming from the manhole	760	Jetted line with 200 ft of pressure hose, relieved mainline choke	Line to be CCTVd	267313
23	8/18/2015	4104 Fairview Ave	21216	Rags, Roots, Grease	DWO	Gwynns Falls	204	Heavy sewage flowing from sanitary into adjacent storm drain. OCAL Nick	5,100	Used 75' of pressure truck hose to relieve mainline choke	CCTV	267384
24	8/18/2015	308 Wendover Rd	21218	Roots, Grease	DWO	N/A	Not Witnessed	Evidence present around the clean out	Evidence of Overflow	Used 200' of sewer jet to remove roots and debris	CCTV	267428
25	8/18/2015	2109 Garrison Blvd	21216	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of overflow present around the clean out	Evidence of Overflow	Used 85' of electric machine and H cutter to remove rags and roots	CCTV	265940
26	8/18/2015	2700 E Chase St	21213	Rags, Grease	DWO	N/A	Not Witnessed	Water and evidence visible around the sump pump, evidence shows that sewage reached storm drain	Evidence of Overflow	Used 250 ft of sewer jet to relieve mainline choke	CCTV	267444
27	8/19/2015	500 N Edgewood St	21229	Rags, Grease, Infiltration, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	28,524	We observed an active sanitary sewer overflow with sewage flowing into adjacent storm drain underground. It was confirmed with dye tests. It was observed by OCAL, Mike	7,131	Overflow is no longer ongoing, pipebursting stopped sewage flowing into adjacent storm drain	Overflow has been stopped	267544
28	8/19/2015	1704 Rogers Ave	21209	Rags, Pipe Break	DWO	N/A	Not Witnessed	Gray water and evidence can be seen around the manhole.	Evidence of Overflow	Used vac con to clean manhole and relieve choke	CCTV	267573
29	8/21/2015	821 Winans Way	21229	Roots	DWO	N/A	Not Witnessed	Gray water and signs of an overflow around the clean out	Evidence of Overflow	Relieved house connection choke with 60' of electric machine	CCTV	267947
30	8/21/2015	2924 Mallview Rd	21230	Unknown	WVO	N/A	Not Witnessed	Gray water and debris showing around the house connection	Evidence of Overflow	Relieved house connection choke with 3' of electric machine	CCTV	267888
31	8/21/2015	3209 N Charles St	21218	Pipe Break	DWO	N/A	3,217	Rear house connection choke clean out is overflowing	3,217	Ran 18' of electric machine cable, could not relieve choke. Initiated bypass pumping.	CCTV	267915

SSO Notification List

August 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
32	8/21/2015	3526 Old Frederick Rd	21229	Rags, Roots	DWO	N/A	Not Witnessed	Waste and paper around clean out	Evidence of Overflow	Used 45' of electric machine to relieve house connection choke	CCTV	268023
33	8/22/2015	Cloverhill Rd & W Highfield Rd	21218	Grease	DWO	N/A	139	Gray Water and debris flowing from the manhole	278	Relieved mainline choke with 450' of pressure machine hose	CCTV	268058
34	8/23/2015	2809 Boston St	21224	Grease	DWO	Inner Harbor	60	Grease and gray water coming from the house connection	300	Partially relieved house connection choke, overflow was stopped	CCTV	268125
35	8/25/2015	2806 Roselawn Ave	21214	Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence of overflow present around the house connection	Evidence of Overflow	45' of electric machine relieved house connection choke	CCTV	268380
36	8/25/2015	4210 N Charles St	21218	Pipe Break	WWO	Jones Falls	351	Overflow is coming from section of previously repaired pipe.	5,265	Overflow has been stopped, temporary fix in place	CCTV	268354
37	8/26/2015	1628 Sexton St	21230	Rags, Roots	WWO	N/A	Not Witnessed	Wet paper around clean out	Evidence of Overflow	Used 105' of electric machine to relieve house connection choke	CCTV	268591
38	8/27/2015	1044 Leadenhall St	21230	Rags, Roots, Grease	DWO	Inner Harbor	107	Heavy gray water overflowing into storm drain	1,070	Relieved mainline choke with 500 ft of pressure truck on 8" line	CCTV	268769
39	8/27/2015	E McComas & Key Hwy	21230	Grease	WWO	N/A	98	Heavy gray water coming out of the manhole	980	Relieved mainline choke with 500 ft of pressure truck on 8"	CCTV	208406
40	8/28/2015	3500 Cottage Ave	21215	Rags, Grease	DWO	N/A	133	Heavy gray water flowing out of manhole	1,995	Relieved mainline choke with 400ft of pressure truck on 8"	CCTV	268914
41	8/28/2015	4210 N Charles St	21218	Pipe Break	DWO	N/A	113	Heavy gray water coming from broken main	1,695	Leak has been stopped, construction will make repairs	CCTV	268354
42	8/30/2015	3101 Pulaski Hwy	21224	Unknown	DWO	N/A	89	Toilet Paper and Debris coming from illegal hookup	89	Pressure Truck Flushed 8" Mainline with 189 ft of hose	Illegal Hook Up	269098
43	8/31/2015	2029 Beechwood Ave	21207	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	267	Grease and debris running from the manhole in rear of building	1,068	Pressure Truck Flush Mainline 450', removed rags, grease, and debris	CCTV	269133
				# WWO	12			TOTAL	56,623	EVIDENCE ONLY	19	