

SSO Notification List

February 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/2/2016	3400 Reisterstown Rd	21215	Rags, Grease	WVO	N/A	Not Witnessed	Found evidence of an overflow running from manhole into grass area	Evidence of Overflow	Relieved mainline choke with 180 ft of pressure machine hose	CCTV	290076
2	2/2/2016	3637 Greenmount Ave	21218	Roots	WVO	N/A	37	Sewer water	185	Relieved house connection choke with 30 ft of electric machine	CCTV	290123
3	2/3/2016	1822 W Lexington St	21223	Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with 13 ft of electric machine on 6" line	CCTV	290311
4	2/3/2016	3221 Presstman St	21216	Pipe Break	WVO	N/A	176	Sewer water overflowing	880	Ran 41 ft of electric machine to relieve house connection choke	Turned over to construction for repairs	290090
5	2/4/2016	739 Springfield Ave	21212	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Found evidence of overflow from cleanout, front house connection choke	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	290462
6	2/4/2016	1700 N Charles St	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Mainline overcharged due to wet weather event	No CCTV, will monitor location	290426
7	2/4/2016	4600 Parkton St	21229	Rags, Trash, Sand, Gravel, Rocks	WVO	Maidens Choice Creek	Not Witnessed	Grey debris and toilet paper around dislodged manhole rim and cover	Evidence of Overflow	Evidence of a overflow around manhole removed debris from manhole	CCTV	290485
8	2/5/2016	1227 N Bentalou St	21216	Rags, Roots	WVO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	290540
9	2/5/2016	S Highland Ave and Claremont St	21224	Grease	WVO	N/A	264	Gray water	1,320	Relieved mainline choke with 200 ft of pressure truck	CCTV	290623
10	2/6/2016	320 E 33rd St	21218	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Paper and evidence around the clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	290697
11	2/6/2016	3626 Greenmount Ave	21218	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Relieved house connection with 30 ft of electric machine	CCTV	290707
12	2/7/2016	827 Martin Luther King Blvd	21201	Grease	WVO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 8 ft of electric machine	CCTV	290760
13	2/8/2016	4501 Penhurst Ave	21215	Rags, Roots	WVO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	290928
14	2/9/2016	5913 Eurith Ave	21206	Rags	WVO	N/A	Not Witnessed	Raw sewage and paper	Evidence of Overflow	Ran 45 ft of electric machine to relieve house connection choke	CCTV	291056
15	2/10/2016	1815 Bolton St	21217	Rags, Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	291096
16	2/10/2016	2805 Bookert Dr	21225	Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	151	Sewer water and toilet paper overflowing	302	Relieved house connection choke with 30 ft of electric machine	CCTV	291125

SSO Notification List

February 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	2/10/2016	2805 Forest View Ave	21214	Pipe Break	WWO	Herring Run	27,420	Sewage slowly leaking into herring run from cracks in sewage pipe	2,742	Manhole and drop connection installed by on-call contractors	New manhole and drop connection installed to prevent any further leaking	
18	2/11/2016	3026 E Fayette St	21224	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Cleaned line with 55 ft of electric machine	CCTV	291321
19	2/11/2016	5400 Loch Raven Blvd	21239	Rags, Roots	WWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	291446
20	2/11/2016	Hillsdale Rd and Liberty Heights Ave	21207	Rags, Grease	WWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 90 ft of electric machine on 6"	CCTV	291453
21	2/12/2016	1400 Lowman St	21230	Other	DWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	Turned over for main to property, bypass pumping initiated at location	CCTV	291603
22	2/12/2016	2760 Wilkens Ave	21223	Trash, Sand, Gravel, Rocks, Pipe Break	DWO	Gwynns Falls	399	Grey water flowing from and pooling around manhole	1,995	Relieved mainline choke with 250 ft of pressure truck on 8" line	CCTV	291534
23	2/16/2016	1800 Falls Rd	21201	Rags, Rain, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	55	Heavy gray water	1,375	Overcharging mainline caused manhole to overflow from rain event	No CCTV	291864
24	2/16/2016	1900 S Charles St	21230	Rags, Grease	WWO	N/A	196	Heavy gray water	1,960	Relieved mainline choke with 325 ft of pressure truck on 10" line	CCTV	291795
25	2/16/2016	2835 E Federal St	21213	Rags, Trash, Sand, Gravel, Rocks	WWO	Herring Run	46	Cloudy water	230	Relieved mainline choke with 100' of pressure machine hose	CCTV	291836
26	2/17/2016	515 E 38th St	21218	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper	Evidence of Overflow	Relieved house connection with 30' of electric machine	CCTV	292089
27	2/17/2016	532 Random Rd	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	292031
28	2/17/2016	1438 Cedarcroft Rd	21239	Rags, Roots	WWO	N/A	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with 30' of electric machine cable	CCTV	291972
29	2/18/2016	247 N Bruce St	21223	Rags, Grease	DWO	N/A	Not Witnessed	Evidence of overflow SSO report needed rear house connection	Evidence of Overflow	Relieved house connection choke with 45 ft electric machine on 6" line	CCTV	292244
30	2/18/2016	1315 Bayard St	21230	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	292222
31	2/19/2016	612 Wyndhurst Ave	21210	Rags, Roots	DWO	N/A	50	Sewer water and toilet paper	250	Relieved house connection choke with 45' of electric machine	CCTV	292390

SSO Notification List

February 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
32	2/19/2016	709 Linnard St	21229	Rags, Roots	DWO	N/A	Not Witnessed	Gray water around house connection	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	292384
33	2/19/2016	2435 Foster Ave	21224	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	292421
34	2/20/2016	15 W North Ave	21202	Rags, Grease	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	292445
35	2/20/2016	2313 Hamilton Ave	21214	Rags	DWO	N/A	Not Witnessed	Heavy gray water around house connection	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	292435
36	2/20/2016	4524 Keswick Rd	21210	Rags, Roots	DWO	N/A	Not Witnessed	Toilet paper	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	292443
37	2/21/2016	1714 Barclay St	21202	Rags	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 8" line	CCTV	292503
38	2/22/2016	737 McCabe Ave	21212	Roots, Grease, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Cleaned line with 200 ft of electric machine	CCTV	292714
39	2/22/2016	905 Nottingham Rd	21229	Rags, Roots, Grease	WVO	N/A	1,207	Gray water and debris	6,035	Relieved mainline choke with 300 ft of pressure machine hose	CCTV	292836
40	2/22/2016	3603 Windsor Mill Rd	21216	Rags, Roots	WVO	N/A	Not Witnessed	Gray water and debris	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	292793
41	2/24/2016	234 N Milton Ave	21224	Rags	WVO	N/A	221	Gray water	1,105	Relieved house connection choke with 30 ft of electric machine	CCTV	293201
42	2/24/2016	301 Edgevale Rd	21210	Roots	WVO	N/A	62	Gray water	310	Relieved mainline choke using 300 ft of pressure hose	CCTV	293183
43	2/24/2016	600 S Hanover St	21230	Rags, Roots	WVO	N/A	Not Witnessed	Evidence of overflow. Side house connection choke	Evidence of Overflow	Relieved house connection choke with 75 ft of electric machine on 6" line	CCTV	293048
44	2/24/2016	1211 W Northern Pkwy	21210	Roots	WVO	N/A	10	Gray water flowing from house connection	50	Relieved house connection choke with 45 ft of electric machine	CCTV	293207
45	2/24/2016	4409 St. Georges Ave	21212	Rags	WVO	N/A	20	Sewer water and toilet paper	60	Drain cleaning machine relieved the house connection choke	CCTV'd lateral.	293145
46	2/24/2016	1731 E Chase St	21213	Rain	WVO	Inner Harbor	326	Sewer water overflowing	114,100	Take picture of overflowing manhole	Waiting for surcharging line to go down	
47	2/24/2016	1000 N Durham St	21205	Rain	WVO	Jones Falls	241	Sewer water	36,150	Located overflowing manhole	Waited for surcharging line to go down	
48	2/24/2016	Armstead Way and Homers Ln	21205	Rain	WVO	N/A	Not Witnessed	Paper and debris around siphon hatch	Evidence of Overflow	Waited for storm to stop	CCTV	293526

SSO Notification List

February 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
49	2/25/2016	3616 Roland Ave	21211	Roots, Grease	DWO	N/A	Not Witnessed	Evidence of SSO. Toilet paper and debris	Evidence of Overflow	Cleaned line with 35 feet of electric machine	CCTV	293367
50	2/27/2016	S Warwick Ave and Frederick Ave	21223	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	423	Gray water overflowing	846	Relieved mainline choke with 100 ft of pressure machine hose	CCTV	293588
51	2/27/2016	1319 W Lombard St	21223	Grease	DWO	N/A	Not Witnessed	Paper and evidence around the clean out	Evidence of Overflow	Relieved house connection choke with pressure truck	CCTV	293582
52	2/29/2016	247 N Bruce St	21223	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	293762
53	2/29/2016	4801 Lorelly Ave	21206	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	Herring Run	40	Active overflow from cleanout	120	Cleaned line with 60 ft of electric machine	CCTV	293777
				# WWO	37			TOTAL	170,015	EVIDENCE ONLY	34	