

SSO Notification List

February 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/1/2018	1500 N Franklinton Rd	21229	Rags, Roots, Grease	Dry	N/A	150	Heavy gray water escaping manhole.	750	Relieved 8" mainline choke with 10 ft of pressure hose.	Performed mainline CCTV inspection.	519110
2	2/1/2018	1214 Seminole Ave	21229	Rags, Roots, Grease	Dry	N/A	304	Heavy gray water escaping manhole.	608	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	519070
3	2/1/2018	2700 Gwynns Falls Pkwy	21216	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	126	Gray water overflowing from sanitary manhole in the rear of property.	126	Flushed and cleaned 4" mainline with 100 ft of pressure hose.	Performed CCTV inspection.	519167
4	2/4/2018	1901 Falls Rd - SSO #67	21211	Rain	Wet	Jones Falls	130	Structure discharges to a storm drain pipe and is monitored by metering equipment in the manhole; not visually observed.	161,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project	
5	2/4/2018	428 E Preston St - SSO #72	21202	Rain	Wet	Jones Falls	265	Structure discharges to a storm drain pipe and is monitored by metering equipment in the manhole; not visually observed.	2,311,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
6	2/6/2018	2500 Liberty Heights Ave	21215	Rags	Wet	N/A	0	Gray water observed around the cleanout and parking lot of the property.	15	Ran 60 ft of electric cable, unable to pass through 6" line. On-site plumber finished relieving choke.	Performed house lateral CCTV inspection.	520076
7	2/6/2018	4711 York Rd	21212	Grease, Trash	Wet	Jones Falls	78	Sanitary sewer overflowing from manhole into adjacent storm drain pipe, found during routine sampling.	156	Relieved mainline choke	Performed CCTV inspection.	520308
8	2/6/2018	4501 N Charles St	21212	Rags, Grease, Trash	Wet	Jones Falls	84	Colored water flowing from manhole in the street.	840	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	520287
9	2/6/2018	1222 Seminole Rd	21229	Rags, Roots, Rain	Wet	Gwynns Falls	412	Subsurface overflow discovered during routine sampling.	824	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	520348
10	2/6/2018	200 Font Hill Ave	21223	Structural	Wet	N/A	0	Leaking occurring from 18" pipe; confirmed via dye test.	0	Contractor is determining course of action for repair.	Exploring the possibility of pipe lining.	
11	2/6/2018	4202 Groveland Ave	21215	Rags, Grease, Trash	Wet	N/A	0	Heavy gray water.	5	Relieved 8" mainline choke with 375 ft of pressure hose.	Confirmed mainline is clear.	520081
12	2/7/2018	Wetheredsville Rd & Windsor Mill Rd	21207	Rags, Roots, Trash	Wet	N/A	59	Heavy gray water escaping the manhole in the street.	590	Relieved 10" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	520481
13	2/8/2018	4000 Linkwood Rd	21210	Rags, Roots, Trash	Wet	N/A	88	Choked sanitary mainline overflowing into adjacent storm sewer; found during routine monitoring.	44	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	520867
14	2/8/2018	460 Roundview Rd	21225	Grease, Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Ran 14 ft of electric cable to remove grease & gravel. Unable to continue on customer side.	Referred for further investigation of mainline due to repeated issues, and alerted health department.	520851
15	2/9/2018	4100 Ethland Ave	21207	Rags, Roots, Trash	Wet	Gwynns Falls	61	Manhole surcharging into nearby storm drain system; found during routine sampling.	305	Relieved 8" mainline choke with 400 ft of pressure hose.	Performed mainline CCTV inspection.	521136
16	2/11/2018	414 Drury Ln	21229	Rags, Roots, Grease	Wet	N/A	0	Gray water observed in the area.	10	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	521383
17	2/11/2018	1901 Falls Rd - SSO #67	21211	Rain	Wet	Jones Falls	300	Structure monitored by metering equipment in the pipe.	955,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
18	2/11/2018	428 E Preston St - SSO #72	21202	Rain	Wet	Jones Falls	525	Structure monitored by metering equipment in the pipe; not visually observed.	4,757,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
19	2/11/2018	Western Run Dr & Bonnie View Dr	21209	Rain	Wet	N/A	121	Heavy water flowing from elevated manhole.	36,300	Replaced manhole cover.	Contractor to CCTV mainline.	521503

SSO Notification List

February 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	2/12/2018	319 E 22nd St	21218	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	521610
21	2/12/2018	2904 Montebello Ter	21214	Rags, Grease	Wet	N/A	0	Gray water and paper observed around cleanout.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	521657
22	2/13/2018	136 S Loudon Ave	21229	Rags, Structural	Wet	N/A	0	Heavy gray water observed around the cleanout.	3	Relieved house connection choke.	This lateral is already scheduled for a repair.	512164
23	2/13/2018	3903 8th St	21225	Rags, Roots, Structural	Wet	N/A	355	Mainline choke causing sewage to discharge from cracks in curb.	710	Relieved mainline choke with 25 ft of pressure hose.	Performed CCTV inspection to determine possible structural damage in pipe.	521965
24	2/14/2018	4430 Seidel Ave	21206	Rags, Grease, Trash	Wet	Herring Run	95	Choked mainline overflowing into adjacent storm drain pipe; found during routine sampling.	95	Relieved 8" mainline choke with 375 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	522197
25	2/14/2018	1751 E Pratt St	21231	Roots, Structural	Wet	Harbor	0	Gray water observed on the sidewalk near the cleanout.	10	Ran 13 ft of electric cable through house connection, encountered structural damage, scheduled repair.	Set up bypass pumping while connection is being repaired.	522192
26	2/14/2018	Fair Oaks Ave & E Northern Pkwy	21214	Rags, Roots, Grease	Wet	Harbor	30	Gray water escaping the manhole.	150	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	522061
27	2/14/2018	251 S Morley St	21229	Rags, Roots	Wet	N/A	410	Heavy gray water flowing from cleanout.	1,230	Relieved house connection choke; flushed and cleaned 8" mainline.	Performed CCTV inspection.	522208
28	2/14/2018	200 Font Hill Ave	21223	Structural	Wet	Gwynns Falls	1,668	Joint leaking in sanitary pipe that is currently set up with bypass pumping.	3,336	Contractor replaced leaking joint.	Pipe is being bypassed and will be fixed in the future.	
29	2/14/2018	4708 Vancouver Rd	21229	Rags, Roots	Wet	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	522243
30	2/14/2018	107 E 25th St	21218	Rags	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Unable to relieve house connection choke using both electric cable and pressure hose.	Performed CCTV inspection to investigate blockage.	522245
31	2/15/2018	2909 Fait Ave	21224	Rags, Grease, Trash	Dry	Harbor	0	Water and debris observed around the cleanout at the rear of the property.	9	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	522277
32	2/15/2018	5010 Queensbury Ave	21215	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	522295
33	2/15/2018	3028 Mosher St	21216	Rags, Grease, Trash	Dry	N/A	1,377	Heavy gray water escaping manhole.	2,754	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	522804
34	2/15/2018	5807 Royal Oak Ave	21207	Rags, Roots, Trash	Dry	N/A	70	Gray water escaping the manhole in the street.	140	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	522935
35	2/16/2018	809 N Caroline St	21205	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	10	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	522951
36	2/16/2018	2024 N Calvert St	21218	Rags, Trash	Wet	N/A	0	Water and debris observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	522956
37	2/16/2018	616 Wyndhurst Ave	21210	Rags, Roots	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	6	Relieved 6" house connection choke with 5 ft of electric cable.	Performed CCTV inspection; left notice for plumber to check consumer side.	523094
38	2/16/2018	2535 Brookfield Ave	21217	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection.	523239
39	2/16/2018	1412 N Luzerne Ave	21213	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection.	523013
40	2/17/2018	5509 Anthony Ave	21205	Roots	Wet	N/A	0	Water observed around the cleanout.	10	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	523322

SSO Notification List

February 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
41	2/18/2018	2745 Rayner Ave	21216	Rags, Roots	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	523406
42	2/20/2018	1939 Ramsey St	21223	Rags, Roots	Wet	N/A	0	Heavy gray water observed.	3	Left notice for a plumber to install a cleanout at a proper location.	N/A	524970
43	2/20/2018	2639 Hampden Ave	21211	Rags, Trash, Sand, Gravel, Rocks	Wet	N/A	0	White liquid observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 13 ft of electric cable.	Performed house lateral CCTV inspection; will investigate further due to mud in connection.	525080
44	2/21/2018	3132 Guilford Ave	21218	Rags, Trash	Dry	N/A	0	Gray water and debris observed in the area.	55	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; left notice for consumer to install cap on cleanout.	525214
45	2/21/2018	1823 McCulloh St	21217	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	5	Relieved house connection choke with electric cable.	Performed CCTV inspection; referred for further investigation for possible pipe damage.	525313
46	2/22/2018	421 E 22nd St	21218	Rags, Trash	Dry	N/A	0	Water and debris observed around the cleanout.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	525864
47	2/22/2018	5615 York Rd	21212	Rags, Grease	Dry	N/A	636	Water and debris flowing from cleanout.	3,180	Relieved house connection choke with 45 ft of electric cable, auger, and expander.	Performed CCTV inspection.	525876
48	2/23/2018	5102 Anthony Ave	21206	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	526152
49	2/24/2018	613 N Carey St	21217	Rags, Roots	Wet	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	11	Relieved 6" house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	526199
50	2/26/2018	1823 Eutaw Pl	21217	Rags, Trash	Wet	N/A	165	Water flowing from cleanout at the rear of the property.	330	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	526633
51	2/27/2018	601 S Beechfield Ave	21229	Trash	Wet	N/A	0	Water observed around the cleanout at the rear of the property.	5	Relieved house connection choke.	Confirmed connection is clear.	526710
52	2/27/2018	Hurley Ave & Wilkens Ave	21223	Rags, Trash	Wet	Gwynns Falls	0	Sanitary discharge observed around a manhole in park.	30	Cleaned the affected area.	Performed mainline CCTV inspection to determine cause.	526752
53	2/27/2018	1627 Ceddox St	21226	Rags, Grease, Trash	Wet	N/A	695	Gray water escaping a crack in the rear alleyway.	1,043	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed mainline CCTV inspection to determine possible structural damage.	526919
54	2/27/2018	351 Gwynn Ave	21229	Rags, Roots, Trash	Wet	N/A	0	Water observed around the cleanout in the front of the property.	7	Relieved house connection choke with 60 ft of electric cable.	Confirmed connection and mainline are clear.	526937
55	2/27/2018	229 N Calhoun St	21223	Rags, Trash	Wet	N/A	0	Water and debris observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Confirmed connection is clear.	526941
56	2/28/2018	515 E 38th St	21218	Roots, Trash	Wet	N/A	176	Gray water and debris escaping the cleanout at the rear of the property.	176	Relieved house connection choke with 30 ft of electric cable and auger.	Confirmed lateral and mainline are clear.	526976
57	2/28/2018	2574 W Lafayette Ave	21216	Rags, Grease, Trash	Wet	N/A	144	Gray water escaping manhole.	288	Relieved mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	527196
				# WWO	46			TOTAL	8,238,233	UNDER 100 GALLONS	33	