

## SSO Notification List

January 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2016	3128 Weaver Ave	21214	Rags, Roots, Grease	WVO	Argonne Run	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6"	CCTV	286324
2	1/1/2016	28 E Preston St	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	N/A	30	Sewer running from manhole	150	Relieved mainline choke with 300 ft of pressure truck on 8" line	CCTV	286328
3	1/2/2016	700 W North Ave	21217	Rags, Grease	DWO	Jones Falls	37	Sewage and debris flowing from the manhole cover	370	Jetted line with pressure truck, relieved mainline choke	Turned over for CCTV	286380
4	1/2/2016	803 Powers St	21211	Rags, Grease	DWO	N/A	Not Witnessed	Toilet paper around cleanout	Evidence of Overflow	Cleaned line with 45 ft of electric machine, relieved choke	CCTV	286377
5	1/4/2016	1901 Eagle Dr	21207	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	1,572	Heavy gray water	7,860	Relieved mainline choke with press truck 150 ft of 8"	CCTV	286516
6	1/4/2016	3004 Frisby St	21218	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	65	Gray water	325	Relieved house connection choke with 15 ft of electric machine	CCTV	286585
7	1/6/2016	603 S Glover St	21224	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Found evidence of an overflow from cleanout in the rear. House connection choke	Evidence of Overflow	Cleaned line with 30ft of electric machine, relieved house connection choke	CCTV	286790
8	1/6/2016	1901 Eagle Dr	21207	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	Dead Run	1,655	Sewage discharging from hole in ground	8,275	Overflow has been contained, sewage is no longer escaping the system	CCTV	287011
9	1/6/2016	4213 Audrey Ave	21225	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	Ran 45' of electric machine to relieve house connection choke	CCTV	286897
10	1/7/2016	3912 Walnut Ave	21206	Rags, Roots, Grease	DWO	Biddison Run	695	Paper and debris	1,390	Jetted line with vactor truck to relieve choke	Line to be CCTV	287100
11	1/7/2016	4102 Maine Ave	21207	Pipe Break	DWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Referred to health department	Locate or install proper clean out	286996
12	1/8/2016	428 E Preston St	21202	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Gray Water	Evidence of Overflow	Relieved choke with 65 ft of pressure truck	CCTV	287051
13	1/12/2016	4009 Walnut Ave	21206	Trash, Sand, Gravel, Rocks	WVO	N/A	177	Rags and grease	885	Relieved mainline choke with 200 ft of pressure truck	CCTV	287705
14	1/12/2016	6006 Hillen Rd	21218	Roots	DWO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Relieved mainline choke with 200 ft of pressure truck	CCTV	287698
15	1/13/2016	3430 Park Heights Ave	21215	Grease	DWO	N/A	265	Gray water	265	Pressure Truck Flushed and relieved mainline choke, used 300ft of pressure hose	CCTV	287845
16	1/14/2016	Greenmount Ave and Exeter Ave	21218	Rags, Grease	DWO	N/A	Not Witnessed	Rags and grease	Evidence of Overflow	Ran 30 ft of electric machine to relieve house connection choke	CCTV	288190

## SSO Notification List

January 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	1/15/2016	5306 McCulloh St	21217	Pipe Break	WWO	N/A	Not Witnessed	Grease and Debris	Evidence of Overflow	Ran 5 ft of electric machine to relieve house connection choke	Left plumbers notice at address, broke down inside property Line	288320
18	1/17/2016	3107 Artaban Pl	21216	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper	Evidence of Overflow	Relieved mainline choke with pressure truck	CCTV	228420
19	1/19/2016	737 McCabe Ave	21212	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Clear water around clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	228638
20	1/19/2016	2733 Rayner Ave	21216	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water and sewage	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	288684
21	1/20/2016	1811 N Broadway	21213	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Relieved house connection choke with pressure truck	CCTV	288819
22	1/20/2016	2311 Cross Country Blvd	21209	Pipe Break	DWO	Western Run	1,860	Subsurface sewage leak from manhole into adjacent storm inlet pipe	1,860	Construction arrived on scene and stopped the sewage leak by repairing damaged joint	CCTV	288856
23	1/20/2016	3100 Artaban Pl	21216	Rags, Grease	DWO	Gwynns Falls	75	Wastewater flowing from the street under ice and from apartment building. Water entering nearby storm inlet	150	Relieved mainline choke with 175 ft of pressure truck on 8" line	CCTV	288806
24	1/20/2016	5801 Greenspring Ave	21209	Pipe Break	DWO	Western Run	1,860	Subsurface sewage leak from manhole and pipe into adjacent storm inlet pipe	2,101	Construction repaired 6 ft of broken pipe, stopped sewage leaking into storm inlet	CCTV	288855
25	1/21/2016	618 Venable Ave	21218	Rags, Roots	DWO	N/A	Not Witnessed	Heavy gray debris	Evidence of Overflow	Flush mainline using 300 ft of pressure hose	CCTV	288972
26	1/21/2016	1239 Glenwood Ave	21239	Rags, Grease	DWO	Chinquapin Run	93	Sewage leaking into storm drain from choked sanitary pipe	47	Jetted line with pressure truck	CCTV ASAP	289085
27	1/21/2016	3501 Taylor Ave	21239	Rags, Roots	DWO	Biddison Run	99	Grey colored water murky	990	Jetted line with a vector truck, relieved mainline choke	CCTV	289058
28	1/22/2016	1300 Parkman Ave	21230	Rags	WWO	N/A	Not Witnessed	Sewer water	Evidence of Overflow	Relieved house connection choke with 45 ft of electric	CCTV	286305
29	1/27/2016	Roland Heights Ave and Laplata Ave	21211	Rags, Grease	DWO	Jones Falls	134	Cloudy water	1,340	Relieved mainline choke with 175 ft of pressure truck on 8" line	CCTV	289398
30	1/28/2016	2953 Greenmount Ave	21218	Roots	WWO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Relieved house connection choke with 17 ft of electric machine	CCTV	289602
31	1/28/2016	3525 Gelston Dr	21229	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	326	Raw sewage flowing from the manhole onto sidewalk	652	Pressure truck relieved mainline choke with 200 ft of pressure hose	CCTV	289581
32	1/29/2016	2807 Elgin Ave	21216	Rags, Grease	WWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 175 ft of pressure truck on 6" line	CCTV	289630

## SSO Notification List

January 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
				# WWO								
					12							
								TOTAL	26,660	EVIDENCE ONLY	17	