

SSO Notification List

January 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2019	2543 Marbourne Ave	21230	Roots, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	653687
2	1/2/2019	436 Kane St	21224	Trash	Wet	N/A	0	Gray water observed around the manhole.	5	Flushed mainline with 300 ft of pressure hose.	Performed mainline CCTV inspection.	655045
3	1/3/2019	700 Chesapeake Ave	21225	Rags, Grease, Trash	Wet	N/A	115	Heavy gray water escaping the manhole.	1,150	Relieved mainline choke with 125 ft of pressure hose.	Performed CCTV inspection.	655126
4	1/3/2019	1901 Chesapeake Ave	21226	Rags, Trash	Wet	N/A	0	Water observed around the cleanout.	10	Relieved house connection choke with 60 ft of electric cable.	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	655628
5	1/5/2019	1603 N Broadway	21213	Rags, Roots, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	10	Relieved 6" house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	657310
6	1/5/2019	3917 Carlisle Ave	21216	Rags, Roots, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	657401
7	1/5/2019	421 S Wickham Rd	21229	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	657403
8	1/7/2019	4006 Raymonn Ave	21213	Rags, Roots, Grease, Trash	Dry	N/A	0	Water and debris observed around the cleanout.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	657888
9	1/8/2019	3130 Foster Ave	21224	Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	3	Relieved house connection choke with 15 ft of electric cable.	Cleaned the mainline.	658328
10	1/8/2019	436 Kane St	21224	Rags	Dry	N/A	0	Gray water observed around the manhole.	10	Relieved mainline choke with pressure hose.	Performed mainline CCTV inspection.	
11	1/9/2019	3305 Taney Rd	21215	Rags, Grease	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	658658
12	1/9/2019	1904 N Pulaski St	21217	Rags	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	658704
13	1/9/2019	1525 Edmondson Ave	21223	Rags, Roots	Wet	N/A	103	Heavy gray water escaping the cleanout at the rear of the property.	206	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	658740
14	1/9/2019	2105 Louise Ave	21214	Roots, Trash	Wet	N/A	0	Water and debris observed around the cleanout at the front of the property.	4	Relieved house connection choke with 40 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	659020
15	1/10/2019	808 N Hilton St	21229	Rags, Grease, Trash	Wet	Gwynns Falls	158	Gray water escaping the manhole in the street.	316	Relieved 10" mainline choke with 150 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	659099
16	1/10/2019	2702 E Strathmore Ave	21214	Rags, Trash	Wet	N/A	48	Gray water escaping the cleanout.	480	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	659276
17	1/14/2019	1007 N Iris Ave	21205	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	5	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	661244
18	1/15/2019	304 S Augusta Ave	21229	Rags, Roots, Infiltration	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	661506
19	1/15/2019	428 E Preston St	21202	Rags, Roots, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	10	Relieved house connection choke with pressure hose and electric cable.	Performed CCTV inspection; confirmed line is clear.	661737
20	1/16/2019	W Lexington St & N Warwick Ave	21223	Structural	Wet	Gwynns Falls	298	Subsurface overflow entering storm drain. Found during routine sampling.	596	Set up bypass pumping to abate the overflow while point repair was done.	Performed dye test and confirmed the problem has been fixed.	662043

SSO Notification List

January 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	1/18/2019	922 W North Ave	21217	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	10	Flushed and cleaned 8" mainline with 200 ft of pressure hose.	Performed CCTV inspection.	662764
22	1/19/2019	519 Brisbane Rd	21229	Rags, Roots, Grease	Dry	N/A	0	Colored water observed around the cleanout at the front of the property.	33	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	662925
23	1/20/2019	3100 Chestnut Ave	21211	Sand, Gravel, Rocks, Structural	Wet	N/A	222	Gray water escaping mainline near manhole.	666	Abated overflow with pressure hose; investigating further for possible damage to pipe.	Performed mainline CCTV inspection.	662999
24	1/20/2019	3404 Glen Ave - SSO Site #155	21215	Rain	Wet	Jones Falls	10	Structure monitored by metered equipment in the pipe. Not visually observed.	500	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
25	1/20/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	175	Structure monitored by metering equipment in the pipe. Not visually observed.	164,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
26	1/21/2019	480 Brunswick St	21223	Rags, Grease, Trash	Wet	N/A	276	Heavy gray water escaping the manhole.	1,380	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	663095
27	1/24/2019	1901 Falls Road - SSO Site #67	21211	Rain	Wet	Jones Falls	330	Structure monitored by metering equipment in the pipe. Not visually observed.	1,477,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
28	1/24/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	320	Structure monitored by metering equipment in the pipe. Not visually observed.	2,784,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
29	1/24/2019	3102 Chestnut Ave	21211	Sand, Gravel, Rocks, Structural	Wet	N/A	1,095	Heavy gray water escaping the manhole.	2,190	Set up bypass pumping to abate the overflow.	Damaged manhole walls will be repaired.	664693
30	1/24/2019	5740 Cross Country Blvd	21209	Rags, Roots, Trash	Wet	N/A	0	Heavy gray water observed around the manhole.	10	Relieved mainline choke with 150 ft of pressure hose.	Confirmed mainline is clear.	664233
31	1/24/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	220	Manhole adjacent to creek overflowed due to heavy rain	1,357,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
32	1/25/2019	3404 Glen Ave - SSO #155	21215	Unknown	Wet	Jones Falls	285	Structure monitored by metered equipment in the pipe. Not visually observed.	27,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
33	1/26/2019	1520 Clipper Rd	21211	Grease, Trash	Wet	N/A	1,380	Gray water escaping the cleanout at the rear of the property.	1,380	Relieved house connection and mainline chokes with 250 ft of pressure hose.	Performed CCTV inspection.	664770
34	1/28/2019	428 E Preston St	21202	Grease, Trash, Structural	Dry	Jones Falls	1,889	Colored water escaping the mainline.	34,002	Specialty cleaning done to remove obstructions; bypass was reinstalled to abate the SSO.	Long-term rerouting of pipe is currently undergoing design.	665057
35	1/29/2019	4300 Hayward Ave (Private)	21215	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole.	10	Relieved mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear.	665644
36	1/30/2019	5618 Frankford Ave	21206	Rags, Roots, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	8	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection.	666566
				# WWO	26			TOTAL	5,852,018	UNDER 100 GALLONS	19	