

SSO Notification List

July 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2015	513 W Cold Spring Ln	21210	Rags, Grease	WWO	N/A	Not Witnessed	Wet around clean out, evidence of an overflow present	Evidence of Overflow	Used 30' of electric machine and H cutter to remove rags and relieve choke	CCTV	261339
2	7/1/2015	2709 Greenmount Ave	21218	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	985	Water flowing from inside garage	2,955	Flushed and relieved sanitary mainline, used 300' of pressure hose	CCTV	261333
3	7/2/2015	4201 Ridgewood Ave	21215	Rags, Roots, Grease	WWO	N/A	151	Mainline choke with sewer coming out of the eyes of the manhole	755	Relieved mainline choke on 8 in line with 250 ft of pressure hose	CCTV	261429
4	7/3/2015	5656 The Alameda	21239	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Some rags and evidence visible around the clean out	Evidence of Overflow	Cleaned line with electric machine and H-Cutter	CCTV	261514
5	7/5/2013	3447 Spelman Rd	21225	Rags, Roots	WWO	N/A	71	Heavy gray water, manhole is overflowing	1,420	Relieved mainline choke on 8 in pipe with 100 ft of pressure hose	CCTV	261604
6	7/6/2013	1110 Cook Ln	21229	Rags, Roots	WWO	Gwynns Falls	180	Water and sewage coming from manhole	360	Used 200 ft of sewer jet to relieve mainline choke	CCTV	261771
7	7/6/2013	4217 Audrey Ave	21225	Rags, Roots	WWO	N/A	Not Witnessed	Front house connection choke with sewer water and toilet paper present around the clean out	Evidence of Overflow	Relieved front house connection choke with 60' of electric machine	CCTV	261649
8	7/6/2013	5807 Royal Oak Ave	21207	Rags, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	100	Water with sewage smell coming from the curb	500	Pressure Truck Flushed and relieved mainline choke, used 250' of pressure hose	CCTV	261673
9	7/7/2015	4000 Edmondson Ave	21229	Infiltration/Inflow, Pipe Break	WWO	Gwynns Falls	1,241	Heavy flow of sewage into adjacent storm drain	62,050	Pressure truck relieved mainline choke with 3' of pressure machine hose	CCTV	261893
10	7/8/2015	3803 Juniper Rd	21218	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	95	Heavy sewage flowing into storm drain verified with red dye	4,750	Jetted line with vector truck	Line to be tved	262017
11	7/8/2015	4300 Hayward St	21215	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Signs of an overflow around the manhole	Evidence of Overflow	Relieved mainline choke with 200 ft of pressure truck on 8" line	CCTV	262109
12	7/9/2015	568 W Preston St	21201	Rags, Grease	DWO	Jones Falls	180	Water and sewage coming from manhole	540	Used 200 ft of sewer jet to relieve mainline choke	CCTV	262251
13	7/9/2015	4002 Kathland Ave	21207	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water, toilet paper and debris visible	Evidence of Overflow	Relieved choke with 465' of Pressure machine hose	CCTV	262145
14	7/9/2015	6830 Overall Ave	21236	Rags, Trash, Sand, Gravel, Rocks	DWO	Biddison Run	1,605	Gray colored water overflowing and running into the stream	8,025	Jetted line with vector truck and used H cutter to remove roots	Line to be tved	262249
15	7/9/2015	Edmondson Ave and Hilton Pkwy	21229	Rags, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	206	Sewage flowing from sanitary manhole, over ground, into stream. Confirmed by DPW office of compliance contact 443-826-2904	5,150	Relieved mainline choke with 200 ft of pressure truck on 8" pipe	CCTV	262177
16	7/11/2015	2600 Marbourne Ave	21230	Rags	DWO	N/A	Not Witnessed	Gray water and evidence present around the clean out	Evidence of Overflow	Relieved house connection choke on 6" with 45 ft of electric machine	CCTV	262468
17	7/11/2015	2700 Tivoly Ave	21218	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	127	Gray water, sewage and debris overflowing from manhole	635	Relieved mainline choke with 45' of pressure machine hose	CCTV	262441
18	7/13/2015	3010 Presbury St	21216	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Found front house connection choke, evidence of overflow visible around clean out	Evidence of Overflow	Relieved front house connection choke with 45' of electric machine	CCTV	262549
19	7/13/2015	6807 Park Heights Ave	21215	Rags	DWO	N/A	223	Found rear house connection choke, active overflow from clean out.	446	Pressure truck relieved house connection choke with 65' of pressure machine hose	CCTV	262556

SSO Notification List

July 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	7/14/2015	817 Stoll St	21225	Rags, Grease	WWO	N/A	Not Witnessed	Paper and evidence visible around clean out	Evidence of Overflow	Used electric machine to relieve house connection choke, removed rags and grease	CCTV	262782
21	7/14/2015	2311 Ashton St	21233	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	102	Mainline choke causing sewage overflow out of manhole	204	Relieved mainline choke with 175 ft of pressure truck on 8"	CCTV	262709
22	7/14/2015	3455 Wilkens Ave	21229	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	73	Heavy gray water flowing from the manhole	1,095	Relieved mainline choke with 255 ft of pressure truck on 8" pipe	CCTV	262723
23	7/15/2015	4506 Wakefield Rd	21216	Rags, Roots	DWO	N/A	Not Witnessed	Evidence of overflow around small hole in street from a house connection	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6"	CCTV	262901
24	7/15/2015	2707 Jefferson St	21224	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of overflow around the cleanout in the rear of the property	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	Line to be tved asap	262970
25	7/15/2015	6465 Frankford Ave	21206	Rags, Trash, Sand, Gravel, Rocks	DWO	Herring Run	34	Sewage discharging from manhole behind 6465 Frankford Ave at corner closest to Moravia	510	Cleaned line with vactor truck, relieved mainline choke	Line to be tved	262966
26	7/16/2015	3324 Lyndale Ave	21213	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper and signs of overflow present around clean out	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	Line to be tved	263067
27	7/16/2015	3505 Cedardale Rd	21215	Rags, Roots	DWO	N/A	Not Witnessed	Paper and evidence around clean out in the front yard	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	263118
28	7/16/2015	3803 Juniper Rd	21218	Rags, Roots, Grease	DWO	Jones Falls	70	Mainline choke at sanitary located in the front yard of 3803 Juniper Rd and overflowing into the storm drain	3,500	Jetted line with vactor truck, relieved mainline choke	Line to be tved	263040
29	7/21/2015	4217 Audrey Ave	21225	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Rags, Toilet paper and debris visible around the clean out	Evidence of Overflow	Relieve house connection choke with 60' of electric machine	CCTV	263568
30	7/21/2015	3209 N Charles St	21218	Rags, Grease	DWO	N/A	Not Witnessed	Evidence of spillage, wet area around clean out	Evidence of Overflow	Used electric machine to flush house connection, removed rags and debris	CCTV	263630
31	7/21/2015	710 N Monroe St	21217	Rags, Grease	DWO	N/A	Not Witnessed	Mainline choke caused overflow, evidence of spillage present	Evidence of Overflow	Relieved the mainline choke with 275 ft of pressure truck on 8" pipe	CCTV	263621
32	7/21/2015	3500 N Calvert St	21218	Infiltration/Inflow, Pipe Break, Other	DWO	Jones Falls	1,440	Leaving sanitary line at S350C1024C1 and infiltrating adjacent storm water line on the 3500 block of N Calvert St.	1,440	Pipe is scheduled to be repaired by contractor, infiltration will be stopped, ongoing	Pipe will be repaired by contractor	263758
33	7/21/2015	7106 Harford Rd	21234	Other	DWO	Jones Falls	90	Water coming from the sump pump	270	Relieved mainline choke with pressure hose, removed mud and debris	CCTV	2613737
34	7/22/2015	1905 Cedric Ave	21216	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Signs of an overflow around the connection, dye showed up at the curbline.	Evidence of Overflow	Flushed and cleaned 8" sanitary mainline, relieved choke with 200' of pressure hose	CCTV	263803
35	7/23/2015	1729 Moreland Ave	21216	Pipe Break	DWO	N/A	Not Witnessed	Found sewage in rear yard could not locate clean out, referred to complaint truck to locate clean out	Evidence of Overflow	Left plumbers notice to locate or install external clean out.	Referred to housing dept	263914
36	7/24/2015	5615 York Rd	21212	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	378	Paper and sewage around manhole and clean out in front of Wendy's restaurant	756	Jetted line with vactor truck, relieved choke	Relieved choke with 50 ft of pressure truck on 6" line	264057
37	7/25/2015	601 E Pratt St	21202	Rags, Grease	DWO	N/A	205	Heavy gray water coming from manhole in front of Hard Rock Cafe.	1,025	Relieved mainline choke with 275 ft of pressure truck on 8" line	CCTV	264187
38	7/26/2015	2417 Puget St	21230	Rags, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	204	Gray colored water coming from manhole on Puget St	1,020	Jetted line with vactor truck, relieved mainline choke	Line to be CCTVd	264213
39	7/26/2015	3903 Mayberry Ave	21206	Rags, Roots, Grease	DWO	N/A	Not Witnessed	Found evidence of overflow, debris around the clean out	Evidence of Overflow	Cleaned line with electric machine	CCTV	264380
40	7/27/2015	1739 E Preston St	21213	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Found rear house connection choke evidence of overflow	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	Line to be CCTVd	264239

