

## SSO Notification List

JUNE 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2018	6900 Bownel Ave	21237	Rags, Roots, Trash	Wet	N/A	50	Gray water escaping the cleanout at the front of the property.	50	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and cleaned the mainline.	558853
2	6/3/2018	427 Drury Ln	21229	Rags, Roots, Trash	Wet	N/A	240	Water escaping manhole at the front of the property.	4,800	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed mainline CCTV inspection.	559292
3	6/3/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	450	Structure monitored by metering equipment in the pipe.	1,471,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
4	6/3/2018	428 Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	505	Structure monitored by metering equipment in the pipe. Not visually observed.	4,779,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
5	6/3/2018	W Cold Spring Ln & Ayrdale Ave - SSO Site #138	21215	Rain	Wet	Jones Falls	180	Structure monitored by metering equipment in the pipe. Not visually observed.	50,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
6	6/3/2018	W Garrison Ave & Queensberry Rd - SSO Site #139	21215	Rain	Wet	Jones Falls	210	Overflow due to heavy rain.	129,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
7	6/3/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	225	Structure monitored by metering equipment in the pipe. Not visually observed.	26,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
8	6/3/2018	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	35	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	4,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
9	6/3/2018	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	30	Structure monitored by metering equipment in the pipe. Not visually observed.	3,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
10	6/3/2018	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	235	Structure is monitored by metering equipment in the pipe. Not visually observed.	53,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
11	6/3/2018	3404 Glen Ave - SSO Site #155	21215	Rain	Wet	Jones Falls	150	Structure monitored by metering equipment in the pipe. Not visually observed.	35,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	6/3/2018	Western Run Dr & Bonnie View Dr	21209	Rain	Wet	N/A	360	Water flowing out of the top of a stacked manhole.	72,000	Inspected site after rainfall occurred.	The location is susceptible to overflow during heavy rains and is under consideration for metered monitoring.	
13	6/4/2018	4403 Frederick Ave	21229	Rags, Rain, Trash	Wet	N/A	1430	Heavy rain caused surcharged manhole to overflow.	28,600	Procedures are in place to determine obstruction in flow at this location.	Multiple field visits including CCTV inspection performed by contractor.	559415
14	6/4/2018	3908 Maine Ave	21207	Rags, Roots	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	8	Relieved 6" house connection choke with 75 ft of electric cable.	Confirmed mainline and lateral are clear.	559390
15	6/6/2018	4701 Reisterstown Rd	21215	Rags, Grease, Trash	Wet	N/A	85	Overflowing sanitary pipe; found during routine monitoring.	425	Relieved 8" mainline choke with 325 ft of pressure hose.	Performed mainline CCTV inspection; confirmed line is clear.	565717
16	6/9/2018	3012 Gibbons Ave	21214	Rags, Roots	D	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	6	Relieved 6" house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	567567
17	6/10/2018	823 Vine St	21201	Grease, Trash	Wet	N/A	94	Gray water escaping manhole.	282	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	567627
18	6/11/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	130	Structure monitored by metering equipment in pipe.	48,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of capital project.	
19	6/11/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	285	Structure monitored by metering equipment in the pipe. Not visually observed.	849,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
20	6/12/2018	Back River WWTP, 8201 Eastern Ave	21224	Unknown	Dry	N/A	N/A	A capped cleanout line leaked around 3,000 gallons max (estimated). No receiving waters or storm drains were involved.	3,000	Lime was added to the affected area, soaked up, scooped up and cleaned up.	N/A	

## SSO Notification List

JUNE 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	6/13/2018	1901 Chesapeake Ave	21226	Rags, Trash	Wet	N/A	0	Heavy gray water and debris observed around the cleanout.	10	Relieved house connection choke with 35 ft of pressure hose.	Confirmed connection is clear.	568319
22	6/13/2018	5665 Purdue Ave	21239	Rags, Roots	Wet	N/A	0	Gray water observed near the cleanout at the front of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection.	568332
23	6/13/2018	3636 Woodland Ave	21215	Rags	Wet	N/A	58	House connection overflowing into street. Found during routine sampling.	29	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	568395
24	6/14/2018	4600 E Wabash Ave	21215	Infiltration, Structural	Dry	Gwynns Falls	0	House connection leaking into adjacent storm drain pipe. Found during routine sampling.	0	Performed CCTV inspection to determine cause of leak. Flow rate determined by the property's average daily use, with 20% of the lateral flow entering the storm.	Next steps will be determined once cause has been identified.	568588
25	6/14/2018	2805 Bookert Dr	21225	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	568616
26	6/16/2018	701 N Carey St	21217	Rags, Roots	Dry	N/A	0	Gray water observed on the sidewalk near the cleanout.	10	Relieved house connection choke with 45 ft of electric cable.	Confirmed house connection and mainline are clear.	569284
27	6/16/2018	3603 Windsor Mill Rd	21216	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 75 ft of electric cable.	Performed house lateral CCTV inspection; flushed and cleaned 8" mainline.	569301
28	6/16/2018	4103 Springdale Ave	21207	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Confirmed connection and mainline are clear.	569307
29	6/16/2018	406 N Paca St	21201	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around manhole.	6	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	569345
30	6/20/2018	29 N Poppleton St	21201	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around meter on front lawn.	2	Flushed and cleaned 8" mainline with 170 ft of pressure hose.	Performed dye test and CCTV inspection.	570405
31	6/22/2018	447 Brunswick St	21223	Rags, Grease, Trash	Wet	N/A	179	Gray water escaping the manhole in the alley.	537	Relieved mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	573902
32	6/23/2018	6400 O'Donnell St	21224	Rags, Grease, Trash	Wet	N/A	39	Gray water overflowing from manhole.	156	Relieved mainline choke with 125 ft of pressure hose.	Performed CCTV inspection.	574045
33	6/25/2018	729 Dolphin St	21201	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed connection and mainline are clear.	574229
34	6/25/2018	1822 E 29th St	21218	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	574380
35	6/26/2018	2001 W Patapsco Ave	21230	Rags, Grease, Trash	Dry	N/A	500	Gray water escaping the cleanout in the parking lot.	1,000	Relieved house connection choke with 45 ft of electric cable; washed down the area.	Performed house lateral CCTV inspection.	574679
36	6/28/2018	1515 Burnwood Rd	21239	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	575390
				# WWO	24			TOTAL	7,557,957	UNDER 100 GALLONS	16	