

## SSO Notification List

March 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/5/2015	910 Reverdy Rd	21212	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Water and evidence on side walk and in the snow	Evidence of Overflow	Used sewer jet to relieve choke	CCTV	242471
2	3/6/2015	751 W Saratoga St	21201	Roots, Grease	WWO	N/A	1,089	Mainline choke at location, sewage flowing	2,178	Relieved mainline choke with pressure truck, 200 ft of 8"	CCTV	242314
3	3/6/2015	1600 E Lombard St	21231	Rags, Grease	DWO	Inner Harbor	65	Clear colored water	325	Jetted line with pressure truck	Line to be CCTV	243413
4	3/6/2015	3413 Menlo Dr	21215	Rags	WWO	N/A	Not Witnessed	Rags and paper around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	243857
5	3/8/2015	1011 W 37th St	21211	Roots	DWO	N/A	Not Witnessed	Debris and evidence	Evidence of Overflow	Relieved choke with 30' electric machine	CCTV	244174
6	3/8/2015	2276 Druid Park Dr	21209	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper	Evidence of Overflow	Relieved choke with 30ft electric machine	CCTV	244329
7	3/9/2015	2024 Mount Royal Ter	21211	Rags, Roots	DWO	N/A	30	Gray water & debris	30	Relieved with 45' electric machine	CCTV	244492
8	3/10/2015	4507 Wakefield Rd	21216	Rags, Roots, Grease	WWO	N/A	173	Sump pump was discharging sewage	865	Relieved mainline choke with press truck 300 ft of 8"	CCTV	244736
9	3/11/2015	2628 Oswego Ave	21215	Rags	WWO	N/A	Not Witnessed	Choked house connection causing discharge	Evidence of Overflow	Relieved house connection with electric machine, 45 ft of 6"	CCTV	245027
10	3/11/2015	6307 Park Heights Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Toilet paper and other evidence	Evidence of Overflow	Relieved choke with 75' electric machine	CCTV	245039
11	3/11/2015	212 Northway	21218	Rags	WWO	N/A	Not Witnessed	Paper, wet around clean-out and sidewalk	Evidence of Overflow	Used electric machine to relieve choke	CCTV	245100
12	3/11/2015	2728 Laurretta Ave	21223	Rags, Roots	WWO	N/A	90	Gray water & Debris	450	Relieved with 600' pressure hose	CCTV	245106
13	3/12/2015	3229 Powhatan Ave	21216	Rags, Roots	DWO	N/A	Not Witnessed	Evidence of house connection choke	Evidence of Overflow	House connection clean, 30 ft of elec Mach cable	CCTV	245190
14	3/12/2015	5010 Wetheredsville Rd	21207	Rags, Roots, Grease	WWO	N/A	210	Main line choke causing overflow	5,250	Relieved mainline choke with press truck 200 ft of 10"	CCTV	245226
15	3/12/2015	3710 Gibbons Ave	21206	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper and rags around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	245293
16	3/12/2015	5813 Loch Raven Blvd	21239	Rags	WWO	N/A	Not Witnessed	Rags and debris around clean out	Evidence of Overflow	Used electric machine and pressure machine to relieve choke	CCTV	245315
17	3/13/2015	4403 Frederick Ave	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	229	Heavy gray water	5,725	Relieved mainline choke with pressure truck, 400 ft of 8"	CCTV	245457
18	3/13/2015	1622 McCulloh St	21217	Rags, Roots	DWO	N/A	Not Witnessed	Debris around clean out	Evidence of Overflow	Relieved house connection choke with electric Machine, 27.6	CCTV	245498
19	3/13/2015	4629 Reisterstown Rd	21215	Rags	DWO	N/A	Not Witnessed	Rags in pipe	Evidence of Overflow	Used electric machine to relieve choke	CCTV	245554
20	3/14/2015	827 N Brice St	21217	Rags, Grease	WWO	Gwynns Falls	60	Grease and rags	120	Used sewer jet to relieve mainline choke	CCTV	245781
21	3/15/2015	901 Dartmouth Ave	21212	Rags	DWO	N/A	Not Witnessed	Paper & debris around house connection	Evidence of Overflow	Relieved choke with 75' of electric machine cable	CCTV	245945
22	3/16/2015	2501 Maryland Ave	21218	Rags	DWO	N/A	22	Toilet paper & debris around clean out	22	Relieved choke with 30' electric machine	CCTV	246077
23	3/16/2015	2824 Alvarado Sq	21234	Rags	WWO	N/A	Not Witnessed	Rags, wet around cleanout	Evidence of Overflow	Used electric machine to help relieve choke	CCTV	246209

## SSO Notification List

March 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
24	3/17/2015	2043 W North Ave	21217	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	85	Sewage overflowing	170	Relieved mainline choke with pressure truck 20 ft of 6"	CCTV	246339
25	3/17/2015	1845 W North Ave	21217	Rags, Other	DWO	N/A	Not Witnessed	Evidence of spillage and gray water around clean out	Evidence of Overflow	Relieved mainline choke with electric machine, 30 ft of 6"	CCTV	246384
26	3/17/2015	2900 Gibbons Ave	21214	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Wet around manhole	Evidence of Overflow	Used sewer jet to clean mainline and relieve choke	CCTV	246455
27	3/17/2015	900 Brunswick St	21223	Rags, Grease	DWO	Gwynns Falls	240	Heavy gray water flowing	6,000	Relieved mainline choke with pressure truck in manhole	CCTV	246465
28	3/18/2015	508 N Payson St	21223	Roots	DWO	N/A	Not Witnessed	Toilet paper and evidence around clean out	Evidence of Overflow	Ran 30' of electric machine to relieve choke	CCTV	246548
29	3/18/2015	20 S Tremont Rd	21229	Rags	DWO	N/A	Not Witnessed	Spillage around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	246761
30	3/18/2015	2719 W North Ave	21216	Rags, Roots	DWO	N/A	Not Witnessed	Evidence of overflow around the clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	246768
31	3/19/2015	6004 Clover Rd	21215	Rags, Roots	DWO	N/A	Not Witnessed	Gray water and evidence around house connection	Evidence of Overflow	Relieved house connection choke with electric machine, 30 ft 6"	CCTV	246926
32	3/19/2015	301 Edgevale Rd	21210	Rags, Roots	DWO	N/A	Not Witnessed	Gray water and evidence around clean out	Evidence of Overflow	Pressure truck relieved choke, used 100' of pressure machine hose	CCTV	246928
33	3/20/2015	414 Fonthill Ave	21223	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper & debris around clean out	Evidence of Overflow	Ran 45' electric. machine to relieve choke	CCTV	247475
34	3/20/2015	3107 Fairmount Ave	21224	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Relieved choke with electric machine	CCTV	247480
35	3/21/2015	1610 Saint Stephens St	21216	Rags, Roots	WVO	N/A	Not Witnessed	Gray water and evidence around clean out	Evidence of Overflow	Relieved house connection choke with electric Machine, 30 ft of 6"	CCTV	247610
36	3/21/2015	2909 Alvarado Sq	21234	Rags, Roots, Grease	WVO	N/A	Not Witnessed	Debris and evidence around clean out	Evidence of Overflow	Relieved mainline choke with pressure truck 300 ft of 8"	CCTV	247654
37	3/21/2015	3506 Glenmore Ave	21206	Rags, Roots, Grease	WVO	N/A	477	Heavy gray water flowing	2,385	Relieved mainline choke with pressure truck, 300 ft of 8"	CCTV	247658
38	3/22/2015	3478 Spelman Rd	21225	Rags, Roots, Grease	WVO	N/A	Not Witnessed	Found gray water and evidence	Evidence of Overflow	Relieved mainline choke with pressure truck, 250 ft of 15"	CCTV	247662
39	3/23/2015	2703 Round Rd	21225	Rags, Roots, Grease	WVO	N/A	Not Witnessed	Evidence of sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with electric machine, 45 of 6"	CCTV	247861
40	3/23/2015	4000 Groveland Ave	21215	Rags, Roots	WVO	N/A	Not Witnessed	Evidence of spillage, sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with electric machine, 75 ft of 6"	CCTV	247871
41	3/23/2015	538 N Payson St	21223	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Gray water & debris	Evidence of Overflow	Ran 3' of electric machine to relieve choke	CCTV	247884
42	3/23/2015	6002 Harford Rd	21214	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Found evidence of sewer water running from cleanout	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	247893
43	3/24/2015	851 W 36th St	21211	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of a sewer overflow coming from home into the yard of 851 W 36th St	Evidence of Overflow	Left plumbers notice	From 853 left plumbing notice at choke side property	248092
44	3/24/2015	932 Seagull Ave	21225	Rags, Grease	DWO	Curtis Bay	77	Rags and grease causing mainline choke, overflowing	154	Used sewer jet to relieve the mainline choke	CCTV	248181
45	3/24/2015	1909 McElderry St	21205	Rags	DWO	N/A	Not Witnessed	Wet around the clean out, evidence of overflow	Evidence of Overflow	Used electric machine to relieve choke	CCTV	248186
46	3/24/2015	5200 Beaufort Ave	21215	Rags	DWO	N/A	Not Witnessed	Rags and evidence around clean out	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	248202

**SSO Notification List**

**March 2015**

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #	
47	3/25/2015	1617 Moreland Ave	21216	Unknown	DWO	N/A	Not Witnessed	Clear water coming from sump pump	Evidence of Overflow	Left plumber notice to locate or install external cleanout	Locate or install external cleanout	248278	
48	3/26/2015	2200 Hunter St	21218	Grease, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	17	Sewer main line choke manhole overflowing	255	Pressure jet relieved mainline choke	Turned over for CCTV	248433	
49	3/27/2015	4409 Springdale Ave	21207	Pipe Break	WWO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Ran 35' Electric machine	Refer for repairs on House connection	248604	
50	3/27/2015	1703 S Clinton St	21224	Rags	WWO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	248620	
51	3/27/2015	2733 Rayner Ave	21216	Pipe Break	WWO	N/A	Not Witnessed	Debris & Toilet paper visible	Evidence of Overflow	Ran 2' of electric machine, unable to pass on the consumers side	Left plumber notice	248651	
52	3/29/2015	2318 Ivey Ave	21214	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence of toilet paper and debris around clean out	Evidence of Overflow	Ran 45' of electric machine to relieve house connection choke	CCTV	248774	
53	3/29/2015	825 Yale Ave	21229	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water and evidence visible	Evidence of Overflow	Relieved mainline choke with 300' of pressure machine hose	CCTV	248841	
54	3/30/2015	3434 Park Heights Ave	21215	Rags	DWO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Used electric machine to relieve H/C choke	CCTV	248951	
55	3/30/2015	4629 Reisterstown Rd	21215	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper, rags and evidence	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	248955	
56	3/30/2015	5805 Dale Rd	21209	Rags	DWO	N/A	Not Witnessed	House connection choke with signs of overflow	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	248966	
57	3/30/2015	2509 Marbourne Ave	21230	Rags	DWO	N/A	Not Witnessed	Paper and signs of overflow at location	Evidence of Overflow	Evidence of overflow, no clean out property	CCTV	248966	
58	3/31/2015	2764 Kinsey Ave	21223	Rags	DWO	N/A	Not Witnessed	Evidence of overflow, looks like someone dumped sewage in alley	Evidence of Overflow	Evidence of overflow, no clean out property	CCTV	180724	
59	3/31/2015	3439 Edmondson Ave	21229	Trash, Sand, Gravel, Rocks	DWO	N/A	41	Heavy gray water	82	Relieved m/l choke with press truck 150 ft of 8"	CCTV	249080	
60	3/31/2015	5108 Hillen Rd	21239	Roots	DWO	N/A	Not Witnessed	Paper and debris around house connection	Evidence of Overflow	Drain cleaning machine relieved lateral choke, removed roots	TV'd lateral	249115	
61	3/31/2015	420 E 25th St	21218	Rags	DWO	N/A	Not Witnessed	Rags and evidence around house connection	Evidence of Overflow	Used electric machine and sewer jet to relieve choke	CCTV	249179	
62	3/31/2015	212 Northway	21218	Rags	DWO	N/A	Not Witnessed	Evidence and paper found around house connection	Evidence of Overflow	Used electric machine to relieve choke	CCTV	249192	
				# WWO			29			TOTAL	24,011	EVIDENCE ONLY	47