

SSO Notification List

March 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2016	1600 Bruce Ct	21217	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	115	Clear colored water	115	Cleaned line with pressure truck to relieve choke	Line to be CCTV'd	294011
2	3/1/2016	2400 Windsor Ave	21217	Rags	DWO	N/A	Not Witnessed	Heavy gray water around clean out	Evidence of Overflow	Relieved choke with 30 ft of electric machine	CCTV	293941
3	3/2/2016	1325 W Saratoga St	21223	Rags, Roots	DWO	N/A	Not Witnessed	Gray water, dampness around house connection	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	294065
4	3/3/2016	1239 Glenwood Ave	21239	Pipe Break	DWO	Chinquapin Run	60	Sewage discharging into storm inlet pipe from adjacent choked sanitary pipe	12	Jetted line with a vactor truck to abate SSO	Line needs to be CCTV'd	294363
5	3/3/2016	2806 Roselawn Ave	21214	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Cleaned line with electric machine, relived house connection choke	Line to be CCTV'd	294411
6	3/3/2016	4210 N Charles St	21218	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Sewage debris in stream from open sanitary pipe. Stream water is flowing into pipe where VC pipe meets PVC pipe	Evidence of Overflow	Relieved mainline choke with 250 ft of pressure truck on 12 inch	CCTV	294384
7	3/5/2016	2628 E Baltimore St	21224	Rags, Grease	WWO	N/A	Not Witnessed	Heavy gray water around the clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	294647
8	3/6/2016	22 N Ellwood Ave	21224	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Cloudy water around the clean out	Evidence of Overflow	Cleaned line with 15 ft of electric machine	Line will be CCTV'd	294670
9	3/6/2016	3738 Manchester St	21215	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray murky water	Evidence of Overflow	Relieved house connection choke. Turned over for mainline cleaning	CCTV	294679
10	3/7/2016	2116 Presbury St	21217	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	114	Gray water and debris	114	Relieved house connection choke with 75' of electric machine	CCTV	294850
11	3/7/2016	3700 E Baltimore	21224	Rags, Grease	DWO	N/A	318	Heavy gray water	1,590	Relieved mainline choke with 250 ft of pressure truck on 12" line	CCTV	294876
12	3/7/2016	3205 Fairfield Rd	21226	Rags, Grease	DWO	N/A	208	Heavy gray water	3,120	Relieved mainline choke with 1,500 ft of pressure truck on 8" line	CCTV	294882
13	3/8/2016	828 Newington Ave	21217	Rags, Roots	DWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	295049
14	3/8/2016	6228 Laurelton Ave	21214	Grease	DWO	N/A	55	Gray water overflowing from house connection	275	Relieved house connection choke with 60 ft of electric machine	CCTV	295106
15	3/9/2016	5624 Mattfeldt Ave	21209	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	295155
16	3/9/2016	2300 Reisterstown Rd	21215	Rags	DWO	N/A	73	Heavy gray water	219	Relieved mainline choke with 180 ft of pressure truck on 8" line	CCTV	295133

SSO Notification List

March 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	3/9/2016	1925 W Saratoga St	21223	Pipe Break	DWO	N/A	Not Witnessed	Paper and sewage	Evidence of Overflow	Ran 32 ft of electric machine to relieve house connection choke	Turn over for repairs, broken sanitary connection	293118
18	3/10/2016	1701 N Caroline St	21213	Rags	DWO	N/A	Not Witnessed	Heavy paper and muck	Evidence of Overflow	Drain cleaning machine relieved house connection choke	CCTV	295394
19	3/10/2016	2500 Oswego Ave	21215	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	241	Heavy gray water overflowing	482	Relieved mainline choke with 500 ft press truck on 8" line	CCTV	295596
20	3/10/2016	3304 W North Ave	21216	Rags, Grease	DWO	N/A	240	Heavy gray water	1,200	Relieved mainline choke with 300 ft of pressure truck on 8" line	CCTV	295571
21	3/12/2016	319 E 22nd St	21218	Rags, Roots	WVO	N/A	65	Rear house connection choke, cleanout overflowing	65	Relieved house connection choke with 60 ft of electric machine on 6" line	CCTV	295744
22	3/14/2016	2137 N Smallwood St	21217	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	54	Gray water and debris	27	Relieved house connection choke with 30 ft of electric machine.	CCTV	295876
23	3/14/2016	3834 Lewin Ave	21215	Rags, Roots, Grease	WVO	N/A	Not Witnessed	Dark murky water and paper	Evidence of Overflow	Relieved house connection choke with 85 ft of electric machine on 6" line	CCTV	295916
24	3/14/2016	1011 Hilton St	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	WVO	Gwynns Falls	292	Heavy gray water	5,840	Relieved mainline choke with 275 ft of pressure truck on 8" line	CCTV	295897
25	3/15/2016	5009 Blythewood Rd	21210	Infiltration/Inflow, Pipe Break	DWO	Stony Run	80	Sewage overflowing into storm drain and entering stream. Entering storm pipe on the left side, about 30ft up from D29UU1078MH. Discharge is surging to more than double estimated flow.	240	Relieved choke with 5' of pressure machine hose	CCTV	296059
26	3/15/2016	1820 Spence St	21230	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	Murky gray water	230	Murky gray water	1,150	Relieved mainline choke with 100 ft of pressure machine hose	CCTV	296063
27	3/17/2016	3109 Juneau Pl	21214	Pipe Break	WVO	N/A	Not Witnessed	Front house connection choke, evidence of an overflow from clean out. SSO report is needed. Sewer maintenance crew 751 stated clean out is broken down on consumer side, left a notice for problem. Referred location to housing code enforcement -Sr#201197	Evidence of Overflow	This location has a broken clean out on private property, break at the bottom of cleanout	A plumbers note was left with the consumer and this location was turned over to HCD. SR number 201197	295863
28	3/17/2016	2311 Cross Country Blvd	21209	Roots	DWO	Western Run	48,965	Sewage is leaking from sanitary manhole through open joints into the adjacent storm drain inlet pipe.	2,448	Maintenance repaired the leaking pipe, sewage is no longer escaping the system	CCTV, the leaking asset was repaired by UMD	296507
29	3/17/2016	5810 Greenspring Ave	21202	Roots	DWO	Western Run	349,916	Sewage is leaking front open joints in the sanitary manhole into the adjacent storm drain inlet pipe	34,991	Leaking pipe repaired by, no longer overflowing	Construction repaired leaking pipe	296508

SSO Notification List

March 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
30	3/18/2016	1450 Ridgely St	21230	Rags, Trash, Sand, Gravel, Rocks, Pipe Break	DWO	N/A	Not Witnessed	Sewage and debris	Evidence of Overflow	Relieved choke with 75 ft of electric machine	CCTV	296618
31	3/20/2016	3324 Gwynns Falls Pkwy	21216	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water and debris	Evidence of Overflow	Ran electric machine to attempt to relieve choke	Left plumbers notice to remove pipe in connection	298826
32	3/20/2016	265 W 31st St	21211	Rags, Roots	WVO	N/A	Not Witnessed	Murky gray evidence around clean out	Evidence of Overflow	Relieved house connection choke with 9 ft of electric machine.	CCTV	296803
33	3/22/2016	2307 E Fairmont Ave	21224	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Heavy gray water and debris	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	297237
34	3/24/2016	1811 E 29th St	21218	Grease	DWO	N/A	Not Witnessed	Sewer water and toilet paper	Evidence of Overflow	Relieved house connection choke with 45ft of electric machine	CCTV	238274
35	3/24/2016	1814 N Bond St	21213	Roots	DWO	N/A	Not Witnessed	Paper and water	Evidence of Overflow	Cleaned line with 30 ft of electric machine and h-cutter	CCTV	297481
36	3/24/2016	4301 West Bay Ave	21226	Rags, Roots	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved mainline choke with 125 ft of pressure truck on 8"	CCTV	297563
37	3/24/2016	5001 Pulaski Hwy	21205	Rain, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Extensive waste debris around overturned manhole cover and surrounding area.	Evidence of Overflow	Overflow location will be monitored during heavy rain events	Replace manhole frame and cover to try and prevent future overflows	297533
38	3/25/2016	810 Glen Allen Dr	21229	Roots	WVO	N/A	Not Witnessed	Gray water and dampness	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	238506
39	3/28/2016	2803 E Preston St	21213	Rags, Grease	WVO	N/A	Not Witnessed	Cloudy water and evidence	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	297851
40	3/28/2016	4417 Findlay Rd	21206	Rags, Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	290	Found active overflow at location, main line choke	1,160	Pressure machine truck relieved 400 ft of pressure machine hose	CCTV mainline	297882
41	3/29/2016	1740 E Lanvale St	21213	Trash, Sand, Gravel, Rocks	WVO	N/A	97	Rear house connection choke, active overflow in rear of location. Also running from cleanout stack against house no cap	97	Relieved house connection choke with electric machine	CCTV	297971
42	3/29/2016	6307 Wallis Ave	21215	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper and evidence	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	298002
43	3/30/2016	245 N Monroe St	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Light sewage	Evidence of Overflow	Relieved mainline choke with 150 ft of pressure truck on 6" line	CCTV	298233
44	3/30/2016	1501 Hartsdale Rd	21239	Pipe Break	DWO	Chinquapin Run	82,020	Sewage is leaking from a sanitary sewer pipe and is being conveyed through an unknown course. It is appearing in the stream at a sewer crossing approximately 420 ft downstream from the leaking pipe	20,505	Leaking pipe identified through dye testing has been lined and is no longer leaking.	Pipe was lined by on call contractors	

SSO Notification List

March 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
45	3/30/2016	1704 Joplin St	21224	Trash, Sand, Gravel, Rocks	WVO	N/A	55	Paper and sewage overflowing from house connection	220	Relieved house connection choke with 45 ft of electric machine	CCTV	298196
46	3/30/2016	2506 Mosher St	21216	Roots, Grease	WVO	N/A	Not Witnessed	Gray water	Evidence of Overflow	Ran 30 ft of electric machine to relieve house connection choke	CCTV	298252
47	3/30/2016	2924 Mallview Rd	21230	Roots	WVO	N/A	Not Witnessed	Gray water and debris visible	Evidence of Overflow	Ran 4 ft of electric machine to relieve house connection choke	CCTV	298152
48	3/30/2016	4403 Frederick Ave	21229	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Found evidence of overflow, sewer running into creek in rear of Mt. Saint Joseph High School	Evidence of Overflow	Met with school maintenance worker at location, referred for mainline choke	CCTV	298175
49	3/31/2016	2400 Harriett Ave	21230	Rags, Grease	WVO	N/A	195	Debris and tissue	975	Relieved mainline choke with 300' of pressure machine hose	CCTV mainline	298460
				# WVO	20			TOTAL	74,845	EVIDENCE ONLY	28	