

## SSO Notification List

MARCH 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/2/2018	247 N Bruce St	21223	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	8	Relieved 6" house connection choke with 30 ft of electric cable.	Confirmed connection is clear and performed mainline CCTV inspection.	527676
2	3/2/2018	238 S Loudon Ave	21229	Rags, Roots, Trash	Wet	N/A	0	Water observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	527774
3	3/4/2018	3519 Rosekemp Ave	21214	Rags, Roots, Trash	Wet	N/A	0	Water observed around the manhole at the rear of the property.	30	Relieved 8" mainline choke with 175 ft of pressure hose.	Performed mainline CCTV inspection.	527929
4	3/5/2018	W Fairmount Ave & N Franklinton Rd	21223	Rags, Grease	Dry	N/A	101	Heavy gray water escaping manhole.	101	Flushed and cleaned 8" mainline with 200 ft of pressure hose.	Confirmed mainline is clear.	528131
5	3/5/2018	503 N Streeper St	21205	Trash, Sand, Gravel, Rocks, Structural	Dry	N/A	295	Gray water flowing at the rear of the property.	295	Private plumber fixed issue on consumer side.	Flushed and cleaned 8" mainline.	528172
6	3/5/2018	3208 Piedmont Ave	21216	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Confirmed connection and mainline are clear.	528194
7	3/6/2018	2657 Norland Rd	21230	Rags, Grease, Trash	Wet	N/A	0	Grease buildup observed around the cleanout at the front of the property.	5	Relieved house connection choke with 7 ft of electric cable.	Confirmed mainline and connection are clear.	528547
8	3/9/2018	6308 Clearspring Rd	21212	Unknown	Wet	N/A	42	Choked manhole found during routine watershed survey.	210	Relieved mainline choke with 90 ft of pressure hose.	Confirmed mainline is clear.	529241
9	3/10/2018	212 N Streeper St	21224	Rags, Grease, Trash, Sand, Gravel, Rocks, Structural	Dry	N/A	93	Heavy gray water flowing in the street.	186	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection to determine possible structural damage..	529559
10	3/10/2018	2111 Mount Holly St	21216	Rags, Roots	Dry	N/A	0	Water observed around the cleanout at the front of the property.	4	Relieved 6" house connection choke with 35 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	529556
11	3/12/2018	6900 Bownel Ave	21237	Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	10	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned mainline.	529759
12	3/12/2018	600 S Martin Luther King Jr Blvd	21201	Rags, Grease	Dry	N/A	150	Gray water escaping manhole in the street.	750	Relieved mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	529732
13	3/13/2018	18 Midvale Rd	21210	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	35	Relieved house connection choke with 30 ft of electric cable.	Camera confirmed connection is clear.	530153
14	3/14/2018	5200 Darien Rd	21206	Rags, Trash	Dry	N/A	0	Water and debris observed around the cleanout at the front of the property.	25	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	530499
15	3/14/2018	5417 Reisterstown Rd	21215	Rags, Grease	Dry	Gwynns Falls	127	Office of Compliance and Laboratories discovered a choked manhole while investigating nearby.	127	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	530566
16	3/14/2018	6216 Pinehurst Rd	21212	Rags, Roots, Trash	Dry	N/A	0	Dampness observed around the cleanout.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; cleaned the mainline.	530685
17	3/15/2018	3400 Reisterstown Rd	21215	Rags, Trash	Dry	N/A	139	Heavy gray water escaping the manhole.	695	Relieved 8" mainline choke with 275 ft of pressure hose.	Performed mainline CCTV inspection.	530868
18	3/16/2018	5015 Falls Road Ter	21210	Rags, Roots, Trash	Dry	N/A	500	Gray water escaping the manhole.	1,000	Relieved mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	531234
19	3/16/2018	4524 Keswick Rd	21210	Rags, Roots, Trash	Dry	N/A	0	Dampness observed around the cleanout at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; cleaned the mainline.	531313

## SSO Notification List

MARCH 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	3/18/2018	6011 Falls Rd	21209	Rags, Grease, Trash	Dry	N/A	290	Heavy gray water flowing in the street.	580	Relieved mainline and house connection chokes with 160 ft of pressure hose.	Performed CCTV inspections.	531403
21	3/18/2018	726 Newington Ave	21217	Rags, Trash, Other	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Left door notice indicating findings.	531420
22	3/19/2018	Evesham Ave & The Alameda	21239	Rags, Trash	Dry	N/A	242	Gray water escaping manhole in the street.	484	Relieved mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	531701
23	3/19/2018	1149 Covington St	21230	Rags, Roots, Rain	Dry	N/A	196	Gray water actively flowing on sidewalk and street.	392	Relieved mainline and house connection chokes.	Performed CCTV inspections.	531754
24	3/21/2018	2100 E 20th St	21213	Rags, Grease, Trash	Wet	N/A	64	Heavy gray water escaping manhole.	320	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	533045
25	3/22/2018	1412 N Luzerne Ave	21213	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear.	533711
26	3/22/2018	W Cold Spring Ln & Keswick Rd	21210	Rags, Grease, Trash	Wet	N/A	232	Gray water escaping manhole.	464	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	533704
27	3/26/2018	2804 Wilkens Ave	21223	Rags, Trash	Dry	Gwynns Falls	0	Gray water observed around manhole.	50	Relieved mainline choke.	Confirmed choke was relieved.	535569
28	3/26/2018	Back River WWTP, Old Influent	21224	Other	Dry	N/A	125	Overflow through a 4" opening in a wall	1,000	The gates were immediately opened and the chamber level decreased.	Contact consultant for SC877 to prevent any future accidental shutdowns.	
29	3/27/2018	919 Claymont Ave	21216	Rags, Grease, Trash	Dry	N/A	125	Heavy gray water escaping the manhole in the street.	625	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	535873
30	3/28/2018	2657 Norland Rd	21230	Rags, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 10 ft of electric cable.	Confirmed choke is relieved; left notice for consumer.	536091
31	3/28/2018	723 E Preston St	21202	Rags, Trash	Dry	N/A	0	Heavy gray water and debris observed around the cleanout.	15	Relieved house connection choke with 30 ft of electric cable.	Flushed and cleaned 8" mainline; confirmed connection is clear.	536209
32	3/28/2018	3114 Grindon Ave	21214	Rags, Roots, Grease	Dry	N/A	0	Heavy gray water and debris observed around the cleanout.	6	Relieved 6" house connection choke with 30 ft of electric cable.	Cleaned lateral to confirm it's clear.	536221
33	3/28/2018	428 E Preston St	21202	Rags, Grease, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout on the sidewalk.	7	Relieved house connection choke with 30 ft of electric cable.	Flushed and cleaned 8" mainline; confirmed lateral is clear.	536233
34	3/29/2018	3025 Wolcott Ave	21216	Rags, Trash	Dry	N/A	166	Gray water escaping the manhole in the street.	166	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	536476
35	3/29/2018	4059 Evans Chapel Rd	21211	Rags, Trash	Dry	N/A	0	Dampness observed around the manhole in the street.	15	Relieved 8" mainline choke with 500 ft of pressure hose.	Performed mainline CCTV inspection.	536480
36	3/30/2018	3229 Abell Ave	21202	Rags, Trash	Wet	N/A	191	Gray water flowing from cleanout at the rear of the property.	382	Relieved house connection choke; flushed and cleaned 8" mainline.	Performed CCTV inspection; confirmed lines are clear.	536554
37	3/31/2018	5801 Leith Walk	21239	Rags, Grease	Wet	N/A	0	Water observed around the manhole.	7	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	536612
				# WWO	10			TOTAL	8,034	UNDER 100 GALLONS	20	