

SSO Notification List

May 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2015	Guilford Ave and 26th St	21218	Pipe Break	DWO	Jones Falls	303	Heavy gray water	7,575	Bulkhead off of 12" inch mainline, bypass pumping was required to abate overflow	Pipe was CCTV'd. Broken pipe will be repaired	253309
2	5/3/2015	2711 Ruscombe Ave	21215	Roots	DWO	N/A	Not Witnessed	Evidence of spillage in and around the house connection	Evidence of Overflow	Ran 30 ft of electric machine cable to relieve the choke	CCTV	253687
3	5/3/2015	4122 Westview Rd	21218	Rags, Roots	DWO	N/A	Not Witnessed	Wet around manhole, evidence of overflow present	Evidence of Overflow	Used 100' of pressure hose to relieve mainline choke	CCTV	253726
4	5/5/2015	203 Chancery Rd	21218	Trash, Sand, Gravel, Rocks	DWO	Jones Falls	99	Heavy sewage discharge into storm	9,900	Used 300' of pressure truck to relieve choke	Pipe will be CCTV'd	253981
5	5/5/2015	823 N Central Ave	21205	Rags, Roots	DWO	N/A	Not Witnessed	Evidence showing and area is wet around cleanout	Evidence of Overflow	Used electric machine to relieve choke	CCTV	254061
6	5/6/2015	Deepdene Rd & Edgevale Rd	21210	Rags, Roots, Grease	DWO	N/A	252	Heavy gray water	1,260	Relieved mainline choke with pressure truck, used 250 ft of pressure hose on 6" inch pipe	CCTV	254116
7	5/6/2015	1249 N Broadway	21213	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper and other evidence showing around the clean out	Evidence of Overflow	Relieved rear house connection choke with 30' of electric machine	CCTV	254126
8	5/7/2015	2106 Harford Rd	21218	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water and evidence around the clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	254270
9	5/7/2015	2760 Wilkins Ave	21223	Rags, Trash, Sand, Gravel, Rocks, Pipe Break	DWO	Gwynns Falls	133	Grey water discharging from manhole	3,325	Pressure truck relieved the mainline choke with 450' of pressure hose	CCTV	254367
10	5/8/2015	1730 W North Ave	21217	Rags	DWO	N/A	Not Witnessed	Evidence of overflow caused by rear house connection choke	Evidence of Overflow	Ran 30' electric machine to relieve rear house connection choke, used H-cutter to remove rags	CCTV	254511
11	5/8/2015	1631 Gwynns Falls Pkwy	21217	Rags	DWO	N/A	Not Witnessed	Found evidence of an overflow caused by rear house connection choke	Evidence of Overflow	Relieved house connection choke with 35' of electric machine, used H-cutter to remove rags	CCTV	254552
12	5/8/2015	3204 Juneau Pl	21214	Rags	DWO	N/A	Not Witnessed	Front house connection choke, evidence of an overflow	Evidence of Overflow	Relieved house connection choke with 30' of electric machine, used H-cutter to remove rags	CCTV	254572
13	5/9/2015	912 W Franklin St	21201	Rags	DWO	N/A	Not Witnessed	Sewer water and toilet paper around the clean out	Evidence of Overflow	Relieved house connection choke with 35ft of electric machine on 6" pipe	CCTV	254535
14	5/9/2015	3607 Brooklyn Ave	21225	Rags	DWO	N/A	Not Witnessed	Evidence of overflow caused by front house connection choke, cap is off of clean out	Evidence of Overflow	Relieved front house connection choke with electric machine	CCTV	254606
15	5/10/2015	306 E 33rd St	21218	Roots	DWO	N/A	Not Witnessed	Signs of an overflow around front house connection	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	254677
16	5/10/2015	Edmondson Ave and Evergreen St	21223	Rags	DWO	N/A	Not Witnessed	Murky gray water and toilet paper around manhole	Evidence of Overflow	Relieved mainline choke with pressure hose, removed grease	CCTV	254664
17	5/10/2015	2815 Carver Rd	21225	Rags	DWO	N/A	57	Murky water coming out of cleanout	570	Relieved choke with pressure truck	CCTV	254673
18	5/11/2015	6101 Oak Leaf Ave	21215	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Dried up toilet paper and other evidence noticeable around the clean out	Evidence of Overflow	Used 45' of electric machine to relieve house connection choke	CCTV	254819
19	5/11/2015	600 Stony Spring Dr	21210	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Water and sewage around the manhole	Evidence of Overflow	Used 200' of pressure hose to remove grease and debris	CCTV	254841
20	5/12/2015	420 E 25th St	21218	Grease	DWO	N/A	Not Witnessed	Evidence of sewer water and toilet paper around the clean out.	Evidence of Overflow	Used 3' of electric machine cable, H-cutter, and auger.	CCTV	254851
21	5/12/2015	721 E Preston St	21202	Rags, Grease	DWO	N/A	Not Witnessed	Gray water and debris around the clean out.	Evidence of Overflow	Relieved house connection choke with 9' of electric machine on 6" pipe	CCTV	254972

SSO Notification List

May 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	5/14/2015	5308 Lantern Ct	21229	Rags, Grease	DWO	N/A	Not Witnessed	Gray water and debris around the clean out	Evidence of Overflow	Relieved connection choke with 90' of electric machine	CCTV	255313
23	5/14/2015	5619 Frankford Ave	21206	Roots, Grease, Trash, Sand, Gravel, Rocks	DWO	Herring Run	180	Sewage flowing out of the manhole into the stream	540	Mainline choke was relieved with 400' of pressure hose	CCTV	255274
24	5/15/2015	3506 Spaulding Ave	21215	Other	DWO	N/A	Not Witnessed	Dampness, gray water	Evidence of Overflow	Pressure truck flush mainline	Left plumbers notice	255430
25	5/15/2015	1631 Gwynns Falls Parkway	21217	Rags, Grease	DWO	N/A	Not Witnessed	Area wet around clean out, evidence visible	Evidence of Overflow	Used electric machine to relieve the house connection choke	CCTV	255501
26	5/16/2015	16 S Tremont Rd	21229	Rags	DWO	N/A	Not Witnessed	Water and evidence visible around cleanout	Evidence of Overflow	Cleaned connection with electric machine, relieved choke	Line to be CCTV'd ASAP	255541
27	5/17/2015	2813 Cheswolde Rd	21209	Rags, Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper and evidence showing around cleanout	Evidence of Overflow	Cleaned and relieved the house connection choke with electric machine	Line to be CCTV'd ASAP	255621
28	5/17/2015	2800 Rosalind Ave	21215	Rags, Roots	WVO	Jones Falls	104	Sewage running from rear cleanout	208	Jetted line with pressure truck	Line to be CCTV'd ASAP	255635
29	5/18/2015	1800 Appleton St	21217	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Standing water by manhole near construction site.	Evidence of Overflow	Flushed 6" main using 250 ft of pressure hose, removed rags and debris	CCTV Inspection	255900
30	5/19/2015	1151 N Charles St	21202	Rain, Infiltration/Inflow	WVO	N/A	Not Witnessed	Gray water and evidence around the manhole	Evidence of Overflow	Evidence of overflow around manhole, line to be cleaned	CCTV	255937
31	5/19/2015	3103 E Northern Parkway	21214	Rain, Trash, Sand, Gravel, Rocks	WVO	Biddison Run	208	Sump Pump	1,040	Cleaned mainline with pressure truck, relieved choke	This line to be CCTV'd	255873
32	5/19/2015	3300 Clipper Mill Rd	21211	Other	WVO	N/A	Not Witnessed	Wastewater flushed into stream	Evidence of Overflow	Assessing Maryland Zoo operating practices to mitigate high flows through this sewer pipe	Performed hydraulic analysis of the pipe	255928
33	5/19/2015	5619 Frankford Ave	21206	Roots, Rain	WVO	N/A	1,941	Sewer water discharging	3,882	Pressure jet relieved mainline choke	Turned over to CCTV	256044
34	5/20/2015	2750 Wilkens Ave	21223	Trash, Sand, Gravel, Rocks, Pipe Break	DWO	Gwynns Falls	346	Heavy gray water	1,730	Relieved manhole choke with pressure truck, used 250 ft of hose on 8" pipe	CCTV	256140
35	5/20/2015	909 N Charles St	21202	Rags	WVO	N/A	Not Witnessed	Rags, paper and sewage present around the clean out	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	256166
36	5/20/2015	2316 Erdman Ave	21213	Rags, Roots	WVO	N/A	Not Witnessed	Rags, paper and other evidence found around the clean out	Evidence of Overflow	Used electric machine to relieve the house connection choke	CCTV	256193
37	5/20/2015	3300 Clipper Mill Rd	21211	Other	DWO	Jones Falls	8	Wastewater flowing into stream	1,600	Assessing Maryland Zoo operating practices to mitigate high flows through this sewer pipe	Performed hydraulic analysis of the pipe	256229
38	5/21/2015	5423 O'Donnell St	21224	Trash, Sand, Gravel, Rocks	WVO	N/A	241	Sewer water and toilet paper	1,205	Relieved choke with pressure truck	CCTV	256217
39	5/21/2015	2800 Sethlow Rd	21225	Rags, Rain, Grease	WVO	Patapsco River	196	Heavy gray water	3,920	Relieved mainline choke with pressure truck, used 300 ft of hose on 12" line	CCTV	256242
40	5/21/2015	1503 Clifton Ave	21217	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Rear house connection choke, evidence of an overflow found. Not overflowing at this time, SSO report needed	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	256257
41	5/22/2015	136 Duncan St	21231	Rags	WVO	N/A	Not Witnessed	Gray water and debris visible around the house connection	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	256366
42	5/25/2015	1328 Tompkins St	21225	Rags, Grease	DWO	N/A	Not Witnessed	Evidence present around manhole	Evidence of Overflow	Used 150' of pressure hose on 8" line to relieve mainline choke	CCTV	256625
43	5/26/2015	1000 W North Ave	21217	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	67	Cloudy water and discharge	1,340	Relieved mainline choke with 350 ft of pressure truck on 8" pipe	CCTV	256651

