

## SSO Notification List

November 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/2/2015	5819 Western Run Dr	21209	Rags, Roots	DWO	N/A	378	Heavy gray water coming from the manhole	756	Relieved mainline choke with 175ft of pressure truck on 8" sanitary sewer line	CCTV	278579
2	11/4/2015	200 East St	21224	Rags, Grease	DWO	N/A	Not Witnessed	Wet around manhole, evidence and sewage present.	Evidence of Overflow	Flushed and cleaned 8 in sanitary mainline with 250 ft of pressure hose	CCTV	278940
3	11/4/2015	575 Lucia Ave	21229	Rags, Roots	DWO	N/A	Not Witnessed	Sewage in alley form sump pump	Evidence of Overflow	Used 200ft of sewer jet to relieve mainline choke and abate overflow.	CCTV	278814
4	11/4/2015	Park Ave and Reservoir St	21217	Rags, Grease	DWO	N/A	66	Heavy gray water flowing from manhole	132	Relieved mainline choke with 225 ft of pressure truck on 8" line	CCTV	278824
5	11/6/2015	5009 Blythewood Rd	21210	Rags, Roots	DWO	Stony Run	107	Sewage leaving the choked sanitary underground and entering the storm drain.	26	Relieved m/l choke with press truck 400 ft of 8"	CCTV	279129
6	11/6/2015	701 N Carey St	21217	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper	Evidence of Overflow	Rel. 45' elec. machine	CCTV	279149
7	11/6/2015	4116 Doris Ave	21225	Rags, Roots, Grease	WWO	N/A	Not Witnessed	Wet around manhole, evidence is present	Evidence of Overflow	Used 400 ft of sewer jet to relive mainline choke	CCTV	279221
8	11/7/2015	1453 Medfield Ave	21211	Rags, Roots, Grease	WWO	Jones Falls	10	Cloudy water overflowing from manhole	100	Relieved mainline choke with 60' of pressure machine hose	CCTV	279261
9	11/11/2015	1910 Eastern Ave	21231	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence is present around clean out	Evidence of Overflow	Relieved house connection choke with 30ft of electric machine on 6" line	CCTV	279700
10	11/13/2015	719 Eastern Ave	21230	Grease	WWO	Inner Harbor	120	Gray and brown water flowing from manhole in parking lot	240	Used 200ft of sewer jet to relieve mainline choke	CCTV	279934
11	11/14/2015	2121 Mount Holly St	21216	Rags, Trash, Sand, Gravel, Rocks, Unknown	WWO	Gwynns Falls	Not Witnessed	Clear and cloudy water around sump pump	Evidence of Overflow	Used pressure truck to flush mainline	CCTV	280055
12	11/14/2015	4755 Melbourne Rd	21229	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	135	Medium flow of sewage flowing from the manhole	405	Relieved mainline choke with 400' of pressure machine hose	CCTV	280086
13	11/15/2015	259 Robert St	21217	Roots, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray Water and debris visible around the clean out	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	280118
14	11/16/2015	4220 Parkton St	21229	Rags, Roots	DWO	N/A	1,114	Coming out a clean out pipe over top of mainline outside the property line.	2,228	Relieved house conn choke with press truck 125 ft of pressure truck on 6" line	CCTV	280200
15	11/17/2015	Martin Luther King Jr. Blvd and Saratoga St	21201	Rags, Roots	DWO	N/A	26	Clear water overflowing from clean out in front of the building	130	Pressure truck relieved house connection choke with 30' of pressure machine hose	CCTV	280340
16	11/17/2015	1107 Slater Rd	21225	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	102	Cloudy water overflowing from eyes of sewer manhole	510	Relieved mainline choke with 175 ft of pressure truck on 8 inch line	CCTV	280422

## SSO Notification List

November 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	11/17/2015	5100 Perring Parkway	21239	Pipe Break	DWO	Herring Run	5,540	Main line choke sewer running in stream from sewer manhole stack	55,400	Bypass pumping was used to abate the overflow. Overflow is no longer ongoing	Turned over to contractor to start bypass pumping operation and to stop leak	220416
18	11/18/2015	4302 Maine Ave	21207	Rags	DWO	N/A	Not Witnessed	Rear house connection choke, evidence of overflow from clean out	Evidence of Overflow	Relieved house connection choke with 60 ft of electric machine on 6" line	CCTV	280545
19	11/18/2015	5715 Park Heights Ave	21215	Rags, Roots	DWO	N/A	50	Rear house connection choke. Active overflow from clean out	50	Relieved house connection choke with 60 ft of electric machine on 6" line	CCTV	280559
20	11/22/2015	700 Pennsylvania Ave	21201	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	37	Paper and murky water overflowing from manhole	185	Jetted line with 300' of pressure hose to relieve mainline choke	Line to be CCTV'd ASAP	281086
21	11/24/2015	100 Beechdale Rd	21210	Rags, Roots	DWO	N/A	123	Murky gray water and toilet paper coming from clean out	246	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	281381
22	11/24/2015	5100 Perring Pkwy	21239	Pipe Break	DWO	Herring Run	276	Sewage seeping into the stream due to the line being surcharged during the bypass operation	276	Seepage stopped once bypass operation ended and flow level returned to normal	Manhole will be lined	
23	11/24/2015	Gusryan St and O'Donnell St	21224	Rags, Grease	DWO	N/A	Not Witnessed	Evidence of overflow around manhole	Evidence of Overflow	Mainline is flowing free and clear, manhole no longer overflowing	CCTV	281334
24	11/26/2015	6209 Everall Ave	21206	Roots	DWO	N/A	Not Witnessed	Evidence of spillage around rear clean out	Evidence of Overflow	Relieved house connection choke with electric machine, used H-cutter to remove roots	CCTV	221154
25	11/27/2015	810 N Hilton St	21229	Rags, Grease	DWO	Gwynns Falls	90	Gray colored water leaking from manhole	270	Used sewer jet to relieve mainline choke and abate overflow at this location	CCTV	281767
26	11/28/2015	1906 N Pulaski St	21217	Rags, Roots, Grease	DWO	N/A	79	Rags and sewage overflowing from rear house connection	79	Relieved house connection choke with 15ft of electric machine on 6" line	CCTV	281824
27	11/30/2015	2215 Rogene Dr & Bonnie View Dr	21209	Rags, Roots	WWO	Jones Falls	1,020	Sewage coming from the clean out	1,020	Relieved house connection choke with 50 ft of pressure truck 6" line	CCTV, notified construction for repair	281862
28	11/30/2015	811 Druid Park Lake Dr	21217	Rags	WWO	N/A	Not Witnessed	Found evidence of overflow from clean out in rear of location. Could not remove cap. Left notice for consumer to remove cap	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	Left plumbers notice to have clean out cap removed	281942
29	11/30/2015	810 N Hilton St	21229	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	1,338	Heavy gray water flowing out of the manhole in rear of property	13,380	Relieved mainline choke with 175 ft of pressure truck on 8" line	CCTV	281934
30	11/30/2015	1714 W North Ave	21217	Rags	WWO	N/A	Not Witnessed	Paper and sewage around the clean out	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	281965
				# WWO	9			TOTAL	75,433	EVIDENCE ONLY	12	