

SSO Notification List

October 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/3/2015	2119 Kentucky Ave	21218	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of overflow in rear	Evidence of Overflow	Relieved house connection choke with 21' of electric machine	CCTV	274969
2	10/4/2015	412 E 31st St	21218	Roots, Grease	DWO	N/A	Not Witnessed	Evidence of sewer overflow from clean out in rear	Evidence of Overflow	Relieved house connection choke with 60' of electric machine	CCTV	275051
3	10/5/2015	301 S Beechfield Ave	21229	Rags, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	Not Witnessed	Sewage debris on sanitary stack. Collar and lid in streambed next to stack	Evidence of Overflow	Removed debris from manhole and repaired 30" frame cover on manhole	Monitor location	275177
4	10/5/2015	4818 Richard Ave	21214	Roots	DWO	N/A	Not Witnessed	Front house connection choke, evidence of an overflow present	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	CCTV	275205
5	10/5/2015	320 Millington Ave	21223	Rags, Other	WWO	N/A	Not Witnessed	Toilet paper and evidence visible around cleanout	Evidence of Overflow	Relieved house connection choke with 30ft of electric machine, removed rags.	CCTV	275275
6	10/5/2015	4219 Berger Ave	21206	Other	WWO	N/A	Not Witnessed	Evidence of sewer overflow from sump pump discharging on front lawn.	Evidence of Overflow	Turned over to housing dept	Left plumbers note to locate or install clean out	275131
7	10/5/2015	827 N Martin Luther King Jr Blvd	21201	Rags, Roots	WWO	N/A	Not Witnessed	Evidence of spillage around the cleanout caused by a rear connection choke	Evidence of Overflow	Relieved rear connection choke with 35ft of electric machine, used H-Cutter to remove roots.	CCTV	275233
8	10/5/2015	1800 Falls Road	21201	Rags, Rain, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper and debris visible around manhole	Evidence of Overflow	Met crew 748 to clean area. Removed paper and debris around sanitary manhole.	Monitor location for possible future overflows	275165
9	10/5/2015	4221 Rokeyb Rd	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	Dead Run	207	Heavy sewage flowing from base of stack into stream.	5,175	Relieved mainline choke with 5ft of pressure hose in the manhole	CCTV	275273
10	10/7/2015	Asiatic Ave & Northbridge Ave	21226	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Evidence of overflow from manhole, sewer mainline choke.	Evidence of Overflow	Pressure truck relieved mainline choke. Used 130 ft of pressure hose to relieve choke.	CCTV	275540
11	10/7/2015	1611 Gwynns Falls Pkwy	21217	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray water and evidence visible around the manhole	Evidence of Overflow	Relieved mainline choke with 150 ft of pressure truck on 8" sanitary sewer line	CCTV	275571
12	10/8/2015	2816 W Lafayette Ave	21216	Rags, Roots	DWO	N/A	Not Witnessed	Sewage and toilet paper visible around the clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	275659
13	10/9/2015	3325 W Northern Pkwy	21215	Rags, Other	WWO	N/A	Not Witnessed	Paper and evidence visible around clean out	Evidence of Overflow	Used 30 ft of electric machine and H-cutter to relieve house connection choke	CCTV	275868
14	10/9/2015	4550 N Charles St	21210	Roots	WWO	Patapsco River	386	Heavy gray water leaking into the stream from the mainline	386	Heavy gray water leaking into the stream from the mainline choke on 8" line	CCTV	275862
15	10/10/2015	5301 Saint Georges Ave	21218	Rags, Roots	WWO	N/A	Not Witnessed	Toilet Paper and other debris around clean out	Evidence of Overflow	Relieved house connection choke with 30' of electric cable, removed roots with expander cutter.	CCTV	275883
16	10/11/2015	4614 Wilmslow Rd	21210	Rags, Roots	DWO	N/A	Not Witnessed	Gray water and debris visible around the clean out	Evidence of Overflow	Relieved house connection choke with 15 ft of electric machine on 6"	CCTV	275979

SSO Notification List

October 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	10/13/2015	202 Longwood Rd	21210	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke with 60 ft of electric machine on 6" line	CCTV	276211
18	10/14/2015	2725 Hampden Ave	21211	Rags, Other	DWO	N/A	Not Witnessed	Evidence of overflow from house connection in rear, rear gate locked to get to clean out	Evidence of Overflow	Ran 6 ft of electric machine and expander cutter to relieve house connection choke	CCTV	276370
19	10/15/2015	202 Longwood Rd	21210	Rags, Roots	DWO	N/A	Not Witnessed	Heavy gray water and debris visible around the rear clean out	Evidence of Overflow	Relieved house connection choke with 90ft of pressure truck on 6" line	CCTV	276211
20	10/15/2015	3601 Fords Ln	21215	Rags, Roots, Other	DWO	N/A	Not Witnessed	Wet paper around clean out	Evidence of Overflow	Used 30' of electric cable and H-cutter to remove rags and roots from the house connection	CCTV	276550
21	10/16/2015	1610 Ashburton St	21216	Pipe Break	DWO	N/A	Not Witnessed	Evidence of an overflow visible around the clean out	Evidence of Overflow	Clean out is broken on the homeowners side	Plumbers notice was left on the scene	276616
22	10/17/2015	4550 N Charles St	21210	Pipe Break	DWO	N/A	5,424	Heavy gray water in stream coming from exposed pipe.	5,424	Exposed leaking pipe was repaired by construction, overflow is no longer active	CCTV	275826
23	10/17/2015	Hilton Pkwy and Edmondson Ave	21229	Rags, Grease	DWO	N/A	93	Heavy gray water flowing from manhole	2,325	Relieved sanitary mainline choke with 175 ft of pressure truck	CCTV	276708
24	10/19/2015	3012 Gibbons Ave	21214	Rags, Roots	DWO	N/A	Not Witnessed	Front house connection choke, evidence of overflow	Evidence of Overflow	Used 45' of electric machine to relieve house connection choke	CCTV	276930
25	10/19/2015	6301 Brook Ave	21206	Rags, Roots	DWO	N/A	Not Witnessed	Wet paper around clean out, evidence present	Evidence of Overflow	Used 45' of electric machine to relieve the house connection choke	CCTV	276937
26	10/20/2015	3510 Greenmount Ave	21218	Rags, Roots	DWO	N/A	Not Witnessed	Wet around clean out, evidence is present	Evidence of Overflow	Used 30ft of electric machine and H-cutter to remove debris	CCTV	277113
27	10/20/2015	1201 N Woodington Rd	21229	Pipe Break	DWO	Gwynns Falls	1,554	Heavy green water, dye is showing up in the stream after dye test was performed.	1,554	Broken pipe was repaired by construction, SSO has been abated.	CCTV	277085
28	10/21/2015	1301 E Fayette St	21231	Rags, Grease, Other	DWO	N/A	Not Witnessed	Found evidence of an overflow due to mainline choke	Evidence of Overflow	Relieved 8" sanitary mainline choke with 360 ft of pressure hose	CCTV	277241
29	10/22/2015	6200 Shipview Way	21224	Rags, Grease	DWO	N/A	Not Witnessed	Wet around manhole, evidence and sewage present.	Evidence of Overflow	Used 300ft of sewer jet to relieve mainline choke and remove grease, rags and debris.	CCTV	277408
	10/22/2015	4611 Wilmslow Rd	21210	Roots, Pipe Break	DWO	Stony Run	100,620	4611 Wilmslow Rd, main is leaking into adjacent storm drain pipe verified by dye testing	100,620	Contractor lined the leaking pipe that was the source of the ongoing SSO at this address, pipe is no longer leaking	CCTV	266955
30	10/24/2015	832 Herndon Ct	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	117	Sewage with rags, grease, and debris overflowing	117	Relieved mainline choke with 100' of pressure machine hose	CCTV	277562
31	10/24/2015	2806 Roselawn Ave	21214	Rags, Grease	DWO	N/A	Not Witnessed	Sewage and evidence present around the clean out in the rear	Evidence of Overflow	Relieved house connection choke with 60' of electric machine, removed rags and grease.	CCTV	277568

