

## SSO Notification List

October 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/1/2017	2121 Kentucky Ave	21218	Rags, Grease	DWO	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	456030
2	10/2/2017	5800 Royal Oak Ave (Private)	21207	Rags, Trash	DWO	N/A	0	Heavy gray water observed in the street.	10	Relieved 6" mainline choke with 75 ft of pressure hose.	Performed mainline CCTV inspection.	456604
3	10/5/2017	1624 Moreland Ave	21216	Rags, Trash	DWO	N/A	0	Heavy water observed around the cleanout at the rear of the property.	9	Relieved house connection choke with 30 ft of electric cable and H Cutter.	Performed house lateral CCTV inspection.	457726
4	10/7/2017 / Abated 10/12/2017	3500 Parkdale Ave	21211	Structural	DWO	Jones Falls	7,230	Sewage discharging from private broken lateral pipe connections, entering public mainline and storm drain.	2,892	Sewer lateral connections have been repaired by a contractor.	The Office of Compliance and Laboratories has confirmed the abatement.	
5	10/8/2017	4009 Barrington Rd	21207	Roots, Trash	WWO	N/A	0	Gray water observed around the cleanout at the front of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the 8" mainline.	458312
6	10/8/2017	3404 Glen Ave - SSO #155	21215	Rain	WWO	Jones Falls	60	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	2,500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
7	10/9/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	70	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	11,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
8	10/9/2017	3404 Glen Ave - SSO #155	21215	Rain	WWO	Jones Falls	185	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	3,500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
9	10/10/2017	101 W 39th St	21210	Rags, Rain	WWO	N/A	0	Heavy gray water caused by storm drain reaching house connection.	3	Relieved house connection choke.	Performed CCTV inspection.	458709
10	10/11/2017	3404 Glen Ave - SSO #155	21215	Rags, Roots, Grease	WWO	Jones Falls	1,730	Structure discharges to a storm pipe.	7,500	Removed meter and contractor relieved 8" mainline choke with 175 ft of pressure hose.	Performed CCTV inspection.	459163
11	10/12/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	60	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	48,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	10/15/2017	6202 Wirt Ave	21215	Rags, Trash	DWO	N/A	72	Water flowing out of a manhole in the alley.	108	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	459601
13	10/19/2017	3812 Reisterstown Rd	21215	Rags, Roots	DWO	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	460472
14	10/20/2017	508 E Preston St	21202	Unknown	DWO	Jones Falls	4,160	Engineered overflow structure discovered within manhole is actively discharging into the nearby storm drain.	41,600	Bypass pumping set up to abate the overflow.	Contractor engaged to explore possible solutions. Location will be evaluated for flow monitor installation.	
15	10/20/2017	200 E 32nd St	21218	Rags, Roots, Trash	DWO	N/A	0	Water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	460806
16	10/20/2017	3402 Pinkney Rd	21215	Rags, Roots	DWO	N/A	60	Heavy gray water flowing from the manhole in the street.	300	Relieved 6" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	460773
17	10/22/2017	3502 Chestnut Ave	21211	Rags	DWO	N/A	0	Water around the cleanout at the rear of the property.	10	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	460915
18	10/23/2017	4201 Ridgewood Ave	21215	Rags, Grease	DWO	N/A	75	Water flowing from the manhole.	338	Relieved 8" mainline choke with 145 ft of pressure hose.	Mainline CCTV inspection.	460936
19	10/23/2017	5620 Frankford Ave	21206	Roots, Trash	DWO	N/A	0	Gray water around the cleanout at the rear of the property.	9	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	461039

## SSO Notification List

October 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	10/23/2017	2315 Maryland Ave	21218	Roots, Grease, Trash	DWO	N/A	0	Water around the cleanout at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	461070
21	10/24/2017	4812 Frankford Ave	21206	Rags, Roots, Trash	DWO	N/A	61	Colored water escaping cleanout and onto the sidewalk.	61	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	461189
22	10/25/2017	2585 Edmondson Ave	21223	Rags, Trash, Sand, Gravel, Rocks, Structural	DWO	Gwynns Falls	8,855	Collapse in pipe segment causing water to overflow and enter into storm drain.	17,710	8" mainline choke was relieved. Multiple leaking points on the pipe are being repaired due to structural damage. Bypass pumping set up to abate SSO.	Performed mainline CCTV inspection.	461622
23	10/25/2017	32 N Bentalou St	21215	Rags, Trash, Structural	DWO	N/A	154	Gray water coming out of the cleanout at the rear of the property.	308	Flushed and cleaned 8" mainline with 200 ft of pressure hose.	Informed consumer to contact a private plumber to remove old-style trap on cleanout. Washed down the area around cleanout.	461679
24	10/25/2017 / Abated 10/31/2017	528 E 43rd St	21212	Rags, Roots, Trash	DWO	N/A	0	Gray water and debris around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection; cleaned the 8" mainline.	461698
25	10/30/2017	3609 Copley Rd	21215	Rags, Roots	WWO	N/A	0	Heavy gray water around the cleanout at the front of the property.	3	Relieved 6" house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	462321
26	10/30/2017	5807 Royal Oak Ave (Private)	21207	Trash	WWO	N/A	106	Gray water observed in the street.	106	Relieved mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	462557
				# WWO	9			TOTAL	135,878	UNDER 100 GALLONS	29	