

SSO Notification List

OCTOBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/2/2018	3318 Burleith Ave	21215	Rags, Roots, Trash	Dry	N/A	0	Water observed around the cleanout at the front of the property.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	623186
2	10/2/2018	Annapolis Rd & Kent St	21230	Structural	Dry	N/A	89	Heavy gray water escaping broken pressure main.	8,900	Stopped overflow by opening a diversion valve and redirecting flow to another mainline.	Damaged pipe will be repaired.	623169
3	10/2/2018	5516 Park Heights Ave	21215	Rags, Grease, Trash	Dry	N/A	436	Gray water escaping the cleanout.	436	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	623416
4	10/3/2018	4121 Marx Ave	21206	Rags, Grease, Sand, Gravel, Rocks	Dry	Herring Run	122	Sanitary mainline choke causing wastewater to infiltrate adjacent storm drain.	244	Relieved 8" mainline choke with 210 ft of pressure hose.	Confirmed mainline is clear.	623662
5	10/3/2018	2327 Reisterstown Rd	21217	Rags, Grease, Trash	Dry	N/A	89	Gray water escaping manhole.	178	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	623917
6	10/4/2018	3128 Weaver Ave	21214	Rags	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed mainline and lateral are clear.	623962
7	10/4/2018	Annapolis Rd & Kent St	21230	Structural	Dry	Gwynns Falls	1,262	Broken pressure main discharging onto street and into storm drain.	378,600	Bypass pumps were installed to abate the overflow.	Site will be closely monitored until 84" pressure main can be repaired.	624234
8	10/4/2018	2032 E 30th St	21218	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	624207
9	10/5/2018	5214 Belair Rd	21206	Trash, Sand, Gravel, Rocks	Wet	N/A	199	Gray water and debris escaping the cleanout.	398	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	624770
10	10/6/2018	2347 Washington Blvd	21230	Rags, Trash	Wet	N/A	0	Gray water observed on the ground.	25	Relieved mainline choke with 10 ft of pressure hose.	Performed CCTV inspection.	624933
11	10/6/2018	Annapolis Rd & Clare St	21230	Rags, Trash, Structural	Dry	Gwynns Falls	7,317	Heavy gray water escaping manhole.	73,170	Overflow subsided following change in flow amount in pipe.	Nearby 84" pressure main will need to be repaired to return to normal conditions.	624942
12	10/7/2018	810 N Hilton St	21229	Rags, Grease, Trash	Dry	N/A	765	Gray water escaping the manhole.	3,825	Relieved 8" mainline choke with 120 ft of pressure hose.	Confirmed mainline is clear.	625023
13	10/9/2018	2101 Sidney Ave	21230	Structural, Other	Dry	Gwynns Falls	3,175	Overflowing manhole due to upstream bypass.	127,000	Overflow subsided following change in flow amount in pipe.	Nearby 84" pressure main will need to be repaired to return to normal conditions.	625309
14	10/10/2018	Annapolis Rd & Kent St	21230	Structural	Wet	Gwynns Falls	4,200	Heavy gray water escaping 84" pressure main into the storm drain.	1,224,750	Set up 20 MGD bypass pumping to reduce flow and abate the overflow. Sandbags were used to contain the compromised pressurized pipe.	Bypass pump will be continuously working until 84" pressure main can be repaired.	626000
15	10/11/2018	3310 Ridgewood Ave	21215	Rags, Grease, Trash	Dry	N/A	106	Heavy gray water escaping the manhole.	530	Relieved 8" mainline choke with 225 ft of pressure hose.	Performed CCTV inspection.	626171
16	10/13/2018	2701 Liberty Heights Ave	21215	Rags, Roots, Grease, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	7	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	626904
17	10/16/2018	110 W 39th St	21210	Rags, Grease, Trash	Dry	N/A	53	Heavy gray water escaping the manhole.	1,325	Relieved 8" mainline choke with 330 ft of pressure hose.	Confirmed mainline is clear.	627545
18	10/17/2018	3500 Parkdale Ave	21211	Structural	Dry	Jones Falls	9,967	Sewer pipe overflowing due to loss of power at an electric sewage pump.	19,934	Replaced pump to restore conditions to normal.	Pump was tested and confirmed to be fully functional.	
19	10/18/2018	3915 Glen Ave	21215	Rags, Roots, Trash	Dry	N/A	110	Gray water escaping the cleanout at the front of the property.	110	Relieved house connection choke with 45 ft of electric cable.	Confirmed connection is clear.	628655
20	10/19/2018	2315 Maryland Ave	21218	Rags, Roots, Grease	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed connection and mainline are clear.	628838

SSO Notification List

OCTOBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	10/19/2018	714 N Monroe St	21217	Rags, Roots, Grease	Dry	N/A	0	Gray water and debris observed around the cleanout.	4	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned mainline.	628887
22	10/20/2018	1822 N Payson St	21217	Rags	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	10	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspections on lateral and mainline, confirmed both are clear.	629244
23	10/21/2018	572 W University Pkwy	21210	Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	629282
24	10/22/2018	5400 Frederick Ave	21228	Rags, Roots, Trash	Dry	N/A	122	Heavy gray water escaping the manhole.	3,050	Relieved 10" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	629417
25	10/22/2018	3315 Bancroft Rd	21215	Structural	Dry	N/A	0	Sanitary sewer pipe leaking into adjacent storm drain pipe.	0	Performing CCTV inspection to help determine extent of structural damage and long-term solution.	Eventual lining of the pipe will prevent any further escape of sewage into storm drain.	
26	10/23/2018	1901 Chesapeake Ave	21226	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	5	Relieved 6" house connection choke with 25 ft of pressure hose.	Confirmed mainline and lateral are clear.	630031
27	10/25/2018	1250 N Gay St	21213	Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	10	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	630647
28	10/25/2018	2422 W Patapsco Ave	21230	Rags, Roots, Grease	Dry	Gwynns Falls	133	Overflowing manhole discovered by Pollution Control Analyst.	3,325	Relieved 8" mainline choke with 30 ft of pressure hose.	Performed CCTV inspection.	630780
29	10/29/2018	Greenspring Ave & Dupont Ave	21209	Rags, Grease, Trash	Wet	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	7	Relieved 6" house connection choke with 25 ft of electric cable.	Cleaned 10" mainline; confirmed mainline and lateral are clear.	631785
30	10/29/2018	4812 Sipple Ave	21206	Roots, Grease, Trash	Wet	N/A	0	Gray water and paper observed at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	631993
31	10/30/2018	5400 Frederick Ave (Private)	21228	Rags, Grease, Trash, Structural	Dry	N/A	1,156	Sewage escaping private system and into the waterway.	5,780	Relieved choke in the mainline.	Advised owner to install a new line.	632238
				# WWO	6			TOTAL	1,845,869	UNDER 100 GALLONS	23	