

SSO Notification List

September 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/1/2017	406 Kingston Rd	21229	Rags, Roots, Trash	DWO	N/A	137	Water with grease and debris overflowing from cleanout.	274	Relieved house connection choke with 90 ft of electric cable and expander.	Performed CCTV inspection and cleaned the mainline.	449116
2	9/1/2017	1806 Druid Hill Ave	21217	Rags, Roots	DWO	N/A	0	Gray water around the cleanout and sidewalk.	11	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	449128
3	9/2/2017	N Charles St & W Lanvale St - SSO #152	21202	Rain	WVO	Jones Falls	20	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	1,500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
4	9/3/2017	6100 The Alameda	21239	Rags, Grease	DWO	N/A	120	Colored water escaping manhole into the street and reaching the storm drain.	240	Relieved 8" mainline choke with 490 ft of pressure hose.	Performed mainline CCTV inspection.	449219
5	9/4/2017	605 E 35th St	21218	Rags, Roots	WVO	N/A	64	Water overflowing from cleanout at the rear of the property.	192	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the 8" mainline.	449286
6	9/5/2017	2918 Woodland Ave	21215	Structural	WVO	Jones Falls	3,389	House connection is leaking it the storm drain. Discovered during the investigation of an SDUO by OCAL.	102	Point repair completed for leaking location on the pipe.	OCAL confirmed abatement of the overflow.	
7	9/5/2017	1522 E Biddle St	21213	Rags, Trash, Structural	WVO	N/A	0	Heavy gray and murky water observed around the cleanout.	104	Attempted to relieve house connection choke. Pipe is clogged on customer side.	Alerted the property owner to the issue.	449320
8	9/5/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WVO	Jones Falls	10	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
9	9/6/2017	1809 Bolton St	21217	Rags, Trash	WVO	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	11	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	449566
10	9/7/2017	E Preston St & Guilford Ave	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	WVO	N/A	428	Heavy gray water flowing from the manhole.	2,140	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	449953
11	9/7/2017	6513 Eastern Pkwy	21214	Grease, Trash	WVO	N/A	0	Gray water in the street along the curb.	10	Flushed and cleaned 8" mainline using 300 ft of pressure hose.	Performed CCTV inspection.	450092
12	9/8/2017	1628 Braddish Ave	21216	Rags, Grease	WVO	N/A	0	Heavy gray water around the cleanout at the rear of the property.	10	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection and cleaned the mainline.	450194
13	9/9/2017	412 E Biddle St	21202	Rags, Roots	WVO	N/A	0	Gray water around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	450435
14	9/11/2017	1100 Covington St	21230	Rags, Trash	DWO	N/A	109	Gray water around the cleanout and manhole.	1,090	Relieved mainline choke and house connection choke using 60 ft of electric cable.	Performed CCTV inspection.	450730
15	9/12/2017	Deepdene Rd & Edgevale Rd	21210	Rags, Roots, Trash	DWO	N/A	60	Cloudy water escaping the manhole in the woods.	6	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	451489
16	9/12/2017	5813 Loch Raven Blvd	21239	Rags, Roots, Trash	DWO	N/A	0	Dampness observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and spoke with consumer.	451676
17	9/12/2017	2505 W Lexington St	21223	Structural	DWO	Gwynns Falls	63,193	Sanitary pipe segments leaking into underdrain discharging into storm sewer. Discharge rate determined using the EPA approved SDUO Quantification Protocol (2010).	582,639	Identified all leaking segments of the pipe and put measures in place to have lining performed. Contractor performed lining to all leaking segments of the pipe to abate the overflow.	Baltimore City Office of Compliance and Laboratories performed a dye test to confirm the abatement.	
18	9/12/2017	711 N Payson St	21217	Rags, Grease, Trash	DWO	N/A	0	Gray water observed around the cleanout at the rear of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	451735
19	9/13/2017	421 E 22nd St	21218	Rags, Roots, Grease, Trash	DWO	N/A	0	Heavy gray water around the cleanout at the rear of the property.	14	Relieved house connection choke with 60 ft of electric cable and H Cutter.	Performed CCTV inspection and confirmed connection and mainline are clear.	452059

SSO Notification List

September 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	9/14/2017	826 North Point Rd	21224	Grease, Trash	DWO	N/A	104	Colored water flowing from the cleanout.	104	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	452252
21	9/14/2017	709 Chesapeake Ave	21225	Rags, Trash	DWO	N/A	45	Contractor's sanitary bypass pump leaking waste water and discharging into nearby stream. Additional small leak was found in bypass hose.	900	Bypass pump was fixed and restored by contractor.	Spoke with Spiniello and City project manager to ensure problem does not reoccur.	452343
22	9/14/2017	N Charles St and W Lanvale St - SSO #152	21202	Other	DWO	Jones Falls	115	SSO structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe; not visually observed.	141,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
23	9/16/2017	6711 Park Heights Ave	21215	Roots, Trash	DWO	N/A	0	Gray water observed around the manhole.	8	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	452653
24	9/17/2017	3132 Guilford Ave	21218	Roots	DWO	N/A	0	Heavy gray water observed around cleanout at the rear of the property.	7	Relieved 6" house connection choke with 30 ft electric cable and H Cutter.	Performed CCTV inspection; confirmed house connection and mainline are clear.	452742
25	9/18/2017	115 S Kresson St	21224	Rags, Grease, Trash	WVO	N/A	195	Gray and murky water emerging from the manhole.	195	Relieved 8" mainline choke with pressure hose.	Performed CCTV inspection.	452878
26	9/18/2017	410 Brunswick St	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	129	Water flowing from manhole into stream.	1,290	Relieved 12" mainline choke with 5 ft of pressure hose.	Performed CCTV inspection and cleaned the mainline.	452904
27	9/18/2017	2423 W Garrison Ave (Private)	21215	Grease, Structural	DWO	N/A	285	Gray water emerging from a broken private sump pump.	214	Relieved house connection choke with 45 ft of electric cable and H Cutter.	Performed CCTV inspection and left a door notice for the consumer.	452941
28	9/18/2017	Deepdene Rd & Edgevale Rd	21210	Rags, Roots, Trash	DWO	N/A	37	Gray water escaping the manhole in the street.	74	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	452987
29	9/18/2017	3812 Reisterstown Rd	21215	Rags, Roots, Trash	DWO	N/A	0	Gray water observed around the cleanout.	4	Relieved house connection choke with 60 ft of electric cable and H Cutter.	Performed CCTV inspection.	452946
30	9/19/2017	5502 Benton Heights Ave	21206	Rags, Roots, Trash	DWO	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection and left a door notice.	453237
31	9/19/2017	2913 Windsor Ave	21216	Rags, Trash	DWO	N/A	0	Heavy gray water around the cleanout at the front of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	453114
32	9/21/2017	N Charles St & W Lanvale St - SSO #152	21201	Grease, Trash	DWO	Jones Falls	1,335	Cleaning from contractor caused chunk of grease to break off and choke the flow in the pipe. Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	1,193,000	Contractor vacuumed out the broken off grease and debris from the pipe to return normal flow.	The SSO structure will be closed upon completion of necessary capital project.	
33	9/22/2017	4116 Fairhaven Ave	21226	Rags, Roots, Trash	DWO	N/A	0	Dampness around the cleanout at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable and H Cutter.	Confirmed connection is clear.	453995
34	9/22/2017	2563 Marbourne Ave	21230	Rags, Roots, Trash	DWO	N/A	0	Water observed around the cleanout at the front of the property.	6	Relieved house connection choke with 60 ft of electric cable and H Cutter.	Performed CCTV inspection.	454004
35	9/23/2017	300 S Bentalou St	21223	Rags, Grease, Trash	DWO	Gwynns Falls	162	Gray water around the manhole and street.	486	Relieved 8" mainline choke.	Performed mainline CCTV inspection.	454095
36	9/25/2017	6222 Benhurst Rd	21209	Rags, Roots, Trash	DWO	N/A	48	Water overflowing from cleanout at the rear of the property.	48	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	454426
37	9/27/2017	302 E 33rd St	21218	Rags, Roots, Rain	DWO	N/A	0	Dampness observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable and H Cutter.	Confirmed the connection is clear.	455229

SSO Notification List

September 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
38	9/29/2017	3500 Parkdale Ave	21211	Structural	DWO	Jones Falls	11,550	Broken sanitary pipe within a large storm drain is discharging wastewater directly into the storm drain.	57,750	Established bypass pumping to abate the overflow.	Baltimore City DPW is investigating long term solutions for this area.	455755
39	9/29/2017	3623 Old York Rd	21218	Rags, Roots	DWO	N/A	0	Dampness observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 35 ft of electric cable.	Performed house lateral CCTV inspection.	455828
40	9/29/2017	1352 Cedarcroft Rd	21239	Rags, Trash	DWO	N/A	0	Grey water observed around the cleanout and street.	10	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection and dye test.	455895
				# WWO	11			TOTAL	1,983,760	UNDER 100 GALLONS	24	