

SSO Notification List

September 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/2/2019	4818 Richard Ave	21214	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	766767
2	9/4/2019	3609 Howard Park Ave	21207	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	767582
3	9/6/2019	2527 Loch Raven Rd	21218	Structural	Dry	Jones Falls	0	Mainline leaking wastewater into the storm drain. Confirmed via dye test.	Ongoing	Determining a solution to resolve the issue.	Pipe lining or bypass pumping may be installed if a quick repair cannot be done.	768738
4	9/6/2019	2700 Loch Raven Rd	21218	Structural	Dry	Jones Falls	0	Mainline leaking wastewater into the storm drain. Confirmed via dye test.	Ongoing	Determining a solution to resolve the issue.	Pipe lining or bypass pumping may be installed if a quick repair cannot be done.	768738
5	9/6/2019	913 Harlem Ave	21217	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the manhole.	7	Flushed and cleaned 8" mainline with 50 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	768900
6	9/7/2019	605 E 35th St	21218	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Performed lateral CCTV inspection.	769113
7	9/7/2019	2257 Cedley St	21230	Trash, Structural	Dry	N/A	0	Debris and sewage observed around the cleanout at the rear of the property.	4	Left notice to contact a plumber; structural issues present on consumer's side of pipe.	Notified Housing Authority of the situation; cleaned the area.	769153
8	9/8/2019	2805 Bookert Dr	21225	Rags, Roots	Dry	N/A	44	Gray water escaping the cleanout.	22	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	769336
9	9/9/2019	3302 The Alameda	21218	Rags, Grease, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 75 ft of electric cable.	Confirmed lateral is clear.	770057
10	9/12/2019	2537 Oswego Ave	21215	Structural	Dry	Jones Falls	7265	Sanitary sewer pipe leaking into storm inlet pipe.	1,816	Repairs were made to the line.	Abatement confirmed via dye testing.	771820
11	9/13/2019	1232 N Franklinton Rd	21229	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	5714	Sanitary stack manhole overflowing in woods.	1,142,800	Relieved mainline choke with 225 ft of pressure hose.	Confirmed mainline is clear.	772577
12	9/14/2019	1506 McCulloh St	2127	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	772999
13	9/14/2019	5109 Midwood Ave	21212	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	773010
14	9/15/2019	2924 Saint Paul St	21218	Rags, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	773024
15	9/18/2019	3420 Benson Ave	21227	Rags, Trash, Other	Dry	N/A	0	Gray water observed around the manhole.	8	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	775386
16	9/19/2019	801 N Stricker St	21217	Rags, Grease	Dry	N/A	180	Gray water escaping the manhole.	720	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	775632
17	9/19/2019	1744 E Lafayette Ave	21213	Rags, Roots, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	775854
18	9/20/2019	101 Cotswold Rd	21210	Roots	Dry	Jones Falls	42	Gray water escaping the manhole.	84	Relieved 8" mainline choke with 320 ft of pressure hose.	CCTV inspection will be performed.	776462
19	9/24/2019	1248 N Gay St	21213	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Flushed the mainline; confirmed lateral is clear.	778971

SSO Notification List

September 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	9/25/2019	618 E 30th St	21218	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	780033
21	9/26/2019	5105 Roland Ave	21210	Trash, Structural	Dry	N/A	0	Gray water observed on the sidewalk.	15	Flushed and cleaned mainline with 335 ft of pressure hose; ran 120 ft of electric cable in lateral.	Set up bypass pumping to stop possible future overflow(s). Repair will take place.	780203
22	9/27/2019	1611 Laurens St	21217	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	781313
23	9/28/2019	2805 Overland Ave	21214	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	781464
24	9/28/2019	3900 Ferndale Ave	21207	Other	Dry	N/A	0	Gray water observed at the front of the property.	5	Advised consumer to contact a plumber to have a cleanout installed.	Mainline will be cleaned and Housing Authority notified.	781602
25	9/30/2019	3436 Dudley Ave	21213	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the manhole.	8	Relieved mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear; advised nearby consumer to install cleanout cap.	781875
				# WWO	0			TOTAL	1,145,522	UNDER 100 GALLONS	20	