

## SSO Notification List

September 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/1/2023	2218 N Forest Park Ave	21207	Infiltration, Structural	Dry	Gwynns Falls	36112	Wastewater is infiltrating the adjacent storm drain from sanitary mainline below ground.	180560	Point repair was performed on the mainline to restore system to regular functionality.	Abatement confirmed via dye testing by OREP.	1256707
2	9/2/2023	612 Wyndhurst Ave	21210	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV will be performed.	1256851
3	9/3/2023	3732 Roland Ave	21211	Rags	Dry	N/A	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	1256910
4	9/6/2023	1052 Bethune Rd - Private	21225	Roots, Grease	Dry	N/A	1498	Private manhole overflowing in wooded area.	(1498)	DPW assisted by relieving mainline choke with 300 ft of pressure hose.	Advised consumer that this system is not DPW responsibility.	1257447
5	9/11/2023	206 Oakdale Rd	21210	Roots, Rags	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	1258416
6	9/12/2023	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	65	Structure monitored by metered equipment in the pipe. Not visually observed.	32045	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
7	9/12/2023	N Charles St & Lafayette Ave - SSO Site #154	21201	Rain	Wet	Jones Falls	90	Structure monitored by metering equipment in the pipe. Not visually observed.	13050	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
8	9/12/2023	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	200	Structure monitored by metering equipment in the pipe. Not visually observed.	1744000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
9	9/12/2023	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	35	Structure monitored by metered equipment in the pipe. Not visually observed.	4025	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
10	9/12/2023	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	90	Structure monitored by metering equipment in pipe.	57060	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
11	9/12/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	185	Manhole adjacent to creek overflowed due to heavy rain.	647130	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
12	9/12/2023	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	110	Heavy gray water escaping the manhole.	75020	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
13	9/12/2023	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	225	Structure monitored by metering equipment in the pipe. Not visually observed.	1086075	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	9/13/2023	1736 Poplar Grove St	21216	Rags, Roots, Grease	Wet	Gwynns Falls	155	Gray water escaping the manhole.	310	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1259118
15	9/13/2023	422 E Federal St	21202	Grease, Rags, Infiltration	Wet	Jones Falls	85	Routine sampling discovered a choked sanitary mainline causing a subsurface SSO.	425	Used high-pressure jet truck to relieve mainline choke.	CCTV inspection will determine if further action needs to be taken.	1259106
16	9/16/2023	432 S Augusta Ave	21229	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	CCTV inspection confirmed the lateral is clear.	1259969
17	9/21/2023	3703 Mactavish Ave	21229	Trash, Rags	Dry	Maidens Choice	—	Gray water observed in the street around the manhole and storm drain.	10	Flushed and cleaned 8" mainline with 100 ft of pressure hose.	Confirmed the line is clear at this time.	1261186
18	9/22/2023	38 Gwynns Falls Trail	21216	Rags, Roots, Grease	Dry	Gwynns Falls	1475	Heavy gray water escaping the manhole.	1475	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1261494
19	9/25/2023	2405 Francis St	21217	Rags, Trash	Wet	Jones Falls	472	Gray water escaping the manhole in the street.	236	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is now flowing freely; CCTV will be performed.	1261969
20	9/25/2023	204 E Chase St	21202	Roots, Rags	Wet	N/A	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	1261949

SSO Notification List

September 2023

21	9/28/2023	125 N Hilton St	21229	Grease	Dry	Gwynns Falls	48	Mainline choke causing an SSO; through routine sampling.	12	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1262934
22	9/28/2023	22 S Tremont Rd	21229	Rags, Roots, Grease	Wet	N/A	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time.	1262931
				# WWO	14			TOTAL	3,841,439	UNDER 100 GALLONS	8	